STM32MP1 workshop

Workshop known issues







Known issues 2

Vmware player issues:

Symptom: At VM image start you get an error.

"« VMware Workstation and Device/Credential Guard are not compatible. VMware Workstation can be run after disabling Device/Credential Guard. »

Solution

Deactivate 2 options

- > Run **gpedit.msc** (windows+R), open tab : Computer Configuration, Administrative Templates, System, Device Guard Select "Turn on Virtualization Based Security" and disable this option.
- > Run optionalfeatures (windows+R), unselect the Hyper-V tickbox

https://www.windows8facile.fr/bug-vmware-workstation-w10-1709/



Known issues 3

Vmware player issues:

Symptom: VM is slow to start, execution of CubeMx very slow....


Solution


- 1 Exit from VM
- 2 Re-Run VMWorkstationPlayer and select the VM image in the menu.



4 Reduce the size to half of the PC RAM available.

Ex PC has 4GO RAM, select 2GO for VM





Known issues 4

Ac6 system Work-bench issues

Build error: There may be build error with install of system workbench "PATH doesn't include the directory for arm-none-eabi-g++ and -gcc"

Solution: In this case remove current version cd ~/Ac6 rm –rf SystemWorkbench

Then relaunch manual installation of systemworkbench from cd ~/STM32MPU-Tools/CUbeMPUPackage-systemworkbench

Build error in project DK2 TIMER1 OpenAmp Solution in from Lab-M4

arm-none-eabi-as -mcpu=cortex-m4 -mthumb -mfloat-abi=hard -mfpu=fpv4-sp-d16 -g -o "startup/startup stm32mp15xx.o" "../startup/startup stm32mp15xx.s"


/bin/sh: 1: arm-none-eabi-as: not found

startup/subdir.mk:15: recipe for target 'startup/startup stm32mp15xx.o' failed

.settings directory from DK2 TIMER1 OpenAmp Solution directory has incorrect path for this systemworkbech version

Solution: Remove .settings directory in DK2 TIMER1 OpenAmp Solution cd ~/Desktop/DK2 TIMER1 OpenAmp Solution rm -rf .settings/





Thanks