




Cached P5 | Vivado 2018.3 | Virtex-7 routed OOC timing



Route/DRC errors = 0; 16 check timing categories = 0. Setup fails at 25 ns; OOC ports use zero I/O delay. No board or ASIC signoff.