

SAMPLE — CRITERIA NOT VERIFIED

Thresholds marked * are PLACEHOLDERS, not from the AFM or ops specs. Layout sample only — not for dispatch planning.

AIRPORT SUITABILITY ASSESSMENT

KDTO — Denton Enterprise Airport, Denton, TX

DATA SOURCE	NASR CYCLE	ASSESSED BY	DATE
FAA NASR	2026-07-09 (sample)	D. Holsapple	14 Jul 2026

1. DETERMINATION

AIRCRAFT	DETERMINATION	QUALIFYING RUNWAYS
Falcon 50EX	SUITABLE	18L/36R
Gulfstream G280	SUITABLE WITH LIMITATIONS	18L/36R only

G280: single qualifying runway. If 18L/36R is out of service the airport does not meet criteria. See §7.

2. FACILITY

From FAA NASR. Authoritative.

CONTROL TOWER	YES — 0600-2200 L	ELEVATION	642 ft MSL
AIRPORT ATTENDANCE	CONTINUOUS	ARFF INDEX	NOT IN NASR
FUEL ON FIELD	Jet A, 100LL	AIRPORT MANAGER	940-349-7744

NASR REMARKS

- RWY 18L designated as calm wind runway.
- For clearance delivery when ATCT is closed, contact Lone Star Approach at 972-615-2799.
- Dusk-dawn when ATCT closed: MIRL 18L/36R and 18R/36L preset low intensity. To increase intensity and activate MALSR RWY 18L — use CTAF.
- Airport closed to ultralights and gliders. Mowing operations May-Sep.

3. COMMUNICATIONS

FACILITY	FREQUENCY	NOTES
Tower	119.95	0600-2200 L
Ground	123.95	0600-2200 L
Clearance Delivery	123.95	0600-2200 L
Approach / Departure	118.1	Lone Star Approach
ATIS / ASOS	119.325	Phone 940-383-8457
CTAF	119.95	When tower closed
CD when ATCT closed	—	Phone Lone Star Approach 972-615-2799

4. RUNWAY EVALUATION — ALL RUNWAYS

RUNWAY	LENGTH	WIDTH	SURFACE	WT BRG	50EX	G280
18L/36R	7,002 ft	150 ft	Asphalt	S-70 D-100	PASS (+1,502 ft)	PASS (+1,002 ft)
18R/36L	5,003 ft	75 ft	Asphalt	S-30	FAIL (-497 ft)	FAIL (-997 ft)

5. CRITERIA EVALUATION — FALCON 50EX / RWY 18L/36R

CRITERION	ACTUAL	REQUIRED	MARGIN	RESULT
Runway length	7,002 ft	5,500 ft *	+1,502 ft	PASS
Runway width	150 ft	75 ft *	+75 ft	PASS
Weight bearing (DW)	100,000 lb	40,780 lb *	+59,220 lb	PASS
Surface	Asphalt	Paved	—	PASS
Runway lighting	MIRL + MALSR	Required	—	PASS
ARFF index	NOT IN NASR	Index B *	—	UNKNOWN
Approach minimums	200-1/2	≤ 400 ft *	+200 ft	PASS
Alternate distance	KDFW 24 NM	≤ 50 NM *	+26 NM	PASS

* Placeholder threshold — replace with AFM / ops spec value.

6. SERVICES AND FBO

NOT FROM NASR — CONFIRM BY PHONE. FBO services, hours, and fuel change without notice. These entries are a starting point and a phone number, not a verified fact.

FBO	PHONE	FUEL	SERVICES
Sheltair DTO	940-435-2621	Jet A, 100LL	Hangar, crew car, Hertz on site, catering, cargo, lounge
US Trinity Aviation	CONFIRM	Jet A	Fuel, hangar, ground handling, concierge
Jet Works Air Center	940-323-8700	CONFIRM	Maintenance

7. DISQUALIFYING FINDINGS

RWY 18R/36L	5,003 ft below minimum for both airframes. Not usable by either aircraft.
G280 — airport	Single qualifying runway. No usable alternate runway on field if 18L/36R closes.

8. ITEMS REQUIRING VERIFICATION

Auto-generated. Every data point the source could not supply becomes an action item.

#	ITEM	ACTION
1	ARFF index not published in NASR	Confirm with airport ops — 940-349-7744
2	Grooved surface status not in NASR	Verify via AFD or airport ops
3	US Trinity Aviation phone not confirmed	Look up and confirm before dispatch
4	Jet Works fuel availability not confirmed	Call 940-323-8700

9. PIC NARRATIVE

10. SIGN-OFF

ROLE	NAME	SIGNATURE	DATE
Pilot in Command			
Chief Pilot			

This assessment is a planning guide. The Pilot in Command determines actual airport and runway usability for the conditions at the time of operation.