

Virtual Humidity Sensor Time-Series Analysis
Humidity (%)
Reading Number
Raw humidity readings
Moving Average, window = 3
Moving Average, window = 10
80
75
70
65
60
55
50
45
40
0
20
40
60
80
100