

DEMAND ACTION CORRECTION AND PREVENTION

Number: SMK3L-En/ISP/FR-07-01

Revision: 06

Date : 01 Maret 2023

Section Housing Colony Day / Date October 25th 2021							
Description of Non-conformance / Potential Incompatibility:							
The water pump at housing colony make short electricity or pump is broken.							
Description causes of nonconformities / potential nonconformities (Root Cause):							
The water pump mostly is placed outside where the potential expoxed rainwater or other water							
without full cover							
Causing Category ☐ People ☐ Tool ☐ Material ☐ Methods ■ Natural ☐ Others							
Management Representative			Head of Department				
()			()				
Correction Action Plan (Direct) :		-	Responsible Person		Settlement Plan	Finish Date	
Repair of waterpump cable with good condition (good isolation cable connection)		E	Electric		October 25th, 2021		
Corrective Action Plan (In Direct) :		Responsible Person		Settlement Plan	Finish Date		
Install cover for waterpump to prevent of water		Civil		November 25th, 2021			
Change Prevention Action Plan (if necessary):							
Implementation Schedule			No.		Responsible Person		
Starting	Date:	1					
Finish Plan	Date :	3					
Realization	Date .	3					
Verification of corrective and preventive actions:			□ Accepted Date :				
Mana		Head of Department					
()					(_)	