Commercial property insurance submission

Northbridge Furniture Storage Ltd
Request for quotation | Proposed period 1 December 2026 to 30 November 2027

Demonstration document. All organisations, people, premises, records and losses described here are fictional. This is a broker-style training submission, not a real insurance application, certificate or offer of cover. It is not a form issued by any insurer.

1 Broker covering note

Prepared by Pennine Example Insurance Brokers, fictional commercial risks team, reference NB-2026-001. Please consider terms for an owner-occupied furniture distribution warehouse, including property damage, theft and business interruption. The client seeks annual cover on an all-risks basis, subject to insurer terms. No cover has been bound. Liability covers are placed separately and are not requested in this submission.

Proposer	Northbridge Furniture Storage Ltd; private limited company; established 2018. Registration identifier intentionally omitted for this synthetic case.
Risk premises	Unit 4, Example Distribution Park, Greater Manchester, England. Fictional location; no valid postal address or postcode supplied.
Ownership and occupation	Company owns and occupies the whole premises. No tenants, shared occupiers or vacant areas.
Business	Wholesale distribution and temporary storage of new domestic furniture. No manufacture, upholstery work, spray painting or public showroom.
Business size	14 employees; annual turnover £3.2 million. Weekday operations 07:00-18:00; occasional Saturday dispatch 08:00-12:00.
Client contact	Alex Morgan, operations manager, fictional contact. No live contact details included.

2 Information basis and quotation request

This pack combines the client questionnaire dated 22 October 2026, a broker visit note dated 20 October 2026 and short extracts from supplied maintenance records. Full reports and certificates are not enclosed. Statements are attributed below; their inclusion is not independent verification. Outstanding details are stated where known.

Please indicate any additional information or survey requirements with indicative terms. Requested values and cover bases require insurer consideration; no target premium or agreed excess is supplied.

Property details and cover requested

3 Buildings and occupation

The premises comprise a 1,000 m² warehouse constructed in 2004 and a 200 m² single-storey extension added in 2019, including a 100 m² office area within the total 1,200 m² footprint. The main structure is steel framed with brick/block lower walls, profiled metal upper walls and a metal roof. The extension has composite wall panels; panel core specification has not been supplied. Floors are concrete; there is no basement.

Space heating serves the offices through a mains-gas boiler; no fixed heating is used in the warehouse. The client reports no portable heaters or rooftop solar installation. Electrical supply is mains connected. Adjacent units are used for general trade distribution; their detailed processes have not been confirmed. No structural work is planned during the requested insurance period.

4 Requested property sums insured

Buildings	£2,000,000 reinstatement sum requested, including the extension. Client estimate; no recent professional reinstatement assessment supplied.
General contents	£150,000 for racking, handling equipment and office contents, excluding stock and computers.
Computers	£15,000 at the premises, separately identified to avoid duplication with general contents.
Stock	£600,000 maximum anticipated value, including seasonal peaks. Current indicative holding £450,000. No stock declaration arrangement requested.
Business interruption	£1,200,000 estimated insurance gross profit for a 24-month maximum indemnity period; calculation and uninsured working expenses not supplied.
Requested extensions	Accidental damage and theft requested. Flood, storm, escape of water and subsidence to be considered within quoted terms. Terrorism quotation requested separately.

5 Business continuity and other exposures

Most sales are to UK retailers. One supplier accounts for approximately 35% of purchases; the client estimates replacement stock lead times of six to eight weeks. No alternative warehouse is contracted. Order and accounting records are backed up to a cloud service daily; restoration testing has not been documented. Deliveries use contracted hauliers; goods in transit cover is arranged separately.

The client reports no known river or surface-water flooding at the premises since occupation and no observed subsidence. No independent flood search or ground investigation is supplied. A toilet supply-pipe leak occurred in 2024, described on page 4. Accessible internal pipes are reported insulated; inspection records were not provided. There is no fuel tank and no routine outdoor stock storage.

Operations and premises observations

6 Storage and housekeeping

[Client questionnaire, 22 October 2026] Stock includes upholstered sofas, chairs and flat-packed wood-based furniture, with cardboard and plastic packaging. Goods are stored on pallets and steel racking in the main warehouse and extension. Aisles are checked daily and were clear at the broker visit. Maximum storage height and commodity-specific storage specifications were not recorded in the questionnaire.

[Broker visit, 20 October 2026] Cardboard waste was held in a designated internal collection area awaiting daily removal. External waste bins were approximately 8 metres from the main building. No flammable-liquid stock was observed during the visit; this was a visual observation, not a complete inventory check.

7 Electrical supply and work procedures

[Electrical inspection extract, 15 September 2026] The inspection outcome was described as satisfactory, with no outstanding C1 or C2 observations. The full schedule and scope of inspected circuits are not enclosed. Forklifts are electrically powered and charged in a designated bay away from the main stock aisles; recorded separation distances are not supplied.

[Client questionnaire] Smoking is restricted to an external designated location. Contractors must obtain a hot-work permit before work starts, and a written procedure was supplied to the broker. Completed permit examples and records of post-work checks were not supplied. The client reports no hot work planned for the next three months.

8 Building separation and protective installations

[Broker visit] One self-closing fire door between the warehouse and office corridor did not close fully because its closer was defective. Two service penetrations through the same separating wall appeared unsealed. The client had requested contractor quotations, but completion evidence was not available at submission.

[Fire-alarm service extract, 8 October 2026] Routine servicing recorded no outstanding faults. The client states the system covers the warehouse and offices. The supplied extract does not include a zone plan or establish coverage of the extension.

[Broker covering questionnaire] The premises were described as sprinkler protected throughout. [Sprinkler service extract, 30 September 2026] Routine servicing of the listed installation was completed; the extract does not include a coverage drawing, extension schedule or confirmation of suitability for the current furniture storage arrangement. These details remain to be clarified; the extract does not establish that extension protection is absent.

[Client questionnaire] Portable extinguishers are serviced annually and staff receive induction instruction. The current fire risk assessment is reported to have been reviewed in March 2026, but its full report and action register are not enclosed.

Site management and supporting information

9 Entry arrangements and out of hours procedures

[Client questionnaire] External pedestrian doors have mortice locks; roller shutters are secured internally after closing. Keys are issued to four authorised staff and visitors sign in at reception. A 1.8-metre metal fence surrounds the service yard. The rear pedestrian gate is left unsecured during working hours to facilitate staff access and is locked at closing. A written end-of-day checklist includes doors, shutters and gate checks; completed checklists were not supplied.

[Broker visit] CCTV cameras cover the loading area and main entrance. The client reports 30-day retention, with viewing by the operations manager. Camera coverage of the rear gate has not been established. There is no overnight guarding. The surrounding estate remains accessible to other occupiers outside business hours.

10 Alarm arrangements

[Intruder-alarm service extract, 12 August 2026] The main warehouse and office installation was serviced with no outstanding faults recorded. The client reports remote alarm receiving-centre monitoring and a keyholder response arrangement. A maintenance contract is reported current. Installation grade, signalling specification and evidence of police response status are not supplied. The extract does not confirm sensor coverage of the 2019 extension.

11 Five year loss and insurance history

June 2024	Escape of water from toilet supply pipe. £4,800 paid by prior insurer, no outstanding reserve reported. Pipe section replaced and isolation valve labelled.
Other losses	Client reports no other insured or uninsured property losses in the five years to 22 October 2026, including no reported fire or theft losses.
Previous insurance	Annual property and business interruption cover reported in place until 30 November 2026. Expiring schedule and insurer loss run not enclosed.
Insurance history	Client reports no prior cancellation, avoidance or refusal to renew. This is a client statement, not independently checked.

12 Submission status and remaining information

Known outstanding items include full maintenance reports and drawings, composite panel specification, maximum storage height, confirmation of extension alarm and sprinkler arrangements, repair completion records, and the basis of the declared values and business interruption estimate. Valid address and registration details would also be needed for a real application; they are omitted here to keep the case fictional.

Broker compilation status: submitted for demonstration review on 31 October 2026. Client sign-off is not simulated as a real signature. Nothing in this pack confirms acceptance, policy terms or binding. Sources referenced throughout are synthetic extracts contained within this pack, not separate attachments.