SKILLCAD Flat Panel Layout Editor

User Quick Reference

SKLLCAD	Icon	
CACENCE	Switcher	Click to toggle between SKILLCAD icon bar and CADENCE icon bar (in IC5)
-	rRouter (Path)	1) Select Pins 2) Set Parameters. [3) Enter iGuide Points if using iGuide] 4) Click Preview 5) Adjust Parameters and Tune Routing Points 6) Apply
	(raui)	5) Tappiy
(((rRouter (Polygon)	[1) Select Pins and set Pin Extensions] 2) Set Route Mode and Parameters. 3) Enter(Click) Routing Points 4) Adjust Parameters and Routing Width/Points 5) Preview and check Results 6) Finish Route
≱R	rChecker	1) Click Start New Measurement 2) Draw a line cross starting ends of target lines 3) Draw a line cross ending ends of target lines. 4) Review/analysis results
â.	iShape	Select a drawing shape
	Align	OneByOne [1) Click on the reference object] 2) Click on the object to be aligned 3) Adjust offset/Orientation AllSelected: Use Align Arrows, Move Arrows and set Space buttons to adjust the placement of selected objects
+	iDRC	Click Apply/OK to check the given Space/Width design rules.
AØ B1	Mask Label	1) Input the Label (Label Array) 2) Click at layout window to place Label(s)
	Merge Pin	Draw a box over pins to be merged
Draw Line	Draw Line	Click in the same way as drawing Path.
300000000 300000000	Rule Extend	1) Select the shape to be extended 2) Specify correct Space rule 3) Draw a closed polygon from the selected shape with reference to the outlines of the neighboring shapes
r	Round Corner	1) Select bus 2) Select corners of the selected bus
Kits	Kits	Other utilities: Measure Area/Perimeter, fix offgrid, nCopy
1		