



Aviation Investigation Final Report

Location: Queen Creek, Arizona Accident Number: WPR23LA171

Date & Time: April 29, 2023, 09:30 Local Registration: N2207D

Aircraft: Cessna 170B Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported encountering a dust devil (also called a whirlwind) during rollout following a full stall landing maneuver. The airplane did not have any aileron authority due to the low airspeed at the time of the encounter. The left wing subsequently impacted the ground and the airplane departed the runway. It continued to roll down a hill before flipping and coming to rest inverted, resulting in substantial damage to the empennage and both wings. The pilot reported there were no preimpact mechanical malfunctions or failures with the airframe or the engine that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The airplane's encounter with a dust devil after landing, which resulted in a loss of directional control.

Findings

Aircraft Directional control - Attain/maintain not possible

Environmental issues Dust devil/whirlwind - Ability to respond/compensate

Factual Information

History of Flight

| Landing-landing roll | Loss of control on ground (Defining event) | |
|----------------------|--|--|
|----------------------|--|--|

Pilot Information

| Certificate: | Private | Age: | 50 |
|---------------------------|--|-----------------------------------|----------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 4-point |
| Instrument Rating(s): | None | Second Pilot Present: | |
| Instructor Rating(s): | None | Toxicology Performed: | |
| Medical Certification: | Class 3 Unknown | Last FAA Medical Exam: | April 20, 2022 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | April 26, 2022 |
| Flight Time: | 1000 hours (Total, all aircraft), 200 hours (Total, this make and model), 950 hours (Pilot In Command, all aircraft), 20 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | Cessna | Registration: | N2207D |
|-------------------------------|------------------------------|-----------------------------------|-----------------|
| Model/Series: | 170B | Aircraft Category: | Airplane |
| Year of Manufacture: | 1952 | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 20359 |
| Landing Gear Type: | Tailwheel | Seats: | 4 |
| Date/Type of Last Inspection: | April 16, 2022 Annual | Certified Max Gross Wt.: | 2200 lbs |
| Time Since Last Inspection: | 25 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 6099 Hrs | Engine Manufacturer: | Continental |
| ELT: | C91 installed, not activated | Engine Model/Series: | C-145-2 |
| Registered Owner: | On file | Rated Power: | 145 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |
| | | | |

Page 2 of 4 WPR23LA171

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|------------------|
| Observation Facility, Elevation: | KIWA,1382 ft msl | Distance from Accident Site: | 6 Nautical Miles |
| Observation Time: | 09:53 Local | Direction from Accident Site: | 336° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.04 inches Hg | Temperature/Dew Point: | 30°C / -6°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Queen Creek, AZ (5AZ3) | Type of Flight Plan Filed: | None |
| Destination: | Queen Creek, AZ | Type of Clearance: | None |
| Departure Time: | 07:30 Local | Type of Airspace: | Class G |

Airport Information

| Airport: | Pegusas Airpark 5AZ3 | Runway Surface Type: | Asphalt |
|----------------------|----------------------|----------------------------------|-------------|
| Airport Elevation: | 1452 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 08 | IFR Approach: | None |
| Runway Length/Width: | 5124 ft / 80 ft | VFR Approach/Landing: | Straight-in |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 33.208725,-111.61724(est) |

Page 3 of 4 WPR23LA171

Administrative Information

Investigator In Charge (IIC): Basti, Paymaun

Additional Participating Persons:

Original Publish Date: October 20, 2023

Last Revision Date:

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=107166

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 WPR23LA171