



# **Aviation Investigation Final Report**

Location: Barataria, Louisiana Accident Number: CEN24LA047

Date & Time: November 18, 2023, 10:50 Local Registration: N61919

Aircraft: Cessna A185F Aircraft Damage: Substantial

**Defining Event:** Collision during takeoff/land **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Positioning

#### **Analysis**

The pilot reported that she had setup for landing on an intracoastal waterway and picked a landing area based on the locations of three nearby boats. During final approach, she had the three boats in sight, one of which was on the far right side of waterway and traveling in the same direction. She determined that the boats would not be a factor and continued to land. The airplane touched down on the choppy water and she added power to keep the airplane on the step. Immediately after touchdown the airplane veered left, then nosed over and sustained substantial damage to the right wing. The pilot egressed the airplane without further incident. She noticed that the recreational boat that was originally on the right side of the waterway was now on the left side and the boat driver stated that the airplane hit the boat. Since the pilot was seated in the left seat, her view to the lower right area of the airplane would have been restricted by the airframe. The pilot added that three other airplanes had just landed on the waterway and there was one more in position to land behind her.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A recreational boat crossed in front of the airplane's path during landing on the water which resulted in the airplane colliding with the boat.

## **Findings**

Environmental issues	Ground vehicle - Contributed to outcome
Environmental issues	Ground vehicle - Awareness of condition
Personnel issues	Identification/recognition - Pilot

Page 2 of 6 CEN24LA047

# **Factual Information**

## History of Flight

Landing-flare/touchdown	Nose over/nose down
Landing	Collision during takeoff/land (Defining event)

## Pilot Information

Certificate:	Commercial	Age:	39,Female
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	March 24, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	March 28, 2023
Flight Time:	1010 hours (Total, all aircraft), 600 hours (Total, this make and model), 840 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CEN24LA047

#### **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N61919
Model/Series:	A185F	Aircraft Category:	Airplane
Year of Manufacture:	1981	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18504274
Landing Gear Type:	Float	Seats:	4
Date/Type of Last Inspection:	July 19, 2023 100 hour	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	6286.2 Hrs as of last inspection	Engine Manufacturer:	Continental Motors
ELT:	Installed, not activated	Engine Model/Series:	IO-520-D30B
Registered Owner:	TAILSPIN LLC	Rated Power:	285 Horsepower
Operator:	Southern Seaplane, Inc.	Operating Certificate(s) Held:	On-demand air taxi (135), Pilot school (141)

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KNBG,1 ft msl	Distance from Accident Site:	8 Nautical Miles
Observation Time:	10:55 Local	<b>Direction from Accident Site:</b>	54°
<b>Lowest Cloud Condition:</b>	Scattered / 1900 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 2700 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.99 inches Hg	Temperature/Dew Point:	21°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Belle Chasse, LA (65LA)	Type of Flight Plan Filed:	None
Destination:	Belle Chasse, LA (65LA)	Type of Clearance:	None
Departure Time:	10:35 Local	Type of Airspace:	Class E

Page 4 of 6 CEN24LA047

## **Airport Information**

Airport:	Intracoastal waterway	Runway Surface Type:	
Airport Elevation:		<b>Runway Surface Condition:</b>	Water-choppy
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	29.738707,-90.142605

Page 5 of 6 CEN24LA047

#### **Administrative Information**

Investigator In Charge (IIC):	Lindberg, Joshua
Additional Participating Persons:	David Gutkowski; Federal Aviation Administration; Baton Rouge, LA
Original Publish Date:	December 13, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193427

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN24LA047