



# **Aviation Investigation Final Report**

Location: Healy, Alaska Accident Number: ANC23LA075

Date & Time: September 12, 2023, 14:15 Local Registration: N34VV

Aircraft: Cessna 185 Aircraft Damage: Substantial

**Defining Event:** Nose over/nose down **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot of a tailwheel-equipped airplane reported that, during landing rollout at an overgrown remote airstrip, the main landing gear wheels "sunk into soft vegetation." The airplane subsequently nosed over and sustained substantial damage to the fuselage, vertical stabilizer, and wings. The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's selection of an unsuitable landing site, resulting in a nose over.

#### **Findings**

Personnel issues Aircraft control - Pilot

Personnel issues Identification/recognition - Pilot

Environmental issues Soft surface - Effect on operation

Aircraft (general) - Capability exceeded

### **Factual Information**

### **History of Flight**

Landing-landing roll	Nose over/nose down (Defining event)	
----------------------	--------------------------------------	--

#### **Pilot Information**

Certificate:	Commercial	Age:	28,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	May 8, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	August 4, 2023
Flight Time:	1869 hours (Total, all aircraft), 290 hours (Total, this make and model), 1720 hours (Pilot In Command, all aircraft), 150 hours (Last 90 days, all aircraft), 80 hours (Last 30 days, all aircraft)		

#### **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N34VV
Model/Series:	185	Aircraft Category:	Airplane
Year of Manufacture:	1961	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	185-0036
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	September 5, 2023 100 hour	Certified Max Gross Wt.:	3525 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3196.6 Hrs as of last inspection	Engine Manufacturer:	CONT MOTOR
ELT:	C91 installed, not activated	Engine Model/Series:	IO-550
Registered Owner:	WATTUM INVESTMENTS LLC	Rated Power:	300 Horsepower
Operator:	Fly Denali INC	Operating Certificate(s) Held:	Commuter air carrier (135)
Operator Does Business As:	Fly Denali	Operator Designator Code:	A3WC

Page 2 of 4 ANC23LA075

## Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
PAIN,1720 ft msl	Distance from Accident Site:	30 Nautical Miles
14:56 Local	Direction from Accident Site:	213°
Few / 4700 ft AGL	Visibility	10 miles
Overcast / 6000 ft AGL	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	None / None
	Turbulence Severity Forecast/Actual:	N/A / N/A
29.62 inches Hg	Temperature/Dew Point:	12°C / 1°C
No Obscuration; No Precipitation		
Healy, AK (PAHV)	Type of Flight Plan Filed:	Company VFR
Healy, AK	Type of Clearance:	None
13:57 Local	Type of Airspace:	Class G
	PAIN,1720 ft msl  14:56 Local  Few / 4700 ft AGL  Overcast / 6000 ft AGL  /  29.62 inches Hg  No Obscuration; No Precipitate Healy, AK (PAHV)  Healy, AK	PAIN,1720 ft msl Distance from Accident Site:  14:56 Local Direction from Accident Site:  Few / 4700 ft AGL Visibility  Overcast / 6000 ft AGL Visibility (RVR):  / Turbulence Type Forecast/Actual:  Turbulence Severity Forecast/Actual:  29.62 inches Hg Temperature/Dew Point:  No Obscuration; No Precipitation  Healy, AK (PAHV) Type of Flight Plan Filed:  Type of Clearance:

### Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	64.16,-148.3

Page 3 of 4 ANC23LA075

#### **Administrative Information**

Investigator In Charge (IIC):	Ward, Mark
Additional Participating Persons:	Timothy Kirkendall; FAA
Original Publish Date:	April 4, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193057

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ANC23LA075