



# Aviation Investigation Final Report

**Location**: Provo, Utah **Accident Number**: WPR24LA016

Date & Time: October 12, 2023, 14:40 Local Registration: N235PR

Aircraft: Maule M-7-235C Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that during the landing he felt a wind gust that moved the airplane's tail to the left, but was unsuccessful when applying a correctional input. The left wing impacted the ground then nosed over and came to rest inverted. The airplane sustained substantial damage to the wing assembly.

The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing.

#### **Findings**

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

**Environmental issues** Tailwind - Effect on operation

## **Factual Information**

## History of Flight

| Landing-landing roll | Loss of control on ground (Defining event) |  |
|----------------------|--|--|
| Landing-landing roll | Nose over/nose down                        |  |

#### **Pilot Information**

| Certificate:              | Private   | Age:                              | 37              |
|---------------------------|---|-----------------------------------|-----------------|
| Airplane Rating(s):       | Single-engine land  | Seat Occupied:                    | Left            |
| Other Aircraft Rating(s): | None  | Restraint Used:                   | 3-point         |
| Instrument Rating(s):     | Airplane  | Second Pilot Present:             |                 |
| Instructor Rating(s):     | None  | Toxicology Performed:             |                 |
| Medical Certification:    | Class 3 Without waivers/limitations   | Last FAA Medical Exam:            | June 25, 2019   |
| Occupational Pilot:       | No  | Last Flight Review or Equivalent: | August 18, 2023 |
| Flight Time:              | 406 hours (Total, all aircraft), 7 hours (Total, this make and model), 357 hours (Pilot In Command, all aircraft), 27 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft) |                                   |                 |

## **Aircraft and Owner/Operator Information**

| Aircraft Make:                | Maule                         | Registration:                     | N235PR          |
|-------------------------------|-------------------------------|-----------------------------------|-----------------|
| Model/Series:                 | M-7-235C                      | Aircraft Category:                | Airplane        |
| Year of Manufacture:          |                               | Amateur Built:                    |                 |
| Airworthiness Certificate:    | Normal                        | Serial Number:                    | 25066C          |
| Landing Gear Type:            | Tailwheel                     | Seats:                            | 4               |
| Date/Type of Last Inspection: | February 8, 2023 Annual       | Certified Max Gross Wt.:          | 2500 lbs        |
| Time Since Last Inspection:   | 28.7 Hrs                      | Engines:                          | 1 Reciprocating |
| Airframe Total Time:          | 1115.5 Hrs                    | Engine Manufacturer:              | Lycoming        |
| ELT:                          | C91A installed, not activated | Engine Model/Series:              | O-540-B4B5      |
| Registered Owner:             | SUNNYSIDE 7 LLC               | Rated Power:                      | 235 Horsepower  |
| Operator:                     | On file                       | Operating Certificate(s)<br>Held: | None            |

Page 2 of 4 WPR24LA016

## **Meteorological Information and Flight Plan**

| Conditions at Accident Site:     | Visual (VMC)                     | Condition of Light:                  | Day                      |
|----------------------------------|----------------------------------|--------------------------------------|--------------------------|
| Observation Facility, Elevation: |                                  | Distance from Accident Site:         |                          |
| Observation Time:                | 16:40 Local                      | Direction from Accident Site:        |                          |
| <b>Lowest Cloud Condition:</b>   |                                  | Visibility                           | 10 miles                 |
| Lowest Ceiling:                  |                                  | Visibility (RVR):                    |                          |
| Wind Speed/Gusts:                | 6 knots /                        | Turbulence Type<br>Forecast/Actual:  | /                        |
| Wind Direction:                  | 330°                             | Turbulence Severity Forecast/Actual: | /                        |
| Altimeter Setting:               |                                  | Temperature/Dew Point:               | 0°C / 0°C                |
| Precipitation and Obscuration:   | No Obscuration; No Precipitation |                                      |                          |
| Departure Point:                 | Brigham City, UT (KBMC)          | Type of Flight Plan Filed:           |                          |
| Destination:                     | Provo, UT (KPVU)                 | Type of Clearance:                   | VFR;VFR flight following |
| Departure Time:                  | 15:13 Local                      | Type of Airspace:                    | Class C                  |

## **Airport Information**

| Airport:             | Provo Municipal Airport PVU | Runway Surface Type:             | Asphalt                   |
|----------------------|-----------------------------|----------------------------------|---------------------------|
| Airport Elevation:   | 4496 ft msl                 | <b>Runway Surface Condition:</b> | Dry                       |
| Runway Used:         | 31                          | IFR Approach:                    | None                      |
| Runway Length/Width: | 8603 ft / 150 ft            | VFR Approach/Landing:            | Full stop;Traffic pattern |

## Wreckage and Impact Information

| Crew Injuries:         | 1 None | Aircraft Damage:        | Substantial               |
|------------------------|--------|-------------------------|---------------------------|
| Passenger<br>Injuries: | N/A    | Aircraft Fire:          | None                      |
| Ground Injuries:       |        | Aircraft Explosion:     | None                      |
| Total Injuries:        | 1 None | Latitude,<br>Longitude: | 40.219167,-111.72336(est) |

Page 3 of 4 WPR24LA016

#### **Administrative Information**

Investigator In Charge (IIC):

Basti, Paymaun

Jeff Smith; FAA; Salt Lake City, UT

Persons:

Original Publish Date:

July 2, 2024

Last Revision Date:

Investigation Class:

Class 4

Note:

The NTSB did not travel to the scene of this accident.

Investigation Docket:

https://data.ntsb.gov/Docket?ProjectID=193257

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 WPR24LA016