



# **Aviation Investigation Final Report**

Location: Selma, Alabama Accident Number: ERA24LA259

Date & Time: June 12, 2024, 09:35 Local Registration: N62LP

Aircraft: Piper PA-32R-300 Aircraft Damage: Substantial

**Defining Event:** Hard landing **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

#### **Analysis**

The pilot receiving instruction was in training to obtain both a complex and high-performance endorsement. After successfully completing a touch-and-go landing and continuing in the airport traffic pattern, the flight instructor reduced engine power to idle to simulate an emergency forced landing. The airplane touched down on the left main landing gear first and then hard on the right main landing gear. Subsequently, the right main landing gear collapsed, which resulted in the right wing contacting the runway and sustaining substantial damage.

Both pilots reported that there were no preimpact mechanical malfunctions or failures with the airplane that would have precluded normal operation.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot receiving instruction's improper landing flare which resulted in a hard landing and subsequent landing gear collapse.

## **Findings**

Personnel issues	Aircraft control - Student/instructed pilot
Aircraft	Landing flare - Not attained/maintained

Page 2 of 6 ERA24LA259

## **Factual Information**

## **History of Flight**

Landing-flare/touchdown	Hard landing (Defining event)
Landing-landing roll	Landing gear collapse
Landing-landing roll	Dragged wing/rotor/float/other

#### **Pilot Information**

Certificate:	Private	Age:	43,
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	June 5, 2024
Occupational Pilot:	No	Last Flight Review or Equivalent:	August 22, 2022
Flight Time:	100 hours (Total, all aircraft), 10 hours (Total, this make and model), 34 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## Flight instructor Information

Certificate:	Airline transport; Flight instructor	Age:	75,
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	February 16, 2024
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	September 27, 2023
Flight Time:	27228 hours (Total, all aircraft), 162 hours (Total, this make and model), 24141 hours (Pilot In Command, all aircraft), 51 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ERA24LA259

#### **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N62LP
Model/Series:	PA-32R-300	Aircraft Category:	Airplane
Year of Manufacture:	1977	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	32R-7780375
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	August 22, 2023 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	206 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	9408 Hrs as of last inspection	Engine Manufacturer:	LYCOMING
ELT:	C91 installed, not activated	Engine Model/Series:	IO-540-K1G5D
Registered Owner:	MAGIC CITY AVIATORS LLC	Rated Power:	300 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

10000		_
Visual (VMC)	Condition of Light:	Day
SEM,167 ft msl	Distance from Accident Site:	0 Nautical Miles
14:35 Local	Direction from Accident Site:	34°
Clear	Visibility	10 miles
None	Visibility (RVR):	
8 knots /	Turbulence Type Forecast/Actual:	None / None
360°	Turbulence Severity Forecast/Actual:	N/A / N/A
29.93 inches Hg	Temperature/Dew Point:	31°C / 18°C
No Obscuration; No Precipitation		
Calera, AL (EET)	Type of Flight Plan Filed:	None
Selma, AL	Type of Clearance:	VFR;VFR flight following
09:00 Local	Type of Airspace:	Class D
	14:35 Local Clear None 8 knots / 360° 29.93 inches Hg No Obscuration; No Precipital Calera, AL (EET) Selma, AL	SEM,167 ft msl Distance from Accident Site:  14:35 Local Direction from Accident Site:  Clear Visibility  None Visibility (RVR):  8 knots / Turbulence Type Forecast/Actual:  360° Turbulence Severity Forecast/Actual:  29.93 inches Hg Temperature/Dew Point:  No Obscuration; No Precipitation  Calera, AL (EET) Type of Flight Plan Filed:  Selma, AL Type of Clearance:

Page 4 of 6 ERA24LA259

## **Airport Information**

Airport:	Craig Field Airport SEM	Runway Surface Type:	Asphalt;Concrete
Airport Elevation:	166 ft msl	Runway Surface Condition:	Dry
Runway Used:	33	IFR Approach:	None
Runway Length/Width:	8014 ft / 150 ft	VFR Approach/Landing:	Simulated forced landing

## Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	32.343947,-86.987806(est)

Page 5 of 6 ERA24LA259

#### **Administrative Information**

Investigator In Charge (IIC):	Stratton, Lauren
Additional Participating Persons:	Peter Rose; FAA/FSDO; Birmingham, AL
Original Publish Date:	July 18, 2024
Last Revision Date:	July 23, 2024
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=194464

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA24LA259