



Aviation Investigation Final Report

Location: Abingdon, Virginia Accident Number: ERA24LA108

Date & Time: February 4, 2024, 16:00 Local Registration: N756ZW

Aircraft: Cessna R182 Aircraft Damage: Substantial

Defining Event: Abnormal runway contact **Injuries:** 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

During a youth demonstration flight, the pilot became distracted looking for another airplane in the traffic pattern and sharing information with the young passengers. He subsequently forgot to lower the landing gear, and the airplane landed gear up, resulting in substantial damage to the fuselage. The pilot reported that there were no preaccident anomalies or malfunctions with the airplane that would have precluded normal operation and added that he heard no cockpit warnings since he was wearing a noise cancelling headset.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to lower the airplane's landing gear prior to landing, which resulted in abnormal runway contact.

Findings

Personnel issues Lack of action - Pilot

Aircraft Main landing gear - Incorrect use/operation

Factual Information

History of Flight

Landing	Landing gear not configured
Landing	Abnormal runway contact (Defining event)

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	61,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	3-point
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Helicopter; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	February 6, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 11, 2023
Flight Time:	15047 hours (Total, all aircraft), 375 hours (Total, this make and model), 14684 hours (Pilot In Command, all aircraft), 184 hours (Last 90 days, all aircraft), 45 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Passenger Information

Certificate:		Age:	Male
Airplane Rating(s):		Seat Occupied:	Center
Other Aircraft Rating(s):		Restraint Used:	3-point
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Page 2 of 5 ERA24LA108

Passenger Information

Certificate:		Age:	Male
Airplane Rating(s):		Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	3-point
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Cessna	Registration:	N756ZW
R182	Aircraft Category:	Airplane
1979	Amateur Built:	
Normal	Serial Number:	R18201208
Retractable - Tricycle	Seats:	4
August 4, 2023 Annual	Certified Max Gross Wt.:	3100 lbs
67.2 Hrs	Engines:	1 Reciprocating
4619 Hrs at time of accident	Engine Manufacturer:	Lycoming
C91 installed, not activated	Engine Model/Series:	0-540-J3C5D
On file	Rated Power:	235 Horsepower
On file	Operating Certificate(s) Held:	None
	R182 1979 Normal Retractable - Tricycle August 4, 2023 Annual 67.2 Hrs 4619 Hrs at time of accident C91 installed, not activated On file	R182 Aircraft Category: 1979 Amateur Built: Normal Serial Number: Retractable - Tricycle Seats: August 4, 2023 Annual Certified Max Gross Wt.: 67.2 Hrs Engines: 4619 Hrs at time of accident Engine Manufacturer: C91 installed, not activated Engine Model/Series: On file Rated Power: On file Operating Certificate(s)

Page 3 of 5 ERA24LA108

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
VJI,2070 ft msl	Distance from Accident Site:	0 Nautical Miles
16:35 Local	Direction from Accident Site:	150°
Clear	Visibility	10 miles
None	Visibility (RVR):	
9 knots /	Turbulence Type Forecast/Actual:	Unknown / Unknown
100°	Turbulence Severity Forecast/Actual:	N/A / N/A
29.81 inches Hg	Temperature/Dew Point:	13°C / -6°C
No Obscuration; No Precipitation		
Abingdon, VA	Type of Flight Plan Filed:	None
Abingdon, VA	Type of Clearance:	None
	Type of Airspace:	Class E
	VJI,2070 ft msl 16:35 Local Clear None 9 knots / 100° 29.81 inches Hg No Obscuration; No Precipital	VJI,2070 ft msl Distance from Accident Site: 16:35 Local Direction from Accident Site: Clear Visibility None Visibility (RVR): 9 knots / Turbulence Type Forecast/Actual: 100° Turbulence Severity Forecast/Actual: 29.81 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation Abingdon, VA Type of Flight Plan Filed: Type of Clearance:

Airport Information

Airport:	VIRGINIA HIGHLANDS VJI	Runway Surface Type:	Asphalt
Airport Elevation:	2087 ft msl	Runway Surface Condition:	Dry
Runway Used:	06	IFR Approach:	None
Runway Length/Width:	4471 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	36.686186,-82.035334

Page 4 of 5 ERA24LA108

Administrative Information

Investigator In Charge (IIC): Spencer, Lynn

Additional Participating Persons:

Original Publish Date: April 4, 2024

Last Revision Date:

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=193756

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ERA24LA108