



Aviation Investigation Final Report

Location: Friday Habor, Washington Accident Number: WPR23LA291

Date & Time: July 27, 2023, 17:15 Local Registration: N185GG

Aircraft: Cessna A185F Aircraft Damage: Substantial

Defining Event: Hard landing **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, the airplane bounced during touchdown on a 3-point landing. The pilot elected to not correct with power or to execute a go-around. During the second touchdown, he was unable to arrest the airplane veering to the right and ground looped. The airplane exited the runway and the left gear collapsed. The left wing sustained substantial damage. The pilot reported there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of directional control during landing, which resulted in a ground loop.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Factual Information

History of Flight

Landing	Hard landing (Defining event)
Landing	Loss of control on ground

Pilot Information

Certificate:	Commercial	Age:	65,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	February 9, 2023
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	May 14, 2021
Flight Time:	(Estimated) 1631 hours (Total, all aircraft), 730 hours (Total, this make and model), 1414 hours (Pilot In Command, all aircraft), 11 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 2 of 5 WPR23LA291

Aircraft and Owner/Operator Information

Cessna	Registration:	N185GG
A185F	Aircraft Category:	Airplane
1975	Amateur Built:	
Normal	Serial Number:	18502787
Tailwheel	Seats:	6
March 17, 2021 Annual	Certified Max Gross Wt.:	3600 lbs
	Engines:	1 Reciprocating
3490 Hrs as of last inspection	Engine Manufacturer:	Continental
C126 installed, activated, did not aid in locating accident	Engine Model/Series:	IO-520-D24M
On file	Rated Power:	300 Horsepower
On file	Operating Certificate(s) Held:	None
	A185F 1975 Normal Tailwheel March 17, 2021 Annual 3490 Hrs as of last inspection C126 installed, activated, did not aid in locating accident On file	A185F Aircraft Category: 1975 Amateur Built: Normal Serial Number: Tailwheel Seats: March 17, 2021 Annual Certified Max Gross Wt.: Engines: 3490 Hrs as of last inspection C126 installed, activated, did not aid in locating accident On file Rated Power: On file Operating Certificate(s)

Meteorological Information and Flight Plan

	_		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KFHR,112 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	17:53 Local	Direction from Accident Site:	209°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	None /
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	N/A /
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	21°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Seattle, WA (BFI)	Type of Flight Plan Filed:	None
Destination:	Friday Habor, WA	Type of Clearance:	Traffic advisory;VFR flight following
Departure Time:	16:30 Local	Type of Airspace:	Class G

Page 3 of 5 WPR23LA291

Airport Information

Airport:	Friday Harbor Airport FHR	Runway Surface Type:	Asphalt
Airport Elevation:	113 ft msl	Runway Surface Condition:	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	3402 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	48.521972,-123.02436

Page 4 of 5 WPR23LA291

Administrative Information

Investigator In Charge (IIC):	Blum, Contessa
Additional Participating Persons:	Lawrence Tolentino; FAA; Seattle, WA
Original Publish Date:	November 2, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192757

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR23LA291