



# **Aviation Investigation Final Report**

Location: Elbert, Colorado Accident Number: CEN24LA224

Date & Time: June 16, 2024, 15:30 Local Registration: N37JG

Aircraft: JONKER SAILPLANES (PTY) LTD
Aircraft Damage: Substantial

JS3 RES

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The glider pilot reported that during the approach, the wind shifted 180°, and he amended his pattern to land on runway 17. During touchdown, a right crosswind gust lifted the glider, and the right wing contacted tall grass adjacent to the runway. The glider yawed to the right, and the pilot attempted to correct by applying left rudder and aileron. The glider then yawed to the left, and the left wing contacted the tall grass. The glider spun 180° and came to rest upright, which resulted in substantial damage to the fuselage and left aileron. The pilot reported that there were no preaccident mechanical failures or malfunctions with the glider that would have precluded normal operation.

The pilot reported that at the time of the accident, he was landing the glider on runway 17 with a 12-knot right crosswind and wind gusts of 23 knots.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing with a right crosswind.

# Findings

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Environmental issues Crosswind - Effect on operation

**Environmental issues** Gusts - Effect on operation

Page 2 of 6 CEN24LA224

# **Factual Information**

# History of Flight

Landing-flare/touchdown	Other weather encounter	
Landing-flare/touchdown	nding-flare/touchdown Loss of control on ground (Defining event)	
Landing-flare/touchdown	Attempted remediation/recovery	
Landing-flare/touchdown	Collision with terr/obj (non-CFIT)	

### **Pilot Information**

Certificate:	Commercial; Private	Age:	61,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	Glider	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	September 1, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 24, 2024
Flight Time:	1206 hours (Total, all aircraft), 31 hours (Total, this make and model), 1140 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 11 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CEN24LA224

### **Aircraft and Owner/Operator Information**

Aircraft Make:	JONKER SAILPLANES (PTY) LTD	Registration:	N37JG
Model/Series:	JS3 RES	Aircraft Category:	Glider
Year of Manufacture:	2023	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	03-179
Landing Gear Type:	Retractable - None; Ski/wheel	Seats:	1
Date/Type of Last Inspection:	November 3, 2024 Condition	Certified Max Gross Wt.:	1323 lbs
Time Since Last Inspection:		Engines:	1 Electric
Airframe Total Time:	32.5 Hrs as of last inspection	Engine Manufacturer:	Solo
ELT:	Not installed	Engine Model/Series:	RES
Registered Owner:	On file	Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMNH,7060 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	15:35 Local	Direction from Accident Site:	142°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	16 knots / 20 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.93 inches Hg	Temperature/Dew Point:	28°C / 0°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Elbert, CO	Type of Flight Plan Filed:	None
Destination:	Elbert, CO	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 4 of 6 CEN24LA224

# **Airport Information**

Airport:	KELLY AIR PARK CO15	Runway Surface Type:	Asphalt
Airport Elevation:	7040 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	17/35	IFR Approach:	None
Runway Length/Width:	3800 ft / 36 ft	VFR Approach/Landing:	Full stop

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.223726,-104.63974(est)

Page 5 of 6 CEN24LA224

#### **Administrative Information**

Investigator In Charge (IIC): Sauer, Aaron

Additional Participating Persons:

Original Publish Date: July 25, 2024

Last Revision Date:

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=194481

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN24LA224