



# **Aviation Investigation Final Report**

Location: Charlotte Amalie, Caribbean Sea **Accident Number:** ERA23LA257

Date & Time: June 4, 2023, 14:50 Local Registration: N7037E

Aircraft: Cessna 402 Aircraft Damage: Minor

1 Serious, 1 Minor, 4 **Defining Event:** Birdstrike Injuries:

None

Flight Conducted Under: Part 135: Air taxi & commuter - Scheduled

#### **Analysis**

The operator reported that while entering the traffic pattern for landing, the pilot saw a large bird and attempted to take evasive action, but the airplane and the bird collided. The bird entered the cabin through the right windscreen and struck two passengers. One passenger sustained serious injuries while the other passenger incurred minor injuries. The pilot declared an emergency and subsequently landed the airplane uneventfully. The operator reported that there were no preaccident mechanical malfunctions or failures of the airplane that would have precluded normal operation.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

An in-flight collision with a bird while entering the traffic pattern.

#### **Findings**

**Environmental issues** Animal(s)/bird(s) - Effect on equipment

### **Factual Information**

### **History of Flight**

Approach-VFR pattern downwind
-------------------------------

#### **Pilot Information**

Certificate:	Airline transport	Age:	45,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	December 13, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 5, 2023
Flight Time:	2129 hours (Total, all aircraft), 266 hours (Total, this make and model), 1682 hours (Pilot In Command, all aircraft), 170 hours (Last 90 days, all aircraft), 60 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

#### **Passenger Information**

Certificate:	Age:	
Airplane Rating(s):	Seat Occupied:	Right
Other Aircraft Rating(s):	Restraint Used:	Lap only
Instrument Rating(s):	Second Pilot Present:	No
Instructor Rating(s):	Toxicology Performed:	
Medical Certification:	Last FAA Medical Exam:	
Occupational Pilot:	Last Flight Review or Equivalent:	
Flight Time:		

Page 2 of 6 ERA23LA257

**Passenger Information** 

Certificate:	Age:	Female
Airplane Rating(s):	Seat Occupied:	Right
Other Aircraft Rating(s):	Restraint Used:	Lap only
Instrument Rating(s):	Second Pilot Present:	No
Instructor Rating(s): Toxicology Performed:		
Medical Certification: Last FAA Medical Exam:		
Occupational Pilot:	Last Flight Review or Equivalent:	
Flight Time:		

### **Passenger Information**

Age:	
Seat Occupied:	Unknown
Restraint Used:	Lap only
Second Pilot Present:	No
Toxicology Performed:	
Last FAA Medical Exam:	
Last Flight Review or Equivalent:	
	Seat Occupied: Restraint Used: Second Pilot Present: Toxicology Performed: Last FAA Medical Exam:

#### **Passenger Information**

Certificate:	Age:	
Airplane Rating(s):	Seat Occupied:	Left
Other Aircraft Rating(s):	Restraint Used:	Lap only
Instrument Rating(s):	Second Pilot Present:	No
Instructor Rating(s):	Toxicology Performed:	
Medical Certification:	Last FAA Medical Exam:	
Occupational Pilot:	Last Flight Review or Equivalent:	
Flight Time:		

Page 3 of 6 ERA23LA257

### **Passenger Information**

Certificate:	Age:	
Airplane Rating(s):	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Restraint Used:	Lap only
Instrument Rating(s):	Second Pilot Present:	No
Instructor Rating(s):	Toxicology Performed:	
Medical Certification:	Last FAA Medical Exam:	
Occupational Pilot:	Last Flight Review or Equivalent:	
Flight Time:		

### Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N7037E
Model/Series:	402 C	Aircraft Category:	Airplane
Year of Manufacture:	1981	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	402C0471
Landing Gear Type:	Retractable - Tricycle	Seats:	10
Date/Type of Last Inspection:	May 17, 2023 AAIP	Certified Max Gross Wt.:	7210 lbs
Time Since Last Inspection:	51 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	38473.2 Hrs at time of accident	Engine Manufacturer:	CONTINENTAL MOTOR
ELT:	C91A installed, not activated	Engine Model/Series:	TSIO520VB
Registered Owner:	HYANNIS AIR SERVICE INC	Rated Power:	325 Horsepower
Operator:	HYANNIS AIR SERVICE INC	Operating Certificate(s) Held:	Commuter air carrier (135), On-demand air taxi (135)
Operator Does Business As:	Cape Air	Operator Designator Code:	HYIA

Page 4 of 6 ERA23LA257

#### **Meteorological Information and Flight Plan**

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	TIST,46 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	14:53 Local	Direction from Accident Site:	305°
<b>Lowest Cloud Condition:</b>	Few / 2100 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.91 inches Hg	Temperature/Dew Point:	31°C / 26°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Roadtown, OF (TUPJ)	Type of Flight Plan Filed:	None
Destination:	Charlotte Amalie, CB	Type of Clearance:	VFR
Departure Time:	14:40 Local	Type of Airspace:	Class C

### **Airport Information**

Airport:	Cyril E King Airport TIST	Runway Surface Type:	Asphalt
Airport Elevation:	23 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	10	IFR Approach:	None
Runway Length/Width:	7000 ft / 150 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Minor
Passenger Injuries:	1 Serious, 1 Minor, 3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 Minor, 4 None	Latitude, Longitude:	17.694145,-64.801191(est)

Page 5 of 6 ERA23LA257

#### **Administrative Information**

Investigator In Charge (IIC):	Young, Joshua
Additional Participating Persons:	John Callahan; FAA/FSDO; Boston, MA
Original Publish Date:	July 7, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192322

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA23LA257