



Aviation Investigation Final Report

Location: Novato, California Accident Number: WPR23LA253

Date & Time: June 30, 2023, 14:00 Local Registration: N372AH

Aircraft: Cessna 172S Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, during the landing roll for a touch-and-go, he retracted the flaps and advanced the throttle to full. Subsequently, the airplane veered hard left and the pilot attempted to correct with opposite rudder control; however, the airplane exited the runway. The airplane impacted terrain and came to rest in a shallow creek, in which both wings were substantially damaged. The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control of the airplane during the landing roll for a touch and go, which resulted in a collision with terrain.

Findings

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Page 2 of 6 WPR23LA253

Factual Information

History of Flight

Landing-aborted after touchdown	Loss of control on ground (Defining event)
Landing-aborted after touchdown	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Private	Age:	51,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	May 10, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 16, 2022
Flight Time:	450 hours (Total, all aircraft), 112 hours (Total, this make and model), 340 hours (Pilot In Command, all aircraft), 14 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Page 3 of 6 WPR23LA253

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N372AH
Model/Series:	172S	Aircraft Category:	Airplane
Year of Manufacture:	2006	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	172S10156
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	June 1, 2023 100 hour	Certified Max Gross Wt.:	2558 lbs
Time Since Last Inspection:	31 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3679 Hrs at time of accident	Engine Manufacturer:	LYCOMING
ELT:	C126 installed, activated, aided in locating accident	Engine Model/Series:	IO-360-L2A
Registered Owner:	SCANLON AVIATION LLC	Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	On-demand air taxi (135)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KDVO,4 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	14:15 Local	Direction from Accident Site:	41°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	120°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.87 inches Hg	Temperature/Dew Point:	32°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Novato, CA (KDVO)	Type of Flight Plan Filed:	None
Destination:	Novato, CA	Type of Clearance:	None
Departure Time:	12:30 Local	Type of Airspace:	Class G

Page 4 of 6 WPR23LA253

Airport Information

Airport:	Gnoss Field Airport DVO	Runway Surface Type:	Asphalt
Airport Elevation:	4 ft msl	Runway Surface Condition:	Dry
Runway Used:	13	IFR Approach:	None
Runway Length/Width:	3303 ft / 75 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.143576,-122.55709

Page 5 of 6 WPR23LA253

Administrative Information

Investigator In Charge (IIC):	Johnson, Scott
Additional Participating Persons:	Joe Stein; Federal Aviation Administration
Original Publish Date:	November 2, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192525

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR23LA253