



Aviation Investigation Final Report

Location: McCall, Idaho **Accident Number**: WPR23LA250

Date & Time: July 3, 2023, 11:09 Local Registration: N36KG

Aircraft: Piper PA-18 Aircraft Damage: Substantial

Defining Event: Nose over/nose down **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel equipped airplane reported that, during landing, he positioned his feet on the heel brake pedals and applied wheel brakes. When the airplane's tail rose, the pilot's heels remained on the brake pedals and the airplane nosed over and came to rest inverted. The wing struts and rudder were substantially damaged. The pilot reported that there were no preaccident mechanical malfunctions or failures that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's application of wheel brakes during landing roll out, resulting in a nose over.

Findings

Personnel issues Aircraft control - Pilot

Personnel issues Incorrect action performance - Pilot

Aircraft Pitch control - Not attained/maintained

Factual Information

History of Flight

Landing-landing roll	Nose over/nose down (Defining event)	
----------------------	--------------------------------------	--

Pilot Information

Certificate:	Commercial	Age:	56,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	July 20, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	January 10, 2022
Flight Time:	3741.5 hours (Total, all aircraft), 143.9 hours (Total, this make and model), 3605.9 hours (Pilot In Command, all aircraft), 65.4 hours (Last 90 days, all aircraft), 10.7 hours (Last 30 days, all aircraft), 0.6 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N36KG
Model/Series:	PA-18	Aircraft Category:	Airplane
Year of Manufacture:	1955	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18-4586
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	October 1, 2022 Annual	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:	56.9 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5632.9 Hrs at time of accident	Engine Manufacturer:	LYCOMING
ELT:	C126 installed, activated, aided in locating accident	Engine Model/Series:	O-320-A1A
Registered Owner:	On file	Rated Power:	160 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 2 of 4 WPR23LA250

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMYL,5023 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	10:51 Local	Direction from Accident Site:	212°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.05 inches Hg	Temperature/Dew Point:	19°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	McCall, ID	Type of Flight Plan Filed:	None
Destination:	McCall, ID	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class E

Airport Information

Airport:	McCall Municipal Airport KMYL	Runway Surface Type:	Asphalt
Airport Elevation:	5024 ft msl	Runway Surface Condition:	Dry;Vegetation
Runway Used:	16/34	IFR Approach:	None
Runway Length/Width:	6101 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.89425,-116.09978

Page 3 of 4 WPR23LA250

Administrative Information

Investigator In Charge (IIC):	Blocher, Kristyn
Additional Participating Persons:	Tim Greenwell; Federal Aviation Administration; Boise, ID
Original Publish Date:	November 2, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192521

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 WPR23LA250