



Location: Bandera, Washington Accident Number: WPR24LA022

Date & Time: October 18, 2023, 13:39 Local Registration: N734LJ

Aircraft: Cessna 172N Aircraft Damage: Substantial

Defining Event: Nose over/nose down **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that during landing on the 2,344 ft grass runway, the airplane floated and touched down near mid-field. The pilot applied the brakes and retracted the flaps, but the turf runway was waterlogged, and the airplane exited the end of the runway and nosed over. According to the airport's chart supplement, the airport was closed from October 1, 2023, to June 1, 2023. The airplane sustained substantial damage to the left wing spar.

The pilot reported that there were no preimpact mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's decision to land at a closed water-soaked grass runway, which resulted in a runway excursion.

Findings

Environmental issues	Wet surface - Effect on equipment
Personnel issues	Performance calculations - Pilot
Aircraft	Surface speed/braking - Not attained/maintained

Page 2 of 7 WPR24LA022

Factual Information

History of Flight

Landing-landing roll	Runway excursion
Landing-landing roll	Nose over/nose down (Defining event)

Pilot Information

Certificate:	Private	Age:	19,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 None	Last FAA Medical Exam:	October 4, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	June 16, 2023
Flight Time:	(Estimated) 134.1 hours (Total, all aircraft), 78 hours (Total, this make and model), 81.4 hours (Pilot In Command, all aircraft), 47 hours (Last 90 days, all aircraft), 23.5 hours (Last 30 days, all aircraft), 1.3 hours (Last 24 hours, all aircraft)		

Page 3 of 7 WPR24LA022

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N734LJ
Model/Series:	172N	Aircraft Category:	Airplane
Year of Manufacture:	1977	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17268935
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	September 12, 2023 Annual	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:	60.4 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4549.9 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-260-H2AD
Registered Owner:	James Mitchell	Rated Power:	160 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
KSMP,3967 ft msl	Distance from Accident Site:	11 Nautical Miles
13:56 Local	Direction from Accident Site:	112°
	Visibility	10 miles
	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	/
	Turbulence Severity Forecast/Actual:	/
30.15 inches Hg	Temperature/Dew Point:	18°C / 8°C
Easton , WA (ESW)	Type of Flight Plan Filed:	None
Bandera, WA (4W0)	Type of Clearance:	VFR
13:05 Local	Type of Airspace:	Class G
	KSMP,3967 ft msl 13:56 Local / 30.15 inches Hg Easton , WA (ESW) Bandera, WA (4W0)	KSMP,3967 ft msl Distance from Accident Site: 13:56 Local Direction from Accident Site: Visibility Visibility (RVR): Turbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: 30.15 inches Hg Temperature/Dew Point: Easton, WA (ESW) Type of Flight Plan Filed: Type of Clearance:

Page 4 of 7 WPR24LA022

Airport Information

Airport:	BANDERA STATE 4W0	Runway Surface Type:	Asphalt
Airport Elevation:	1636 ft msl	Runway Surface Condition:	Wet
Runway Used:	08/26	IFR Approach:	None
Runway Length/Width:	2344 ft / 100 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	47.395369,-121.53647(est)

Preventing Similar Accidents

Manage Risk: Good Decision-making and Risk Management Practices are Critical (SA-023)

The Problem

Although few pilots knowingly accept severe risks, accidents can also result when several risks of marginal severity are not identified or are ineffectively managed by the pilot and compound into a dangerous situation. Accidents also result when the pilot does not accurately perceive situations that involve high levels of risk. Ineffective risk management or poor aeronautical decision-making can be associated with almost any type of fatal general aviation accident.

What can you do?

Page 5 of 7 WPR24LA022

- Develop good decision-making practices that will allow you to identify personal
 attitudes that are hazardous to safe flying, apply behavior modification techniques,
 recognize and cope with stress, and effectively use all resources. Understand the safety
 hazards associated with human fatigue and strive to eliminate fatigue contributors in
 your life.
- Understand that effective risk management takes practice. It is a decision-making process by which you can systematically identify hazards, assess the degree of risk, and determine the best course of action.
- Be honest with yourself and your passengers about your skill level and proficiency.
 Refuse to allow external pressures, such as the desire to save time or money or the fear of disappointing passengers, to influence you to attempt or continue a flight in conditions in which you are not comfortable.
- Be honest with yourself and the FAA about your medical condition. If you have a
 medical condition or are taking any medication, do not fly until your fitness for flight has
 been thoroughly evaluated.
- Plan ahead with flight diversion or cancellation alternatives, and brief your passengers about the alternatives before the flight.

See https://www.ntsb.gov/Advocacy/safety-alerts/Documents/SA-023.pdf for additional resources.

The NTSB presents this information to prevent recurrence of similar accidents. Note that this should not be considered guidance from the regulator, nor does this supersede existing FAA Regulations (FARs).

Page 6 of 7 WPR24LA022

Administrative Information

Investigator In Charge (IIC):	Hicks, Michael
Additional Participating Persons:	John Williams; FAA; Seattle, WA
Original Publish Date:	June 6, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193299

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 7 of 7 WPR24LA022