



Aviation Investigation Final Report

Location: Oklahoma City, Oklahoma Accident Number: CEN24LA130

Date & Time: March 4, 2024, 16:25 Local Registration: N1955W

Aircraft: Beech B19 Aircraft Damage: Substantial

Defining Event: Aerodynamic stall/spin **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The student pilot was conducting his first solo flight. He reported that during the first landing attempt he flared the airplane too early, which resulted in a bounced landing. He pitched the nose down and the airplane bounced into the air again, then the pitched the nose up. The airplane stalled and impacted the runway in a nose low attitude, which resulted in the nose landing gear collapse and substantial damage to the left wing. The student pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's improper landing flare, which resulted in a bounced landing, aerodynamic stall, and impact with the runway.

Findings

Aircraft Angle of attack - Not attained/maintained

Personnel issues Aircraft control - Pilot

Page 2 of 5 CEN24LA130

Factual Information

History of Flight

Landing-flare/touchdown	Aerodynamic stall/spin (Defining event)	
-------------------------	---	--

Pilot Information

Certificate:	Student	Age:	38,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	August 8, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	33 hours (Total, all aircraft), 5 hours (Total, this make and model), 0 hours (Pilot In Command, all aircraft), 16 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N1955W
Model/Series:	B19	Aircraft Category:	Airplane
Year of Manufacture:	1973	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	MB-619
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	January 12, 2024 Annual	Certified Max Gross Wt.:	2155 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3669 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	0-320-E2D
Registered Owner:	On file	Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN24LA130

Meteorological Information and Flight Plan

tical Miles	
es	
6°C	
No Obscuration; No Precipitation	
ì	

Airport Information

Airport:	SUNDANCE HSD	Runway Surface Type:	Concrete
Airport Elevation:	1192 ft msl	Runway Surface Condition:	Dry
Runway Used:	18/36	IFR Approach:	None
Runway Length/Width:	5001 ft / 100 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	35.601216,-97.706136(est)

Page 4 of 5 CEN24LA130

Administrative Information

Investigator In Charge (IIC):	Lindberg, Joshua
Additional Participating Persons:	Mathew Wineland; Federal Aviation Administration; Oklahoma City, OK
Original Publish Date:	April 12, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193910

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN24LA130