



# **Aviation Investigation Final Report**

Location: White Plains, New York Accident Number: ERA23LA186

Date & Time: April 3, 2023, 15:30 Local Registration: N8500D

Aircraft: Piper PA22 Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot landed in gusting wind. He reported that after touchdown the airplane veered to the left. He attempted to correct with aileron and rudder; however, the airplane departed the runway, the left wing struck the ground, and the airplane nosed over. The pilot reported that there were no preimpact mechanical malfunctions or failures with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing rollout in gusting wind, which resulted in a runway excursion and subsequent nose over.

#### **Findings**

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Environmental issues Crosswind - Response/compensation

### **Factual Information**

### **History of Flight**

Landing-landing roll	Loss of control on ground (Defining event)	
Landing-landing roll	Runway excursion	
Landing-landing roll	Nose over/nose down	

#### **Pilot Information**

Certificate:	Private	Age:	76,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	BasicMed With waivers/limitations	Last FAA Medical Exam:	July 12, 2013
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 14, 2022
Flight Time:	4797 hours (Total, all aircraft), 2356 hours (Total, this make and model), 4680 hours (Pilot In Command, all aircraft), 9 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N8500D
Model/Series:	PA22 160	Aircraft Category:	Airplane
Year of Manufacture:	1957	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22-5727
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	November 12, 2022 Annual	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:	18.5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5257 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	0320-B2A
Registered Owner:	On file	Rated Power:	160 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 2 of 4 ERA23LA186

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	HPN,370 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	14:56 Local	Direction from Accident Site:	313°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots / 22 knots	Turbulence Type Forecast/Actual:	Unknown / Unknown
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	Unknown / N/A
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	13°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Honesdale, PA (N30)	Type of Flight Plan Filed:	None
Destination:	White Plains, NY	Type of Clearance:	VFR flight following
Departure Time:	14:30 Local	Type of Airspace:	Class D

### **Airport Information**

Airport:	WESTCHESTER COUNTY HPN	Runway Surface Type:	Asphalt
Airport Elevation:	439 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	6549 ft / 150 ft	VFR Approach/Landing:	Full stop

### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	41.065785,-73.706291

Page 3 of 4 ERA23LA186

#### **Administrative Information**

Investigator In Charge (IIC):Spencer, LynnAdditional Participating Persons:Donald Smith; FAA; Farmingdale, NYOriginal Publish Date:June 29, 2023Last Revision Date:Investigation Class:Investigation Class:Class 4Note:The NTSB did not travel to the scene of this accident.Investigation Docket:https://data.ntsb.gov/Docket?ProjectID=107028

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ERA23LA186