

# **Aviation Investigation Final Report**

Location: Gallipolis, Ohio Accident Number: ERA24LA002

Date & Time: October 2, 2023, 19:15 Local Registration: N7461W

Aircraft: Piper PA-28-180 Aircraft Damage: Substantial

**Defining Event:** Landing gear collapse **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The student pilot approached the runway for landing and described that the main landing gear first touched down first. The nose landing gear then contacted the runway and immediately collapsed. The student pilot applied the brakes and the airplane departed the left side of the runway onto the grass. The airplane struck a lighting system and came to rest about 35 ft from the runway, which resulted in substantial damage to the right wing. The student pilot reported "there were no visible signs of mechanical failure" on the nose landing gear prior to the accident flight, and a Federal Aviation Administration inspector who examined the nose landing gear after the accident did not observe any mechanical discrepancies.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A collapse of the nose landing gear during landing, which resulted in a runway excursion and collision with an approach lighting system.

## Findings

Aircraft	Directional control - Attain/maintain not possible
Aircraft	Nose/tail landing gear - Not specified

Page 2 of 5 ERA24LA002

## **Factual Information**

## History of Flight

Landing-landing roll	Landing gear collapse (Defining event)
Landing-landing roll	Runway excursion

### **Pilot Information**

			40.14
Certificate:	Student	Age:	48,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	July 26, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	87 hours (Total, all aircraft), 87 hours (Total, this make and model), 18 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N7461W
Model/Series:	PA-28-180	Aircraft Category:	Airplane
Year of Manufacture:	1963	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	28-1367
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	March 30, 2023 Annual	Certified Max Gross Wt.:	2400 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2649.9 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	O-360-A3A
Registered Owner:	On file	Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 ERA24LA002

## Meteorological Information and Flight Plan

Conditions at Accident Site:Visual (VMC)Condition of Light:DuskObservation Facility, Elevation:PKB,805 ft mslDistance from Accident Site:45 Nautical MilesObservation Time:19:53 LocalDirection from Accident Site:48°Lowest Cloud Condition:ClearVisibility10 milesLowest Ceiling:NoneVisibility (RVR):Wind Speed/Gusts:/Turbulence Type Forecast/Actual:Unknown / NoneWind Direction:Turbulence Severity Forecast/Actual:N/A / N/AAltimeter Setting:30.2 inches HgTemperature/Dew Point:21°C / 18°CPrecipitation and Obscuration:No Obscuration; No Precipitation Precipitation and Obscuration:No Obscuration; No Precipitation Precipita				
Observation Time:       19:53 Local       Direction from Accident Site:       48°         Lowest Cloud Condition:       Clear       Visibility       10 miles         Lowest Ceiling:       None       Visibility (RVR):         Wind Speed/Gusts:       /       Turbulence Type Forecast/Actual:       Unknown / None         Wind Direction:       Turbulence Severity Forecast/Actual:       N/A / N/A         Altimeter Setting:       30.2 inches Hg       Temperature/Dew Point:       21°C / 18°C         Precipitation and Obscuration:       No Obscuration; No Precipitation       Type of Flight Plan Filed:       None         Departure Point:       Gallipolis, OH       Type of Clearance:       VFR flight following	Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dusk
Lowest Cloud Condition:  Clear  Visibility  None  Visibility (RVR):  Wind Speed/Gusts:  / Turbulence Type Forecast/Actual:  N/A / N/A  Forecast/Actual:  N/A / N/A  Altimeter Setting:  30.2 inches Hg  Temperature/Dew Point:  Precipitation and Obscuration:  No Obscuration; No Precipitation  Departure Point:  Charleston, WV (CRW)  Type of Flight Plan Filed:  VFR flight following	Observation Facility, Elevation:	PKB,805 ft msl	Distance from Accident Site:	45 Nautical Miles
Lowest Ceiling: None Visibility (RVR):  Wind Speed/Gusts: / Turbulence Type Forecast/Actual:  Wind Direction: Turbulence Severity Forecast/Actual: N/A / N/A  Altimeter Setting: 30.2 inches Hg Temperature/Dew Point: 21°C / 18°C  Precipitation and Obscuration: No Obscuration; No Precipitation  Departure Point: Charleston, WV (CRW) Type of Flight Plan Filed: None  Destination: VFR flight following	Observation Time:	19:53 Local	Direction from Accident Site:	48°
Wind Speed/Gusts:  Wind Direction:  Turbulence Severity Forecast/Actual:  N/A / N/A  Altimeter Setting:  30.2 inches Hg  Temperature/Dew Point:  Precipitation and Obscuration:  No Obscuration; No Precipitation  Departure Point:  Charleston, WV (CRW)  Type of Flight Plan Filed:  None  VFR flight following	<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Wind Direction:  Turbulence Severity Forecast/Actual:  Altimeter Setting:  30.2 inches Hg  Temperature/Dew Point:  21°C / 18°C  Precipitation and Obscuration:  No Obscuration; No Precipitation  Departure Point:  Charleston, WV (CRW)  Type of Flight Plan Filed:  None  Oestination:  VFR flight following	Lowest Ceiling:	None	Visibility (RVR):	
Forecast/Actual:  Altimeter Setting: 30.2 inches Hg Temperature/Dew Point: 21°C / 18°C  Precipitation and Obscuration: No Obscuration; No Precipitation  Departure Point: Charleston, WV (CRW) Type of Flight Plan Filed: None  Destination: VFR flight following	Wind Speed/Gusts:	/	,,	Unknown / None
Precipitation and Obscuration:  No Obscuration; No Precipitation  Departure Point:  Charleston, WV (CRW)  Type of Flight Plan Filed:  None  VFR flight following	Wind Direction:			N/A / N/A
Departure Point:       Charleston, WV (CRW)       Type of Flight Plan Filed:       None         Destination:       Gallipolis, OH       Type of Clearance:       VFR flight following	Altimeter Setting:	30.2 inches Hg	Temperature/Dew Point:	21°C / 18°C
Destination: Gallipolis, OH Type of Clearance: VFR flight following	Precipitation and Obscuration:	No Obscuration; No Precipitation		
	Departure Point:	Charleston, WV (CRW)	Type of Flight Plan Filed:	None
<b>Departure Time:</b> 18:50 Local <b>Type of Airspace:</b> Class D	Destination:	Gallipolis, OH	Type of Clearance:	VFR flight following
	Departure Time:	18:50 Local	Type of Airspace:	Class D

## **Airport Information**

Airport:	GALLIA-MEIGS RGNL GAS	Runway Surface Type:	Asphalt
Airport Elevation:	565 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	05/23	IFR Approach:	None
Runway Length/Width:	3999 ft / 75 ft	VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.834111,-82.16343(est)

Page 4 of 5 ERA24LA002

#### **Administrative Information**

Investigator In Charge (IIC):	Kemner, Heidi
Additional Participating Persons:	Larry Ward; FAA/FSDO; Cincinatti , OH
Original Publish Date:	December 21, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193186

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ERA24LA002