



Aviation Investigation Final Report

Location: Baker City, Oregon Accident Number: WPR24LA033

Date & Time: November 9, 2023, 12:00 Local Registration: N418BS

Aircraft: Piper PA-12 Aircraft Damage: Substantial

Defining Event: Fuel exhaustion **Injuries:**

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported a total loss of engine power resulting from fuel exhaustion, approximately one mile from the airport. While executing a forced landing in a farm field, a strong crosswind gust raised one wing. The pilot was unable to recover from this since no power authority was available. When the airplane contacted terrain, the landing gear and wingtip struck the ground, and the airplane ground looped. The airplane sustained substantial damage to its wings. The pilot reported that there were no mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's inadequate fuel planning, which resulted in a total loss of engine power due to fuel exhaustion.

Findings

Personnel issues Preflight inspection - Pilot

Personnel issues Fuel planning - Pilot

Personnel issues Decision making/judgment - Pilot

Aircraft Fuel - Fluid level

Environmental issues Rough terrain - Contributed to outcome

Page 2 of 5 WPR24LA033

Factual Information

History of Flight

Landing	Fuel exhaustion (Defining event)
Landing-flare/touchdown	Off-field or emergency landing

Pilot Information

Certificate:	Commercial	Age:	73
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Unknown	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	March 12, 2021
Flight Time:	2764 hours (Total, all aircraft), 753.8 hours (Total, this make and model), 6.4 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N418BS
Model/Series:	PA-12	Aircraft Category:	Airplane
Year of Manufacture:	1947	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	12-2831
Landing Gear Type:	Tailwheel	Seats:	3
Date/Type of Last Inspection:	October 4, 2023 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:	11.91 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-320-A2B
Registered Owner:	TWIN BUTTES LLC	Rated Power:	160
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 WPR24LA033

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
KBKE,3363 ft msl	Distance from Accident Site:	0 Nautical Miles
11:53 Local	Direction from Accident Site:	1°
Clear	Visibility	10 miles
None	Visibility (RVR):	
18 knots / 25 knots	Turbulence Type Forecast/Actual:	/
120°	Turbulence Severity Forecast/Actual:	/
30.24 inches Hg	Temperature/Dew Point:	7°C / -1°C
No Obscuration; No Precipitation		
Mitchell, OR	Type of Flight Plan Filed:	None
Baker City, OR (BKE)	Type of Clearance:	None
10:45 Local	Type of Airspace:	Class G
	KBKE,3363 ft msl 11:53 Local Clear None 18 knots / 25 knots 120° 30.24 inches Hg No Obscuration; No Precipitate Mitchell, OR Baker City, OR (BKE)	KBKE,3363 ft msl Distance from Accident Site: 11:53 Local Direction from Accident Site: Clear Visibility None Visibility (RVR): 18 knots / 25 knots Turbulence Type Forecast/Actual: 120° Turbulence Severity Forecast/Actual: 30.24 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation Mitchell, OR Type of Flight Plan Filed: Baker City, OR (BKE) Type of Clearance:

Airport Information

Airport:	Baker City Airport KBKE	Runway Surface Type:	
Airport Elevation:	3375 ft msl	Runway Surface Condition:	Dry
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	N/A	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	N/A	Latitude, Longitude:	44.837333,-117.80913(est)

Page 4 of 5 WPR24LA033

Administrative Information

Investigator In Charge (IIC):	Basti, Paymaun
Additional Participating Persons:	Patrick Darling; Federal Aviation Administration; Boise, ID
Original Publish Date:	June 6, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193378

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR24LA033