

Aviation Investigation Final Report

Location: Alexandria, Louisiana Accident Number: CEN24LA126

Date & Time: February 28, 2024, 15:52 Local Registration: N7770K

Aircraft: Cessna 180 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot encountered a gust of wind about halfway through his landing roll. He was unable to counter the gust with full aileron and rudder deflections, which resulted in a loss on control and ground loop. The airplane sustained substantial damage to the right wing, right horizontal stabilizer, and right elevator. The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation. At the time of the accident the pilot was landing the airplane on runway 9 with wind from 020° at 12 knots with gusts to 22 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing roll with a gusting crosswind.

Findings

Personnel issues Aircraft control - Pilot

Environmental issues Gusts - Ability to respond/compensate

Aircraft Directional control - Not attained/maintained

Page 2 of 5 CEN24LA126

Factual Information

History of Flight

Landing-landing roll	Other weather encounter	
Landing-landing roll	Attempted remediation/recovery	
Landing-landing roll	Loss of control on ground (Defining event)	

Pilot Information

Certificate:	Private	Age:	73,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	December 12, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1790 hours (Total, all aircraft), 360 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N7770K
Model/Series:	180 J	Aircraft Category:	Airplane
Year of Manufacture:	1976	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18052726
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	January 13, 2024 Annual	Certified Max Gross Wt.:	3190 lbs
Time Since Last Inspection:	29.7 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2333.7 Hrs at time of accident	Engine Manufacturer:	CONT MOTOR
ELT:	C126 installed, not activated	Engine Model/Series:	0-470 SERIES
Registered Owner:	On file	Rated Power:	230 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN24LA126

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KESF,112 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	15:53 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	12 knots / 22 knots	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.18 inches Hg	Temperature/Dew Point:	17°C / 1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Dauphin Island, LA (4R9)	Type of Flight Plan Filed:	None
Destination:	Pineville, LA (ESF)	Type of Clearance:	None
Departure Time:	13:48 Local	Type of Airspace:	Class E

Airport Information

Airport:	ESLER RGNL ESF	Runway Surface Type:	Asphalt
Airport Elevation:	111 ft msl	Runway Surface Condition:	Dry
Runway Used:	09/27	IFR Approach:	None
Runway Length/Width:	5998 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	31.394904,-92.295773(est)

Page 4 of 5 CEN24LA126

Administrative Information

Investigator In Charge (IIC): Miller, Bradley

Additional Participating Persons: Myron Billiot; FAA; Baton Rouge, LA

Original Publish Date: April 12, 2024

Last Revision Date: Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=193875

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN24LA126