



Aviation Investigation Final Report

Location: Oscoda, Michigan Accident Number: CEN24LA201

Date & Time: May 28, 2024, 12:30 Local Registration: N9206A

Aircraft: Cessna 170A Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the personal flight reported that he planned on practicing takeoffs and landings at the departure airport; however, once airborne, the winds began gusting. During the first landing, the airplane touched down on the runway with a gusting crosswind. Due to the crosswind, he was unable to maintain directional control during the landing rollout, and the airplane skidded to the left and nosed over on the runway. The airplane sustained substantial damage to the fuselage, wings, and empennage. The pilot reported that there were no mechanical failures or malfunctions with the airplane that would have precluded normal operation.

At the time of the accident, the airplane was landing on runway 07 with wind 341° at 15 knots with gusts over 20 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing rollout with a gusting crosswind that resulted in the airplane nosing over and impacting on the runway.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Crosswind - Effect on operation

Environmental issues Gusts - Effect on operation

Page 2 of 6 CEN24LA201

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event)	
Landing-landing roll	Nose over/nose down	
Landing-landing roll	Collision with terr/obj (non-CFIT)	

Pilot Information

Certificate:	Private	Age:	63,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	BasicMed Without waivers/limitations	Last FAA Medical Exam:	June 13, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 5, 2024
Flight Time:	359.4 hours (Total, all aircraft), 73.5 hours (Total, this make and model), 359.4 hours (Pilot In Command, all aircraft), 4.6 hours (Last 90 days, all aircraft), 4.6 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CEN24LA201

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9206A
Model/Series:	170A	Aircraft Category:	Airplane
Year of Manufacture:	1949	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18967
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	July 21, 2023 Annual	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	4446.4 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	C-145
Registered Owner:	On file	Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	OSC,633 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	12:30 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 4400 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	12 knots / 16 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	320°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.84 inches Hg	Temperature/Dew Point:	23°C / 10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Oscoda, MI	Type of Flight Plan Filed:	None
Destination:	Oscoda, MI	Type of Clearance:	VFR
Departure Time:		Type of Airspace:	Class C

Page 4 of 6 CEN24LA201

Airport Information

Airport:	Oscoda/Wurtsmith Airport OSC	Runway Surface Type:	Asphalt
Airport Elevation:	633 ft msl	Runway Surface Condition:	Dry
Runway Used:	7	IFR Approach:	None
Runway Length/Width:	11800 ft / 200 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.451528,-83.394167(est)

Page 5 of 6 CEN24LA201

Administrative Information

Investigator In Charge (IIC):	Gallo, Mitchell
Additional Participating Persons:	Ramon Grillo; FAA FSDO; Grand Rapids, MI
Original Publish Date:	July 25, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=194340

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN24LA201