



# **Aviation Investigation Final Report**

Location: Midland, Texas Accident Number: CEN23LA421

Date & Time: September 22, 2023, 07:30 Local Registration: N391SP

Aircraft: Cessna 172S Aircraft Damage: Substantial

**Defining Event:** Hard landing **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

The student pilot reported, that during the landing flare, the airplane floated down the runway. He attempted to settle the airplane softly onto the runway, but the airplane bounced twice and came to rest in the dirt on the side of the runway. A post-accident examination revealed that the nose landing gear folded forward, which resulted in substantial damage to the tunnel structure. The student pilot reported that there were no mechanical malfunctions or failures that would have precluded normal operations.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's improper landing flare, which resulted in a hard, bounced landing, and the nose landing gear collapse.

#### **Findings**

Aircraft Landing flare - Not attained/maintained

Personnel issues Aircraft control - Student/instructed pilot

## **Factual Information**

### History of Flight

Landing	Hard landing (Defining event)
Landing-landing roll	Runway excursion
Landing	Landing gear collapse

#### **Pilot Information**

Certificate:	Student	Age:	38,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	May 25, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	48 hours (Total, all aircraft), 48 hours (Total, this make and model), 36 hours (Last 90 days, all aircraft), 18 hours (Last 30 days, all aircraft)		

Page 2 of 5 CEN23LA421

### **Aircraft and Owner/Operator Information**

Cessna	Registration:	N391SP
172S NO SERIES	Aircraft Category:	Airplane
1999	Amateur Built:	
Normal	Serial Number:	172S8286
Tricycle	Seats:	4
August 24, 2023 100 hour	Certified Max Gross Wt.:	2550 lbs
	Engines:	1 Reciprocating
7726 Hrs at time of accident	Engine Manufacturer:	Lycoming
nstalled, not activated	Engine Model/Series:	IO-360-L2A
FLORIS FLIGHT SERVICES LLC	Rated Power:	180 Horsepower
FLORIS FLIGHT SERVICES LLC	Operating Certificate(s) Held:	None
1 1 1 7 II	72S NO SERIES 999  Iormal fricycle august 24, 2023 100 hour  726 Hrs at time of accident estalled, not activated LORIS FLIGHT SERVICES LLC	72S NO SERIES Aircraft Category: 999 Amateur Built: Serial Number: Fricycle Seats: Certified Max Gross Wt.: Engines: F726 Hrs at time of accident Installed, not activated Engine Manufacturer: Engine Model/Series: FLORIS FLIGHT SERVICES LLC Coperating Certificate(s)

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMDD,2803 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	07:35 Local	Direction from Accident Site:	192°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	170°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	24°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Midland, TX (KMDD)	Type of Flight Plan Filed:	None
Destination:	Midland, TX	Type of Clearance:	None
Departure Time:	07:30 Local	Type of Airspace:	Class G

Page 3 of 5 CEN23LA421

### **Airport Information**

Airport:	Midland Airpark MDD	Runway Surface Type:	Asphalt
Airport Elevation:	2805 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	3977 ft / 75 ft	VFR Approach/Landing:	Full stop

### Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	32.036389,-102.10138

Page 4 of 5 CEN23LA421

#### **Administrative Information**

Investigator In Charge (IIC):	Abraham, Laura
Additional Participating Persons:	Jason Wilson; FAA; Lubbock, TX
Original Publish Date:	February 1, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193143

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN23LA421