



# **Aviation Investigation Final Report**

Location: Inver Grove Heights, Minnesota Accident Number: CEN24LA109

Date & Time: February 4, 2024, 12:30 Local Registration: N360WC

Aircraft: Javron PA-12 Replica Aircraft Damage: Substantial

**Defining Event:** Landing gear not configured **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that he was landing the airplane on the water and that after he conducted his before landing "GUMP" checklist he extended the landing gear on his amphibious airplane in error. Following the water landing, the airplane came to rest inverted in the river and sustained substantial damage to both wings and the windscreen. The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to properly configure the landing gear on his amphibious airplane before landing on water.

#### **Findings**

Personnel issues Use of equip/system - Pilot

Aircraft Gear extension and retract sys - Incorrect use/operation

Personnel issues Incorrect action selection - Pilot

Page 2 of 5 CEN24LA109

### **Factual Information**

### History of Flight

Landing	Landing gear not configured (Defining event)	
Landing-landing roll	Dragged wing/rotor/float/other	
Landing-landing roll	Nose over/nose down	

#### **Pilot Information**

Certificate:	Airline transport; Flight instructor	Age:	64,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	November 3, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 4, 2022
Flight Time:	50000 hours (Total, all aircraft), 460 hours (Total, this make and model)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Javron	Registration:	N360WC
Model/Series:	PA-12 Replica	Aircraft Category:	Airplane
Year of Manufacture:	2023	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	JA1804118
Landing Gear Type:	Tailwheel; Amphibian	Seats:	3
Date/Type of Last Inspection:	October 12, 2023 Condition	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1
Airframe Total Time:	60 Hrs as of last inspection	Engine Manufacturer:	
ELT:	C126 installed, not activated	Engine Model/Series:	
Registered Owner:	On file	Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN24LA109

## Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
KSGS,821 ft msl	Distance from Accident Site:	2 Nautical Miles
12:35 Local	Direction from Accident Site:	230°
Clear	Visibility	10 miles
None	Visibility (RVR):	
4 knots /	Turbulence Type Forecast/Actual:	/
80°	Turbulence Severity Forecast/Actual:	/
30.14 inches Hg	Temperature/Dew Point:	7°C / -1°C
No Obscuration; No Precipitation		
Minneapolis, MN, MN (KLVN)	Type of Flight Plan Filed:	None
	Type of Clearance:	Traffic advisory
	Type of Airspace:	Class G
	KSGS,821 ft msl  12:35 Local  Clear  None  4 knots /  80°  30.14 inches Hg  No Obscuration; No Precipital Minneapolis, MN, MN	KSGS,821 ft msl Distance from Accident Site:  12:35 Local Direction from Accident Site:  Clear Visibility  None Visibility (RVR):  4 knots / Turbulence Type Forecast/Actual:  80° Turbulence Severity Forecast/Actual:  30.14 inches Hg Temperature/Dew Point:  No Obscuration; No Precipitation  Minneapolis, MN, MN (KLVN)  Type of Clearance:

### Wreckage and Impact Information

The state of the s			
Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	44.822353,-93.00766(est)

Page 4 of 5 CEN24LA109

#### **Administrative Information**

Investigator In Charge (IIC):	Miller, Bradley
Additional Participating Persons:	Greg Thurston; FAA; Minneapolis, MN
Original Publish Date:	April 12, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193752

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN24LA109