







# **Aviation Investigation Final Report**

Location: Moses Lake, Washington Accident Number: WPR23LA248

Date & Time: July 3, 2023, 08:30 Local Registration: CFXRB

Aircraft: Found FBA2C Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 4 None

Flight Conducted Under: Non-U.S., non-commercial

#### **Analysis**

The instructor of the tailwheel-equipped airplane reported a left crosswind during the landing approach. The pilot receiving instruction executed a 3-point landing and the tailwheel bounced twice. The instructor told the student to "pin the tail" by applying full aft elevator. The airplane deviated right of runway centerline and the pilot corrected with left rudder. The airplane crossed the centerline to the left and did not respond to full right rudder and heavy right braking. The airplane ground looped to the left sustaining substantial damage to the right wing and right horizontal stabilizer and elevator.

The pilot reported there were no preaccident mechanical malfunctions or failures that would have precluded normal operation.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing.

## Findings

Personnel issues	Aircraft control - Student/instructed pilot
Aircraft	Directional control - Not attained/maintained

Page 2 of 6 WPR23LA248

## **Factual Information**

## **History of Flight**

Landing-landing roll	Loss of control on ground (Defining event)	
----------------------	--	--

## Flight instructor Information

Certificate:	Commercial	Age:	59,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	5-point
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	January 6, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 8, 2023
Flight Time:	4850 hours (Total, all aircraft), 85 hours (Total, this make and model), 4500 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

#### **Pilot Information**

Certificate:	Airline transport	Age:	50,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	November 1, 2022
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	September 1, 2022
Flight Time:	(Estimated) 8100 hours (Total, all aircraft), 32 hours (Total, this make and model)		

Page 3 of 6 WPR23LA248

**Passenger Information** 

Certificate:		Age:	
Airplane Rating(s):		Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	4-point
Instrument Rating(s):		Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Passenger Information

Certificate:		Age:	
Airplane Rating(s):		Seat Occupied:	Rear
Other Aircraft Rating(s):		Restraint Used:	4-point
Instrument Rating(s):		Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

**Aircraft and Owner/Operator Information** 

Aircraft Make:	Found	Registration:	CFXRB
Model/Series:	FBA2C	Aircraft Category:	Airplane
Year of Manufacture:	2005	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	54
Landing Gear Type:	Tailwheel	Seats:	5
Date/Type of Last Inspection:	July 2, 2023 Annual	Certified Max Gross Wt.:	3500 lbs
Time Since Last Inspection:	1.5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	766 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C126 installed, not activated	Engine Model/Series:	IO-540-L1C5
Registered Owner:	AngelOne Canada	Rated Power:	300 Horsepower
Operator:	AngelOne Canada	Operating Certificate(s) Held:	None

Page 4 of 6 WPR23LA248

#### **Meteorological Information and Flight Plan**

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMWH,1169 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	07:52 Local	Direction from Accident Site:	170°
<b>Lowest Cloud Condition:</b>		Visibility	10 miles
Lowest Ceiling:	Overcast / 11000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	None /
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.03 inches Hg	Temperature/Dew Point:	20°C / 2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Vernon, BC, OF (CYVK)	Type of Flight Plan Filed:	VFR
Destination:	Moses Lake, WA (MWH)	Type of Clearance:	VFR
Departure Time:	07:00 Local	Type of Airspace:	Class D

## **Airport Information**

Airport:	Grant County MWH	Runway Surface Type:	Concrete
Airport Elevation:	1189 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	14L	IFR Approach:	None
Runway Length/Width:	13500 ft / 200 ft	VFR Approach/Landing:	Straight-in

## **Wreckage and Impact Information**

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	47.208583,-119.31913

Page 5 of 6 WPR23LA248

#### **Administrative Information**

Investigator In Charge (IIC): Blum, Contessa

Additional Participating Persons: Thomas Lang; GEG FSDO; Spokane, WA

Original Publish Date: November 2, 2023

Last Revision Date: Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=192518

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR23LA248