EWMA Chart
**for x**

Number of groups = 30

Center = 10

StdDev = 1.2

Smoothing parameter = 0.1

Control limits at 2.7*sigma

No. of points beyond limits = 0