



2024.1.31


1.修复A.VCC


2.删除多余的二极管


低级错误，此处应该引入A.VCC





TITLE: Sheet_1		REV: 1.0
嘉立创EDA	Company: Your Company	Sheet: 1/1
	Date: 2023-11-09 Drawn By: Denjhang	

















TITLE: Sheet_1		REV: 1.0
嘉立创EDA	Company: Your Company	Sheet: 1/1
	Date: 2023-11-09 Drawn By: Denjhang	



TITLE: Sheet_1		REV: 1.0
嘉立创EDA	Company: Your Company	Sheet: 1/1
	Date: 2023-11-09 Drawn By: Denjhang	



目前中声道声音偏小，可以左右电阻加到3k3





省略一级混音缓冲放大器


SSG在过下拉电阻之前，禁止接电容

此处参考RC2014-YM2149的黄金比例立体声混音

TITLE: Sheet_1		REV: 1.0
嘉立创EDA	Company: Your Company	Sheet: 1/1
	Date: 2023-11-20 Drawn By: Denjhang	







TITLE: Sheet_1		REV: 1.0
嘉立创EDA	Company: Your Company	Sheet: 1/1
	Date: 2025-04-28 Drawn By: Denjhang	