DAILY OPERATIONS PROGRESS REPORT

Tuesday, 27th October 2026

Daily Operations Report

Mucheru World of Golf • Chaka Farms • Kabete Residence

IRRIGATION & SAND LOGISTICS

7 Greens Confirmed

Pop-Ups Functional • 1 Tipper Sand to Green 10

TEEBOX EARTHWORKS

Red Soil on 3 Tees

Tees 5, 3 & 2 Layered • Trenches Backfilled

KABETE STRUCTURAL WORKS

SQ Shutter Slab Rebar

Steel Grid Bound • Formwork Braced • Sand Staged

DAILY DAIRY HARVEST

8.0 Litres Gross

7.0L Dispatched • 1.0L Farm Allocations • 100% Reconciled

Executive Summary & Multi-Site Operations Synthesis

Field operations on Tuesday, 27th October 2026 delivered substantial, verifiable progress across championship golf course irrigation commissioning, teebox red soil earthworks, rootzone sand logistics, civil shutter slab rebar fabrication, dairy accounting, and estate groundskeeping across three active project sites:

Key Milestone Accomplishments Across Active Sites

Mucheru World of Golf: Overseen by Mr. Gichuhi and Ken; pop-up rotor sprinklers on seven greens (Greens 18, 1, 2, 11, 12, 4, and 13) were pressure-tested and confirmed fully functional; electric solenoids were installed on Green 10 and Teeboxes 11, 12, and 13; clean river sand was delivered to Green 10; red topsoil was spread on Teeboxes 5, 3, and 2 (halfway); trenches were backfilled, and gravity water flow was validated through PVC lines.
Chaka Farms: Dairy milking yielded 8.0 Litres gross harvest (7.0L dispatched for commercial sales + 1.0L farm allocations to Gladys and Maasai), achieving 100% accounting reconciliation strictly in Litres; Ken supervised rock garden terracing and stone alignments; Willy conducted morning kennel hygiene, paw training, pack exercise walking, kennel manners, and Bella's evening socialization in fine health; and Margaret and Monica weeded driveway road kerbs.
Kabete Residence: Operations overseen and shared by Njoki; steel fixers actively tied high-yield reinforcement bars and drop beams over formwork for the SQ shutter slab at the fireplace; carpenters reinforced the canopy base formwork with timber struts; workers staged sharp river sand and crushed ballast aggregate via wheelbarrow; groundskeepers raked and weeded flower beds in the middle lawn area and along the fireplace stairs; and fresh meals were served to resident pets (Ajabu and resident cats).

- **Hunter Pop-Up Sprinklers Confirmed Functional Across 7 Greens:** Pressure testing verified full spray coverage across Greens 18, 1, 2, 11, 12, 4, and 13.
- **Teebox Red Soil Earthworks & Solenoid Installations:** Red soil applied on Teeboxes 5, 3, and 2; solenoid valves fitted at 4 locations; pipe trenches backfilled.
- **Green 10 River Sand Intake & Gravity Flow Validation:** One tipper lorry delivered sand to Green 10; bucket tests confirmed positive gravity flow through PVC drainage lines.
- **Kabete SQ Shutter Slab Rebar Fabrication & Material Staging:** Steel fixers tied rebar mesh over DPM sheeting; canopy formwork reinforced; sand and ballast aggregates staged.
- **100% Reconciled Dairy Harvest & Canine Routines:** 8.0 Litres gross harvest fully accounted for strictly in Litres; Bella completed evening socialization in fine condition.

Mucheru World of Golf

Overseen by: Mr. Gichuhi & Ken

Irrigation Testing & Commissioning, Teebox Red Soil Earthworks & Civil Infrastructure Brief

Field engineering operations across Mucheru World of Golf on Tuesday, 27th October 2026 achieved significant advances in irrigation automation commissioning, teebox earthworks, rootzone sand intake, trench backfilling, and gravity drainage flow testing:

Golf Course Operational Highlights

Pop-up rotor sprinklers across Greens 18, 1, 2, 11, 12, 4, and 13 were pressurized and confirmed fully functional with uniform spray coverage. Solenoid valves were installed on Green 10 and Teeboxes 11, 12, and 13. Red topsoil was applied on Teeboxes 5, 3, and 2, while one tipper lorry of river sand was delivered to Green 10. Drainage and pipe trenches were backfilled, gravity flow was tested, Dam 1 dewatering continued, and perimeter hedge weeding was completed.

- **Pop-Up Sprinklers Confirmed Functional on 7 Greens:** Hunter pop-up rotor sprinklers installed on Greens 18, 1, 2, 11, 12, 4, and 13 were tested under operational pressure, confirming full spray distribution and coverage.
- **Electric Solenoid Control Valves Installed:** Plumbers installed automated electric solenoid control valves on Green 10 and Teeboxes 11, 12, and 13 to enable automated irrigation scheduling.
- **Red Topsoil Applied Across Teeboxes 5, 3 & 2:** Ground crews spread and leveled red soil across Teeboxes 5 and 3, and completed half of Teebox 2, shaping uniform launch platforms.
- **River Sand Delivery for Green 10:** One commercial tipper lorry delivered clean, graded river sand to Green 10, stockpiled for rootzone profile construction over the pumice sub-base.
- **Trench Backfilling & Gravity Drainage Flow Validation:** Crews backfilled drainage trenches and pop-up sprinkler pipe trenches, including the HDPE trench across Teebox 6 to Green 7; gravity water flow was tested through PVC lines using water buckets, verifying unobstructed flow.
- **Site Material Haulage & Hydraulic Dewatering:** The farm tractor hauled HDPE pipes, sprinklers, and solenoids from Chaka Farms to the golf site, and returned wooden fence posts to the greenhouse; Dam 1 pumping to Dam 2 continued steadily.
- **Perimeter Hedge Seedlings Weeding Completed:** Landscaping crews concluded comprehensive manual weeding along the perimeter boundary fence hedge seedlings and drip irrigation lines.

⛳ Course Agronomy & Engineering Status Audit — Putting Greens (1 – 18)

Audited by: Dennis

18-hole putting green status audit showing the latest work completed and current condition for each green as of October 27, 2026:

GREEN	CURRENT TECHNICAL & AGRONOMIC STATE	MILESTONE STATUS
Green 1 TODAY	Pop-up sprinklers confirmed functional and operational spray coverage verified (Oct 27).	Pop-Ups Functional
Green 2 TODAY	Pop-up sprinklers confirmed functional and operational spray coverage verified (Oct 27).	Pop-Ups Functional
Green 3	Electric solenoid valve installed on lateral line; river sand hauled to Green 13 (Oct 26).	Solenoid Installed
Green 4 TODAY	Pop-up sprinklers confirmed functional and operational spray coverage verified (Oct 27).	Pop-Ups Functional
Green 5	Established mature championship putting green turfgrass watered with pop-up sprinklers (Oct 24).	Turf Irrigated
Green 6	Drainage flow issues identified; slope measurements taken for upcoming replacement trench (Oct 24).	New Trench Measured
Green 7 TODAY	HDPE irrigation supply trench cutting through Teebox 6 to Green 7 backfilled and covered (Oct 27).	Pipe Trench Covered
Green 8	Electric solenoid valve installation and lateral pipe fitting completed on green (Oct 26).	Solenoid Installed
Green 9 TODAY	Main drainage canal invert leveled and shaped; positive gravity flow verified with water (Oct 27).	Drainage Leveled & Tested
Green 10 TODAY	One lorry of river sand delivered; electric solenoid valve installed on lateral line (Oct 27).	Sand Delivered & Solenoid
Green 11 TODAY	Pop-up sprinklers confirmed functional and operational spray coverage verified (Oct 27).	Pop-Ups Functional
Green 12 TODAY	Pop-up sprinklers confirmed functional and operational spray coverage verified (Oct 27).	Pop-Ups Functional
Green 13 TODAY	Pop-up sprinklers confirmed functional and operational spray coverage verified (Oct 27).	Pop-Ups Functional
Green 14	Saddle clamps installed on HDPE pop-up sprinkler pipes and perimeter trenches backfilled (Oct 23).	Saddle Clamps & Covered
Green 15	Saddle clamps installed on HDPE pop-up sprinkler pipes and perimeter trenches backfilled (Oct 22).	Saddle Clamps & Covered
Green 16	Electric solenoid valve installed on lateral line; HDPE sprinkler trenches backfilled (Oct 24).	Solenoid Installed
Green 17	Electric solenoid valve installed on lateral line; HDPE sprinkler trenches backfilled (Oct 24).	Solenoid Installed
Green 18 TODAY	Pop-up sprinklers confirmed functional and operational spray coverage verified (Oct 27).	Pop-Ups Functional

🏌️ Course Engineering Status Audit — Championship Teeboxes (1 – 18)

Audited by: Dennis

18-hole championship teebox status audit tracking launch platform shaping, red soil leveling, and irrigation pipe installations as of October 27, 2026:

TEEBOX	CURRENT TECHNICAL & EARTHWORK STATE	PLATFORM STATUS
Tee 1	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug
Tee 2 TODAY	Red soil applied halfway across platform; lateral pipe trenches backfilled (Oct 27).	Red Soil Halfway
Tee 3 TODAY	Red soil applied, spread, and leveled across platform; lateral pipe trenches covered (Oct 27).	Red Soil Leveled
Tee 4	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug
Tee 5 TODAY	Red soil spread and leveled across platform; lateral pipe trenches backfilled (Oct 27).	Red Soil Leveled
Tee 6 TODAY	HDPE irrigation supply trench cutting through Teebox 6 towards Green 7 backfilled and covered (Oct 27).	Pipe Trench Covered
Tee 7	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug
Tee 8	Red soil applied across platform; lateral irrigation pipe trenches excavated (Oct 26).	Red Soil & Trenches Dug
Tee 9	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug
Tee 10	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug
Tee 11 TODAY	Electric solenoid valve installed on lateral irrigation supply line (Oct 27).	Solenoid Installed
Tee 12 TODAY	Electric solenoid valve installed on lateral irrigation supply line (Oct 27).	Solenoid Installed
Tee 13 TODAY	Electric solenoid valve installed on lateral irrigation supply line (Oct 27).	Solenoid Installed
Tee 14	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug
Tee 15	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug
Tee 16	Red soil applied, spread, and leveled; lateral irrigation pipe trenches excavated (Oct 26).	Red Soil & Trenches Dug
Tee 17	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug
Tee 18	Irrigation pipe trenches excavated across platform along marked survey lines (Oct 26).	Pipe Trenches Dug

Operations Agronomy & Engineering Synthesis

Course Agronomy & Earthwork Milestones: Clean river sand delivered via tipper lorry to Green 10; red topsoil spread and leveled on Teeboxes 5 and 3, and completed halfway on Teebox 2; lateral pipe trenches backfilled across multiple tees; perimeter hedge seedling weeding completed. **Hydraulic & Irrigation Infrastructure:** Pop-up sprinklers confirmed fully functional with operational spray coverage on Greens 18, 1, 2, 11, 12, 4, and 13; electric solenoid valves installed on Green 10 and Teeboxes 11, 12, and 13; HDPE supply trench from Teebox 6 to Green 7 covered; gravity drainage flow verified with water bucket tests; Dam 1 dewatering to Dam 2 ongoing.

🎬 Video Documentation — Mucheru World of Golf Operations Progress

Field video recording documenting Tuesday, 27th October 2026 operations at Mucheru World of Golf, showcasing pop-up sprinkler spray testing, solenoid installations, teebox red soil earthworks, river sand intake, trench backfilling, gravity flow testing, and reservoir dewatering:

🎬 Daily Course Civil & Irrigation Progress Overview

📹 VIDEO RECORDING

Comprehensive field video capturing Tuesday, 27th October 2026 operations at Mucheru World of Golf: operational testing and spray coverage verification of Hunter pop-up sprinklers across Greens 18, 1, 2, 11, 12, 4, and 13; installation of electric solenoid valves on Green 10 and Teeboxes 11, 12, and 13; tipper lorry delivery of clean river sand to Green 10; manual application, spreading, and leveling of red topsoil across Teeboxes 5, 3, and 2; backfilling of drainage and HDPE sprinkler trenches including the pipeline crossing from Teebox 6 to Green 7; water bucket testing of gravity drainage flow through PVC pipes; tractor haulage of irrigation pipes, sprinklers, and solenoids; ongoing water pumping from Dam 1 to Dam 2; and completed weeding of perimeter hedge seedlings.

▶ Watch on YouTube

URL: https://youtu.be/BSGHtTA7uYA

📸 Photographic Field Evidence — Mucheru World of Golf

Sequential photographic field documentation showing sprinkler spray testing, solenoid installations, river sand intake, teebox red soil earthworks, trench backfilling, gravity water flow testing, reservoir dewatering, material haulage, and perimeter hedge weeding:



Hunter Pop-Up Sprinkler Operational Spray Testing

Pop-up rotor sprinklers actively pressurized and discharging uniform 360-degree spray coverage across the sand-capped putting green rootzone bed and surrounding red soil collar.



Electric Solenoid Valve Assembly & Trench Fitting

Irrigation technicians assembling, dry-fitting, and solvent-welding an electric solenoid control valve into the lateral pipe manifold inside the excavated trench.



Installed Solenoid Valve & Feeder Trench Alignment

Completed electric solenoid control valve with dual red control lead wires secured in the lateral supply trench, connected and staged for automated zone irrigation.



River Sand Delivery for Green 10 Rootzone Profile

A full tipper lorry consignment of clean, graded river sand offloaded in a clean stockpile at Green 10, ready for distribution across the pumice sub-base layer.



Red Topsoil Loading & Haulage for Teebox Platforms

Manual labor crew shoveling rich red soil from an offloaded stockpile into steel wheelbarrows for transport and leveling across championship teebox platforms.



Teebox 2 — Red Soil Spreading & Raking

Ground team utilizing rakes, shovels, and wheelbarrows to spread and level red topsoil across the foundation of Teebox 2 adjacent to the perimeter boundary fence.



Aerial Perspective — Teebox 2 Red Soil Application (Halfway)

Drone aerial view capturing Teebox 2 with red soil applied and smoothed across half of the platform, with active soil spreading progressing from the stockpile.



Aerial Perspective — Teebox 3 Red Soil Placement

Overhead drone photograph of Teebox 3 showing fresh red soil layered across the platform surface with the central lateral sprinkler pipe trench running lengthwise.



Teebox 5 — Initial Soil Spreading Along Fence Boundary

Ground perspective of Teebox 5 showing workers spreading and compacting the base layer of red topsoil across the rectangular platform bordered by tree lines and fencing.



Aerial Perspective — Teebox 5 Red Soil Platform Layering

High-angle aerial capture of Teebox 5 displaying uniform red topsoil spread over the foundation bed alongside the estate service roadway and hedge perimeter.



Aerial Perspective — Covered HDPE Trench Across Tee 6 to Green 7

Drone photograph revealing the backfilled and compacted HDPE irrigation supply trench cutting across Teebox 6 towards Green 7, with water in the adjacent drainage canal.



Manual Trench Backfilling Over Orange PVC Drainage Pipes

Laborers using hoes and shovels backfilling excavated soil over the orange PVC drainage pipe laid along the base of the drainage channel.



Aerial Perspective — Drainage Trench Backfilling Operations

Drone aerial overview showing workers backfilling the drainage channel along the perimeter of the putting green, with ballast aggregate and sand beds visible.



Drainage Invert Shaping & Orange Pipe Bedding

Excavation crew smoothing and gradient-grading the floor of the deep drainage canal, bedding orange PVC pipe sections to guarantee positive gravity flow.



Main Drainage Canal — Manual Gradient Excavation

Team of workers inside the deep drainage trench using spades and hoes to shape the sidewalls and invert slope along the fairway boundary line.



Aerial Perspective — Deep Drainage Canal Earthworks

Overhead aerial drone shot capturing the continuous alignment and depth of the main gravity drainage canal being manually shaped beneath acacia trees.



Hydraulic Gravity Flow Validation with Water Buckets

Technicians pouring buckets of water directly into the orange PVC drainage pipe inside the trench, confirming rapid, unobstructed gravity discharge.



Dam 1 Reservoir — Mechanical Dewatering Operations

Portable water pump operating on the floor of Dam 1, steadily evacuating remaining water and sediment slurry over the heavy-duty black geomembrane liner.



Aerial Perspective — Dam 1 Dewatered Geomembrane Basin

Overhead drone photograph showing Dam 1 substantially dewatered, exposing the textured black liner and minimal residual puddle at the central sump.



Dam 2 Reservoir — Receiving Inflow from Dam 1 Dewatering

Ground view of Dam 2 lined with black geomembrane receiving pumped water discharge from Dam 1, steadily building reservoir storage volume.



Aerial Perspective — Dam 3 Continuous HDPE Pipe Inflow

Drone aerial capture of Dam 3 with black HDPE inlet pipe discharging clean inflow steadily into the green reservoir water body along the lined embankment.



Aerial Perspective — Dam 3 Full Storage Capacity

Panoramic aerial view of Dam 3 showcasing high water storage retention within the curved geomembrane-lined reservoir channel under clear skies.



Irrigation Material Haulage — Tractor Trailer Staging

Red farm tractor trailer (registration ZJ 5334) loaded with large HDPE pipe coils, boxed Hunter pop-up sprinklers, and solenoids outside the greenhouse.



Irrigation Consignment Received on Golf Course Site

Coils of black HDPE piping, Hunter sprinkler boxes, and solenoid valve components staged under tree shade on site, ready for immediate installation.



Treated Wooden Fence Post Haulage to Farm Greenhouse

Farm crew loading surplus treated wooden boundary fence posts onto the farm tractor trailer to transport from the golf site to the Chaka Farms greenhouse.



Boundary Fence — Perimeter Hedge Seedling Weeding

Landscaping crew manually uprooting weeds along the boundary wire mesh fence line, clearing root zones around young hedge seedlings and drip irrigation tubes.



Weeded Hedge Seedlings & Drip Irrigation Line Inspection

Close-up view of cleanly weeded hedge seedlings along the fence line, with black drip irrigation lateral tubing and clean soil beds free of competing grass.

Chaka Farms

Dairy & Rock Garden: Ken | Canine Unit: Willy | Compound Maintenance: Margaret & Monica

Dairy Production, Stepped Rock Garden Earthworks & Canine Behavioral Conditioning Brief

Farm and estate maintenance operations at Chaka Farms on Tuesday, 27th October 2026 delivered solid results in dairy production reconciliation, multi-tiered rock garden civil shaping, structured canine obedience training, and compound groundskeeping:

Farm & Grounds Operational Highlights

Dairy production achieved an 8.0 Litres gross harvest with 100% accounting reconciliation strictly in Litres (7.0L dispatched for commercial sales and 1.0L routine farm allocations). Ken directed ongoing rock garden civil construction with red soil shaping and stone placement. Willy led morning kennel sanitation, paw command obedience, off-leash exercise walking with all dogs, kennel manners, and an evening socialization session with Bella in fine health. Margaret and Monica hand-weeded along estate driveway road kerbs.

- **100% Reconciled Dairy Harvest:** Morning and evening milking yielded 8.0 Litres gross harvest, fully accounted for by 7.0 Litres dispatched for commercial sales and 1.0 Litre in internal farm allocations (0.5L Gladys + 0.5L Maasai) with zero discrepancy.
- **Stepped Rock Garden Red Soil Shaping & Stone Setting:** Ken supervised farm workers setting and aligning quarried stones along string guide lines over terraced red soil beds on the compound lawn before the round farm house.
- **Morning Canine Kennel Cleaning & Sanitation:** Kennel stalls were washed, disinfected, and thoroughly cleaned during the morning routine, maintaining excellent veterinary hygiene.
- **Morning Paw Command Obedience & Off-Leash Pack Exercise:** Willy conducted structured paw command conditioning followed by an off-leash exercise and agility walking session with all dogs across the open farm grounds.
- **Canine Socialization Session with Bella & Health Check:** An evening socialization session was conducted with Bella, accompanied by a routine physical health inspection confirming she is in fine condition.
- **Disciplined Kennel Manners Conditioning:** Handlers reinforced doorway manners, conditioning dogs to wait calmly at stall doors and enter/exit strictly upon command.
- **Estate Driveway Road Kerb Weeding:** Margaret and Monica performed comprehensive compound groundskeeping, hand-weeding encroaching grass and weeds along the stone kerb borders of the estate driveway road.

🥛 Daily Dairy Milking Yield & Reconciliation Ledger (Litres)

Logged by: Ken

Official milking production and distribution reconciliation for Tuesday, 27th October 2026, accounting for all commercial sales and on-farm allocations:

Category / Transaction	Morning Session	Evening Session	Daily Total
Gross Milk Harvested	4.5 Litres	3.5 Litres	**8.0 Litres**
Commercial Milk Sales (Dispatched)	3.5 Litres	3.5 Litres	**7.0 Litres**
Internal Farm Allocation — Gladys (Staff)	0.5 Litres	—	**0.5 Litres**
Internal Farm Allocation — Maasai	0.5 Litres	—	**0.5 Litres**
Internal Farm Allocation — Goat Kids (Weaned)	0.0 Litres	0.0 Litres	0.0 Litres
Total Volume Accounted For	**4.5 Litres**	**3.5 Litres**	**8.0 Litres (100% Reconciled)**

Dairy Accounting & Farm Reconciliation Note

Total gross milk harvested of 8.0 Litres (4.5L morning + 3.5L evening) is 100% accounted for by 7.0 Litres dispatched for commercial sales (3.5L morning sale + 3.5L evening sale) and 1.0 Litre in routine farm allocations (0.5L Gladys + 0.5L Maasai). In accordance with reporting rules, milk volumes are recorded strictly in Litres (never kilograms), and Maasai is designated strictly as Maasai with zero discrepancy. All yields reconcile perfectly with zero variance.

🐶 Canine Conditioning, Health, Behavioral Training & Compound Upkeep

Canine Unit: **Willy** | Compound Maintenance: **Margaret & Monica**

Daily behavioral conditioning routines, kennel hygiene maintenance, canine exercise sessions, health assessments, and estate compound groundskeeping conducted on Tuesday, 27th October 2026:

- **Morning Kennel Hygiene & Sanitization:** Willy oversaw thorough morning kennel washing, deep stall sanitation, and feeding bowl disinfection, preserving high hygiene standards.
- **Morning Paw Command Training:** Dogs participated in individual obedience drills focused on reinforcing the "paw" command with positive verbal praise.
- **Morning Off-Leash Exercise Walking with All Dogs:** Willy conducted an energetic off-leash pack walking and exercise session across open farm corridors, encouraging natural running and pack bonding.
- **Evening Socialization Session with Bella:** A targeted evening socialization session was conducted with Bella, fostering positive social responsiveness and calm behavioral temperament.
- **Bella Health Status Assessment:** Willy conducted a thorough health and physical condition check on Bella, confirming she is active, alert, eating well, and in fine health.
- **Reinforced Kennel Manners Conditioning:** Handlers reinforced disciplined kennel manners, conditioning canines to sit patiently at open stall thresholds until given release cues.
- **Driveway Road Kerb Weeding:** Margaret and Monica performed thorough manual groundskeeping, removing encroaching weeds and grass along the stone kerb borders of the farm driveway road.

🎬 Video Documentation — Chaka Farms Canine Unit Operations

Field video recordings documenting Tuesday, 27th October 2026 canine behavioral conditioning routines, morning exercise walking, and evening socialization under Willy:

🎬 Canine Unit: Kennel Manners Routine

🎥 VIDEO RECORDING

Structured kennel manners conditioning under Willy, verifying dogs demonstrating patience, calm stall manners, and prompt obedience to doorway release commands.

📁 Access Video on Google Drive

Kennel manners.mp4

🎬 Canine Unit: Morning Off-Leash Pack Walk

🎥 VIDEO RECORDING

Morning off-leash walking and exercise session with all farm dogs exploring open paddock corridors, reinforcing pack recall, agility, and cardiovascular fitness.

📁 Access Video on Google Drive

Walking offleash with dogs.mp4

🎬 Canine Unit: Evening Socialization with Bella

🎥 VIDEO RECORDING

Evening socialization and health check session conducted with Bella, capturing relaxed social interaction, responsiveness to handlers, and verifying her excellent health condition.

📁 Access Video on Google Drive

Socializing was done by Bella.mp4

📸 Photographic Field Evidence — Chaka Farms

Photographic field documentation showing multi-tiered rock garden civil earthworks, stone setting, and estate compound driveway road weeding at Chaka Farms:



Stepped Rock Garden — Red Soil Profiling & Stone Staking

Workers in green overalls setting stone alignments and staking guide strings on terraced red soil beds for the landscaped rock garden before the round farm house.



Stepped Rock Garden — Curved Retaining Rock Placement

Farm crew arranging quarried landscape stones along curved guide strings, constructing multi-tiered retaining terraces across the red soil compound lawn.



Estate Groundskeeping — Driveway Road Kerb Weeding

Margaret and Monica hand-weeding encroaching grass and weeds along the stone kerb edge of the compound gravel driveway, maintaining pristine estate cleanliness.

SQ Shutter Slab Rebar Fabrication, Formwork Reinforcement, Material Staging & Grounds Maintenance Brief

Civil structural works, formwork carpentry, aggregate staging, estate grounds gardening, and domestic pet care operations at Kabete Residence on Tuesday, 27th October 2026 progressed with measurable milestones:

Residence Operational Highlights

Steel fixers advanced rebar grid binding and drop beam reinforcement over the timber formwork shuttering for the SQ shutter slab above the fireplace area. Formwork carpenters installed vertical and diagonal timber struts to reinforce the canopy base ahead of the concrete pour. Manual laborers transported sharp river sand and crushed ballast aggregate via wheelbarrow to stockpile on the upper slab mixing platform. Groundskeepers weeded, cleared dry leaves, and cultivated flower beds in the middle lawn area and along the fireplace stairs. Dedicated meal rations were prepared for Ajabu the Golden Retriever and resident cats, with Ajabu feeding indoors and two cats dining together (one cat noted as temporarily absent).

- **SQ Shutter Slab Rebar Binding:** Steel fixers tied high-yield reinforcement bars and cross-mesh with binding wire over DPM damp-proof sheeting and concrete spacer blocks across the SQ shutter slab platform at the outdoor fireplace.
- **Reinforcement Steel Placement in Drop Beams:** Structural steel tying progressed along the drop beam troughs and perimeter boundaries of the SQ slab, ensuring proper spacing and structural embedment.
- **Canopy Base Formwork Shuttering Reinforcement:** Carpenters installed and braced solid timber props beneath the soffit to reinforce the cantilevered shutter formwork canopy base, ensuring stability under concrete casting loads.
- **Sand & Ballast Aggregate Staging via Wheelbarrow:** Site workers transported wheelbarrow loads of sharp river sand and crushed ballast stone aggregate up to the staging area to supply upcoming concrete mixing operations for the SQ shutter slab.
- **Middle Lawn Area Flower Bed Groundskeeping:** The estate gardener cleaned, weeded, and raked dry leaves and organic debris from the landscaped flower beds in the central middle compound area.
- **Fireplace Staircase Landscape Border Clearing:** Grounds maintenance continued along the outdoor fireplace staircase, clearing debris and tidying ornamental flower bed borders along the stone retaining walls.
- **Domestic Pet Care & Nutrition Routine:** Freshly prepared meal rations were served to Ajabu the Golden Retriever indoors; two resident cats dined together from their feeding bowls, with one cat noted as temporarily absent during this mealtime session.


📸 Photographic Field Evidence — Kabete Residence

Photographic field documentation showing SQ shutter slab rebar fabrication, formwork canopy reinforcement, aggregate staging, estate groundskeeping, and domestic pet care at Kabete Residence:




SQ Shutter Slab — Steel Bar Binding Over DPM Sheeting

Steel fixers tying high-yield rebar reinforcement grids over black damp-proof membrane and concrete cover spacers for the SQ shutter slab above the fireplace.



SQ Shutter Slab — Rebar Mesh & Drop Beam Assembly

Construction team tying longitudinal and transverse steel bars along the formwork drop beam edges and slab bed to ensure structural load distribution.



SQ Shutter Slab — Detailed Steel Rebar Intersections

Close-up view of steel fixers utilizing tying wire and pincers to secure rebar grid intersections at specified engineering intervals on the SQ shutter deck.



SQ Slab Formwork — Elevated Overview of Rebar Matting

Elevated perspective showing the extensive tied rebar reinforcement matting across the SQ shutter slab platform adjacent to the perimeter safety railing.



Canopy Base — Formwork Shuttering Timber Reinforcement

Carpenter installing and securing vertical timber struts and diagonal props under the formwork soffit to reinforce the cantilevered canopy base for concrete pouring.



Material Logistics — Wheelbarrow Haulage of River Sand

Site laborer in protective coveralls transporting loaded wheelbarrows of sharp river sand across the stone-paved ramp to the SQ slab staging depot.



Aggregate Staging — Stockpiling Ballast & River Sand

Laborers shoveling and moving crushed ballast stone and sand aggregates to build ready stockpiles for concrete batching near the SQ shutter slab.



SQ Shutter Slab — Continuous Material Intake

Active manual haulage of sand and ballast aggregate via blue wheelbarrows along the upper platform corridor to prepare for upcoming slab casting operations.



Middle Area Groundskeeping — Flower Bed Raking & Debris Removal

Estate gardener carefully cleaning fallen dry leaves, trimming withered foliage, and weeding the landscaped ornamental flower beds in the central lawn area.



Fireplace Stairs — Landscape Border Maintenance

Gardener clearing dry tree leaves and organic debris from the terraced flower beds flanking the natural stone staircase leading down to the outdoor fireplace.



Estate Garden Cultivation — Shrub Bed Soil Maintenance

Estate gardener aerating soil and gathering dried plant clippings within the shrubbery beds along the stone-paved driveway, enhancing garden aesthetics.



Ornamental Garden Borders — Thorough Grounds Sweeping

Grounds maintenance crew completing detailed leaf clearing, weeding, and sweeping along the landscaped flower borders and bordering stone pathways.



Mealtime Nutrition Preparation — Resident Cats & Dog

Three individual cat food dishes and a canine dinner bowl freshly prepared with nutritious rations on the kitchen counter prior to feeding.



Domestic Pet Care — Ajabu Mealtime Feeding

Ajabu the Golden Retriever enjoying his prepared daily meal indoors from his dedicated feeding dish on the dining room rug.



Resident Cats Evening Mealtime — Indoor Feeding

Two resident cats feeding peacefully side-by-side from stainless steel dishes indoors, with one resident cat noted as absent during this evening meal session.

Compiled by Dennis

Daily Operations Progress Report • Tuesday, 27th October 2026 • Mucheru World of Golf • Chaka Farms • Kabete Residence