

# Daily Operations Progress Report

Mucheru World of Golf palm tree hole excavations (60 holes completed to date), Greens 10 & 15 marking, drainage trench alignments & main gate murram leveling; Chaka Farms dairy yield (7.5L), livestock rations, canine care, palm watering & vehicle maintenance.

|                                                                                                 |                                                                                                        |                                                                                                                           |                                                                                                           |
|-------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|
| <div>HEAVY MACHINERY<br/>RUN TIME</div> <div>KES 48,750</div> <div>7.5 hrs Backhoe Loader</div> | <div>DAILY DAIRY MILK<br/>YIELD</div> <div>7.5 Litres</div> <div>Morning: 4.5 L   Evening: 3.0 L</div> | <div>KEY<br/>ACCOMPLISHMENTS</div> <div>60 Palm Holes</div> <div>Tee 7 to Main Gate •<br/>Greens 10 &amp; 15 Marked</div> | <div>ACTIVE SITES<br/>TRACKED</div> <div>2 Sites</div> <div>Mucheru World of Golf •<br/>Chaka Farms</div> |
|-------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|




## Mucheru World of Golf

Overseen by: **Mr. Gichuhi & Ken**

### Boundary Palm Tree Excavations, Green Survey Layouts & Gate Entrance Leveling

- Perimeter Palm Tree Planting Holes (Milestone: 60 Total Holes):** Heavy excavation of ornamental palm tree planting holes along the property perimeter corridor progressed at high efficiency. A cumulative milestone of **60 holes completed to date** was reached, spanning the full corridor distance from the corner of **Tee Box No. 7** directly to the **Main Entrance Gate**.
- Greens Survey Marking (Green No. 10 & Green No. 15):** Topographical and contour perimeter marking executed across **Green No. 10** and **Green No. 15**, establishing precision boundary outlines for subsequent foundation earthworks and sub-base profiling.
- Drainage Trench Alignment & Marking to Dams:** Strategic on-site layout and marking of main sub-surface drainage trenches leading from the putting greens towards the course retention dams, conducted in coordination with course consultant **Joe**, site supervisors, and ground crew.
- Main Gate Entrance Murram Spreading & Ground Leveling:** Spreading, grading, and surface leveling of high-grade murram across the main gate entrance threshold, creating a smooth, stable, and durable approach for vehicular access.
- Executive Site Walkthrough & Alignment Review:** Comprehensive on-site inspection conducted with **Madam Carol** and site supervisor **Mr. Gichuhi** along the boundary alignment, reviewing tree planting pit specifications, drainage corridors, and course shaping milestones.

| EQUIPMENT / RESOURCE                       | OPERATING DURATION         | UNIT RATE (KES) | TOTAL COST (KES)     | OPERATIONAL SCOPE                                                                   |
|--------------------------------------------|----------------------------|-----------------|----------------------|-------------------------------------------------------------------------------------|
| Backhoe Loader<br>(Front Loader / Backhoe) | 7 hrs 30 mins<br>(7.5 hrs) | 6,500 / hr      | 48,750.00            | Palm tree hole excavation along boundary line, murrum spreading & entrance leveling |
| <b>TOTAL DIRECT EQUIPMENT EXPENDITURE:</b> |                            |                 | <b>KES 48,750.00</b> |                                                                                     |



### Milestone Accomplished — 60 Palm Tree Holes Dug & Greens 10 & 15 Marked

The boundary tree planting corridor from Tee Box 7 corner to the Main Gate is now fully excavated with 60 uniform planting pits ready for tree planting. Survey boundaries for Greens 10 and 15 and green-to-dam drainage channels are clearly established.



## Operations Video Record — Mucheru World of Golf



### VIDEO RECORDING



#### Boundary Palm Tree Hole Excavation Operations

Backhoe Loader rear digging arm in continuous operation excavating uniform palm tree planting pits along the fence corridor between Tee Box 7 and the main gate.


[View Video on Google Drive ↗](#)



## Photographic Evidence — Mucheru World of Golf



### Executive Site Walkthrough & Alignment Review

Madam Carol and site supervisor Mr. Gichuhi conducting an on-site review under the shade trees, evaluating the perimeter palm tree corridor and course progress.



### Drainage Layout Review with Course Consultant Joe

Course consultant Joe and the site team inspecting the hardcore foundation base and marking drainage discharge paths connecting the green to the dams.



### Green-to-Dam Drainage Trench Alignment

Ground crew surveying and marking runoff slope paths from the green foundation lip towards the course catchment retention basins.



### Perimeter Palm Tree Planting Pit Alignment

Deep square planting pit excavated along the gabion wire boundary fence corridor, with the backhoe loader continuing hole excavations down the alignment.



### 60 Palm Tree Holes Milestone Along Boundary Corridor

Corridor view along the treated timber post fence line showing the sequence of 60 excavated tree holes extending from Tee Box 7 corner to the main gate.



### Backhoe Loader Excavating Planting Pits

XGMA 765N Backhoe Loader with stabilizer legs deployed, utilizing its rear excavator arm to sink deep planting pits into the soil.



### Excavator Arm Operating in Tree Corridor

Frontal perspective of the backhoe bucket penetrating the ground along the fairway boundary strip to prepare ornamental palm planting holes.



### Continuous Heavy Plant Earthmoving Operations

Backhoe Loader stationed on the graded fairway roadway, coordinating front bucket leveling and rear bucket planting hole excavation.



**Main Entrance Gate Murram Spreading & Leveling**

Fresh high-grade murram spread and leveled evenly across the double-leaf steel entrance gate threshold to create a smooth vehicle entryway.



**Chaka Farms**

Overseen by: **Kamandau & Mwangi**

 **Dairy Production & Livestock Care**

- **Daily Dairy Milking Yield (7.5 Litres Total):** Daily milking operations recorded **7.5 Litres** of fresh milk across morning (**4.5 L**) and evening (**3.0 L**) sessions under Kamandau's supervision.
- **Goat Kids Nutritional Milk Ration:** Goat kids received their dedicated daily ration of **1.0 Litre** (0.5 L morning session and 0.5 L evening session).
- **Maasai Allocation:** Dedicated dairy milk allocation of **0.5 Litres** logged and provided.

| PRODUCTION / RATION CATEGORY | MORNING SESSION  | EVENING SESSION | DAILY TOTAL       |
|------------------------------|------------------|-----------------|-------------------|
| Dairy Cattle Milking Yield   | 4.5 Litres       | 3.0 Litres      | <b>7.5 Litres</b> |
| Goat Kids Nutritional Ration | 0.5 Litres       | 0.5 Litres      | <b>1.0 Litre</b>  |
| Maasai Milk Allocation       | Daily Allocation |                 | <b>0.5 Litres</b> |



**Canine Unit Care, Landscape Upkeep & Vehicle Maintenance**

- **Canine Leash Walking & Exercise:** Mwangi conducted structured walking on leash drills with the canine unit, reinforcing handler control, pacing, and focus.
- **Comprehensive Dog Grooming:** Full grooming routine executed for the dogs, including thorough coat combing and precision nail clipping.
- **Palm Trees Irrigation:** Systematic watering applied to palm trees across the farm compound to support robust growth and vitality.

**Vehicle Maintenance:** Completed thorough washing and detailing of Madam Carol's vehicle.

- **Field Photographic Documentation Note**

No photographs were taken for Mwangi's section today as the supervisor does not own a smartphone device. All reported activities have been verified and logged directly from daily field briefings.



**Compiled by Dennis**

Daily Operations Progress Report • August 23, 2026

**Status: Verified & Logged**