DAILY OPERATIONS REPORT

Sunday, 11th October 2026

Daily Operations Progress Report

Comprehensive field operational briefing covering golf course agronomy, sprinkler irrigation layout, civil drainage connections, livestock dairy production, rock garden landscaping, canine unit training, and facility maintenance across Mucheru World of Golf, Chaka Farms, and Amani Cottage.

COURSE AGRONOMY FINISHING

Greens 2, 3, 4, 8 & 9

Riversand & Red Soil Leveled

IRRIGATION POP-UP LAYOUT

17 Greens Marked

Sprinklers Sited (All except #5)

DAIRY MILK PRODUCTION

6.5 Litres

6.0L Sold • 0.5L Maasai (100% Reconciled)

CIVIL DRAINAGE & FACILITIES

PVC Joined • Doors Fixed

Dam 3 Intake • Amani Cottage Serviced

Executive Summary — Sunday Operations Overview

Field operations on Sunday, 11th October 2026 maintained exceptional momentum across all active project sites, achieving major agronomic finishing milestones, irrigation pop-up sprinkler positioning, civil drainage pipe connections, and continuous reservoir replenishment at Mucheru World of Golf; fully reconciled dairy milk production, rock garden stone terracing, and canine unit socialization and manners training at Chaka Farms; and facility door maintenance at Amani Cottage:

Key Milestone Accomplishments Across Active Sites

Golden riversand and surplus red soil were spread and precision-leveled across five putting greens (Greens 2, 3, 4, 8, and 9); pop-up sprinkler positions were accurately surveyed, measured, and marked across 17 putting greens (all except Green 5); on-site plumber completed handsaw cutting and solvent jointing of orange PVC pipes in fairway drainage trenches; Githinji's crew excavated green and teebox inlet drainage lines; continuous water harvesting into Dam 3 progressed steadily; dairy milk production achieved 100% mathematical reconciliation (6.5L gross harvested, 6.0L commercial sales, 0.5L Maasai allocation); rock garden stone terracing advanced at the main house; canine unit manners, cleaning, paw command drills, goat socialization, and off-leash exercise executed; and two doors serviced at Amani Cottage by Fundi Johnson.

- **Mucheru World of Golf:** Agronomy crews under Joe Kamau and Carol completed riversand spreading and precision leveling over pumice beds on Greens 8, 4, 9, 3, and 2. Concurrently, ground teams leveled surplus red topsoil along outer collars, aprons, and banks across all five greens to establish seamless playing surrounds. Joe surveyed and marked every pop-up sprinkler location across 17 greens (all except Green 5). The site plumber joined orange PVC pipes along network trenches, while Peter Githinji's crew dug inlet water drainage trenches for greens and teeboxes. Replenishment inflow into Dam 3 continued actively under the supervision of Mr. Gichuhi and Ken.
- **Chaka Farms:** Dairy milking operations supervised by Kamandau yielded 6.5 Litres of gross cow milk (3.0L morning / 3.5L evening), fully reconciling commercial sales of 6.0 Litres (2.5L morning / 3.5L evening) and an internal farm allocation of 0.5 Litres for Maasai with zero discrepancy. Ken oversaw ongoing construction of the landscaped rock garden at the main house, where natural stone terracing was erected along the earthen mound. Willy conducted canine unit kennel manners, cleaning, paw command drills, goat herd socialization, and afternoon off-leash exercise in the paddock.
- **Amani Cottage:** Maintenance operations overseen by Edwin included receiving Fundi Johnson, who serviced and repaired two doors on the property: the main entrance door and an interior room door, addressing lock mortise alignment and door clearance issues.

Mucheru World of Golf

Overseen by: Mr. Gichuhi & Ken | On Site: Joe Kamau & Carol | Trenching: Peter Githinji's Crew

Riversand & Red Soil Leveled on 5 Greens (2, 3, 4, 8 & 9), Sprinkler Positioning, Drainage Pipe Jointing & Dam 3 Inflow

Operations at Mucheru World of Golf on Sunday, 11th October 2026 registered major agronomic, civil drainage, and irrigation layout achievements under the site supervision of Mr. Gichuhi and Ken, with technical leadership and agronomy execution led by Joe Kamau and Carol alongside Peter Githinji's trenching crew:

> ### Mucheru World of Golf Operations Summary
>
> Golden riversand and surplus red soil were leveled across Greens 2, 3, 4, 8, and 9; pop-up sprinkler positions were accurately measured and marked across every green except Green 5; on-site plumber cut and joined orange PVC drainage pipes along excavated network trenches; Githinji's crew dug incoming water drainage trenches for greens and teeboxes; and continuous water intake into Dam 3 progressed steadily.

- **Riversand Spreading & Precision Leveling (Greens 2, 3, 4, 8 & 9):** Joe Kamau's agronomy team spread and leveled golden riversand over the volcanic pumice beds on Greens 8, 4, 9, 3, and 2. Ground crews used landscape rakes and straightedges to achieve uniform agronomic rootzone thickness and smooth surface contours across all five greens.
- **Leveling of Surplus Red Soil Surrounds (Greens 2, 3, 4, 8 & 9):** Alongside sand leveling, field teams worked around the perimeters of Greens 8, 4, 9, 3, and 2 to grade and level the surplus red topsoil previously delivered and placed along collars, aprons, and outer embankments, creating clean transitions between putting surfaces and surrounds.
- **Pop-Up Sprinkler Staking & Measurement (17 Greens Marked):** Joe Kamau systematically surveyed, measured with tape, and marked the precise installation locations for automatic pop-up sprinklers across 17 putting greens (covering every green across the course with the sole exception of Green 5). This layout ensures uniform 360-degree irrigation coverage once pipe connections are completed.
- **Drainage PVC Pipe Jointing & Plumbing Connections:** The on-site plumber worked directly along excavated network trenches, cutting orange PVC pipes to length with a handsaw and joining pipe segments to convey excess runoff and stormwater away from greens and fairway corridors.
- **Green & Teebox Inlet Drainage Trenching (Githinji's Crew):** Peter Githinji's crew conducted manual pick and shovel excavation of dedicated inlet water drainage trenches servicing both putting greens and championship teeboxes to manage gravity inflows.
- **Continuous Water Intake Progress at Dam 3:** Replenishment of Dam 3 progressed smoothly throughout the day, with water flowing steadily through inlet channels and accumulating within the lined reservoir basin.

⛳ Course Agronomy & Engineering Status Audit — Putting Greens (1 – 18)

Audited by: Dennis

18-hole putting green status audit showing the latest work completed and current condition for each green as of October 11, 2026:

GREEN	CURRENT TECHNICAL & AGRONOMIC STATE	MILESTONE STATUS
Green 1	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2); pop-up sprinklers measured and marked (Oct 11).	Surplus Red Soil Applied
Green 2 TODAY	Riversand spread and leveled over pumice bed; surplus red soil leveled along surrounds; pop-up sprinklers measured and marked (Oct 11).	Riversand Leveled
Green 3 TODAY	Riversand spread and leveled over pumice bed; surplus red soil leveled along apron and bank; pop-up sprinklers measured and marked (Oct 11).	Riversand Leveled
Green 4 TODAY	Riversand spread and leveled over pumice bed; surplus red soil leveled along surrounds; pop-up sprinklers measured and marked (Oct 11).	Riversand Leveled
Green 5	Connected PVC pipes to green outlet drainage trench for excess runoff and sprinkler lines (Oct 9).	Drainage PVC Connected
Green 6	Surplus red soil applied to raise and level surrounds (Sep 28); pop-up sprinklers measured and marked (Oct 11).	Apron Raised • Palms Placed
Green 7	Riversand applied over pumice bed and precisely leveled across entire green surface (Oct 10); pop-up sprinklers measured and marked (Oct 11).	Riversand Leveled
Green 8 TODAY	Riversand spread and leveled over pumice bed; surplus red soil leveled along surrounds; pop-up sprinklers measured and marked (Oct 11).	Riversand Leveled
Green 9 TODAY	Riversand spread and leveled over pumice bed; surplus red soil leveled along surrounds; pop-up sprinklers measured and marked (Oct 11).	Riversand Leveled
Green 10	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2); pop-up sprinklers measured and marked (Oct 11).	Surplus Red Soil Applied
Green 11	Riversand application in progress over pumice bed; partial coverage completed (Oct 3); pop-up sprinklers measured and marked (Oct 11).	Riversand in Progress
Green 12	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2); pop-up sprinklers measured and marked (Oct 11).	Surplus Red Soil Applied
Green 13	Surplus red soil spread around surrounds to raise and match green level (Sep 29); pop-up sprinklers measured and marked (Oct 11).	Surplus Red Soil Applied
Green 14	Connected PVC pipes to green outlet drainage trench to remove surplus stormwater (Oct 9); pop-up sprinklers measured and marked (Oct 11).	Drainage PVC Connected
Green 15	Riversand applied over pumice bed across most part of green (Oct 3); pop-up sprinklers measured and marked (Oct 11).	Riversand Applied (Most Part)
Green 16	Riversand applied over pumice bed across most part of green (Oct 9); pop-up sprinklers measured and marked (Oct 11).	Riversand in Progress
Green 17	Surplus red soil spread around surrounds to raise and align levels (Sep 29); pop-up sprinklers measured and marked (Oct 11).	Surplus Red Soil Applied
Green 18	Riversand spreading commenced over pumice bed reaching ~50% coverage (Oct 10); pop-up sprinklers measured and marked (Oct 11).	Riversand in Progress (50%)

🏌️ Course Engineering Status Audit — Championship Teeboxes (1 – 18)

Audited by: Dennis

Comprehensive 18-hole championship teebox platform audit tracking earthwork leveling, structural embankments, and playing corridor alignments as of October 11, 2026:

TEEBOX	CURRENT TECHNICAL & EARTHWORK STATE	PLATFORM STATUS
Tee 1	Championship launch platform completely reshaped, cut, and graded to design elevation using Backhoe Loader (Sep 24); received 1 lorry red soil delivery (Sep 26).	Platform Reshaped
Tee 2	Playing launch platform completely reshaped, contoured, and graded using Backhoe Loader (Sep 24); received 1 lorry red soil delivery (Sep 26).	Platform Reshaped
Tee 3	Playing launch platform completely reshaped, contoured, and graded using Backhoe Loader (Sep 24); received 1 lorry red soil delivery (Sep 26).	Platform Reshaped
Tee 4	Championship launch platform completely reshaped, cut, and graded using Backhoe Loader (Sep 23); received 1 lorry red soil delivery (Sep 26).	Platform Reshaped
Tee 5	Main perimeter drainage pipeline backfilled all the way past Maina's place (Oct 2).	Drainage Backfilled
Tee 6	Precision leveling and compaction completed; fresh delivery of 1 lorry red loam topsoil unloaded at platform surrounds (Sep 26).	Red Soil In • Leveled
Tee 7	Both number 7 teebox platforms actively reshaped, cut, and leveled by crew under Joe Kamau and supervisors (Oct 4).	Both Platforms Reshaped
Tee 8	Graded, leveled, and contour-adjusted; fresh delivery of 1 lorry red loam topsoil unloaded directly on platform (Sep 26).	Red Soil In • Graded
Tee 9	Playing platform leveled and surrounding perimeter ground graded (Sep 1); received 1 lorry red soil delivery (Sep 26).	Platform Leveled
Tee 10	Graded and compacted platform serving the start of the back-nine playing corridor; received 1 lorry red soil delivery (Sep 26).	Platform Compacted
Tee 11	Playing launch platform actively shaped, graded, and refined to final architectural contours and levels (Oct 8).	Shaped & Refined
Tee 12	Both championship and forward platforms actively shaped, leveled, and refined to finished design elevation (Oct 8).	Shaped & Refined
Tee 13	Playing platform earthworks completely finished, shaped, and refined to final design elevation and contours (Oct 7).	Finished & Refined
Tee 14	Launch platform earthworks completely finished, shaped, and refined to final playing contour (Oct 7).	Finished & Refined
Tee 15	Launch platform shaping completely finished; terrace cut to design elevation and precision leveled (Oct 6).	Platform Reshaped
Tee 16	Surplus red soil moved onto platform; launch terrace completely reshaped and leveled (Oct 5).	Platform Reshaped
Tee 17	Launch platform reshaped, cleared of brush, and graded to playing corridor alignment (Oct 6).	Platform Reshaped
Tee 18	Championship tee platform leveled; perimeter approach cleared and graded (Sep 1); received 1 lorry red soil delivery (Sep 26).	Platform Leveled

Operations Agronomy & Engineering Synthesis

Putting Greens & Hydraulic Progress: Golden riversand and surplus red soil were spread and precision-leveled across Greens 2, 3, 4, 8, and 9; pop-up sprinkler positions surveyed and marked across 17 putting greens (all except Green 5); plumber joined orange PVC pipes in drainage trenches; Peter Githinji's crew excavated green and teebox inlet drainage lines; continuous water harvesting into Dam 3 ongoing.
Championship Teebox Platforms: 100% of championship launch platforms leveled, compacted, or shaped; teebox inlet water drainage trenches actively excavated to ensure optimal stormwater discharge and irrigation supply.

📸 Photographic Field Evidence — Mucheru World of Golf

Sequential photographic field documentation covering riversand and red soil leveling across greens, pop-up sprinkler measuring and marking, PVC pipe handsaw cutting and jointing in drainage trenches, and continuous water intake into Dam 3:



Crew Leveling Red Soil and Riversand on Green
Field crew using shovels and rakes to level riversand in the center while simultaneously spreading red soil along surrounds.



Joe's Agronomy Crew Leveling Green Surface
Workers in blue attire raking golden riversand smoothly across the green bed while team members level red soil on the left collar.



Green 3 Riversand and Red Soil Collar Leveled
Worker holding a landscape rake standing on Green 3, showing the smooth leveled riversand putting bed and finished red soil surrounds.



Full Perspective of Leveled Riversand & Red Soil
Elevated view of a completed green showing the golden riversand putting surface neatly bordered by uniform red loam surrounds.



Close-Up of Leveled Soil and Sand Boundary
Detailed view of the smooth transition line between the compacted golden riversand bed and the leveled red topsoil collar.



Curved Apron Red Soil and Riversand Contour
Looking along the perimeter contour of the green with smooth riversand inside and neatly leveled red soil bank outside.



Finished Putting Green Surface Profile

Finished view of the organic green shape featuring fully leveled golden riversand framed by contoured red loam topsoil.



Joe Measuring & Staking Pop-Up Sprinklers

Joe Kamau using a measuring tape stretched across the green surface to accurately position and stake pop-up sprinkler points.



Plumber Cutting & Jointing Orange PVC Drainage Pipes

Plumber using a handsaw to cut and prepare orange PVC pipes along the excavated fairway drainage trench for connection.



Dam 3 Continuous Water Intake and Reservoir Inflow

Dam 3 lined water reservoir actively holding incoming harvested water reflecting the sky, with perimeter berms secure.

Chaka Farms

Milking Operations: Kamandau | Rock Garden: Ken | Canine Routines: Willy

Dairy Production (6.5L Reconciled), Main House Rock Garden Terracing & Canine Unit Socialization & Manners

Operations at Chaka Farms on Sunday, 11th October 2026 maintained rigorous standards across commercial dairy production, landscape civil construction, and canine behavioral conditioning:

> **Chaka Farms Progress Summary**
>
> Dairy milking achieved 6.5 Litres gross yield with 100% mathematical reconciliation (6.0L commercial sales and 0.5L Maasai allocation); Ken oversaw ongoing stone terracing and mound shaping for the main house rock garden; Willy conducted canine kennel manners, cleaning, paw command drills, goat socialization, and afternoon off-leash exercise.

- **Dairy Production & Volume Reconciliation (Kamandau):** Morning milking produced 3.0 Litres and evening milking yielded 3.5 Litres, providing a gross production of 6.5 Litres. Commercial sales accounted for 6.0 Litres (2.5L morning + 3.5L evening), while 0.5 Litres was allocated on-farm for Maasai, achieving 100% volume reconciliation with zero discrepancy.
- **Main House Rock Garden Construction (Ken):** Construction of the landscaped rock garden fronting the main residence continued under Ken's supervision. Selected natural building stones were arranged along the sculpted earthen mound to form multi-tiered terraced retaining borders for ornamental garden beds.
- **Canine Unit Kennel Manners & Stall Cleaning (Willy):** Willy performed thorough stall sanitation and kennel hygiene. Dogs underwent kennel manners drills, practicing threshold restraint and entering/exiting stalls upon verbal command.
- **Paw Command & Behavioral Conditioning (Willy):** Dogs were guided through "paw" obedience commands, reinforcing positive engagement and handler attentiveness.
- **Goat Herd Socialization Training (Willy):** The canine unit was introduced to the farm's goat herd in a structured, supervised socialization drill, training the dogs to remain calm, respectful, and non-reactive around livestock.
- **Afternoon Exercise & Off-Leash Play (Willy):** During the afternoon, Willy exercised the dogs in the open paddock, allowing energetic play and physical enrichment while maintaining responsive voice recall.

🥛 Daily Dairy Milking Yield Ledger & Volume Reconciliation

Complete volumetric breakdown of daily milk production, commercial sales, and internal farm allocations recorded on Sunday, 11th October 2026:

Category / Transaction	Morning Session	Evening Session	Daily Total
Gross Milk Harvested	3.0 Litres	3.5 Litres	**6.5 Litres**
Commercial Milk Sales (Dispatched)	2.5 Litres	3.5 Litres	**6.0 Litres**
Internal Farm Allocation — Maasai	—	—	**0.5 Litres**
Internal Farm Allocation — Gladys (Staff)	—	—	0.0 Litres
Internal Farm Allocation — Goat Kids (Weaned)	0.0 Litres	0.0 Litres	0.0 Litres
Total Volume Accounted For	**3.0 Litres**	**3.5 Litres**	**6.5 Litres (100% Reconciled)**

> **Milk Reconciliation Formula Verification**
> Total Gross Milk Harvested (6.5L) = Commercial Sales (6.0L) + Internal Allocation (0.5L Maasai). 100% accounted for with zero discrepancy.

🎬 Video Documentation — Chaka Farms Canine Unit Training & Exercise

Field video recordings documenting Sunday's canine unit off-leash paddock play, goat herd socialization, and kennel manners training conducted by Willy:

Dogs Playing & Paddock Exercise

🎥 VIDEO RECORDING

Willy supervising the farm dogs enjoying free play and active exercise in the afternoon paddock, reinforcing natural pack dynamics and recall responsiveness.

📁 Access on Google Drive

`dogs playing.mp4 (9.8 MB)`

Socializing with Goats

🎥 VIDEO RECORDING

Controlled socialization session with the dogs interacting calmly with the goat herd to instill livestock harmony and eliminate chase instincts.

📁 Access on Google Drive

`Socializing with goates.mp4 (9.2 MB)`

Kennel Manners Drill

🎥 VIDEO RECORDING

Willy conducting kennel entry/exit restraint drills and paw commands with the canine unit, reinforcing stall boundary discipline and attentiveness.

📁 Access on Google Drive

`Kennel manners.mp4 (10.2 MB)`

📸 Photographic Field Evidence — Chaka Farms

Photographic field documentation covering the ongoing construction of stepped stone terracing and mounds for the rock garden at the main house:



Main House Rock Garden Stone Terracing Construction

Multi-tiered natural stone retaining borders erected along the sculpted earthen mound fronting the lawn at the main residence.

Amani Cottage

Overseen by: Edwin

Carpentry Specialist: Fundi Johnson

Facility Maintenance — Main Door & Bedroom Door Repairs by Fundi Johnson

Facility maintenance operations at Amani Cottage were overseen by Edwin, addressing essential door hardware and architectural carpentry adjustments:

> ### Amani Cottage Maintenance Summary
>
> Fundi Johnson visited the cottage to repair and service two doors: the cottage main entrance door and an interior bedroom door that had a minor issue, ensuring smooth operation, strike alignment, and secure closure.

- **Main Entrance Door Mortise & Strike Realignment:** Fundi Johnson inspected the main entrance wooden door, using hand chisels and alignment tools to adjust the lock mortise and latch strike plate. This eliminated binding against the door jamb and restored effortless latching.
- **Interior Bedroom Door Repair & Lubrication:** Fundi Johnson addressed minor alignment and clearance issues on one of the room doors, fine-tuning hinge balance and lubricated latch components to ensure quiet and seamless opening and closing.

📸 Photographic Field Evidence — Amani Cottage

Photographic field documentation capturing door repairs and carpentry maintenance conducted by Fundi Johnson at Amani Cottage:



Fundi Johnson Servicing Door Lock Mortise
Carpenter using a hand chisel to carefully adjust the wooden door edge and mortise opening for latch alignment.



Door Strike Plate Adjustment & Edge Finishing
Adjusted metal strike plate and wooden door frame jamb completed at Amani Cottage, with pliers and lubricant spray on site.

D **Compiled by Dennis**

Sunday, 11th October 2026 • Operations Reporting