DAILY OPERATIONS PROGRESS REPORT

Wednesday, 21st October 2026

Daily Operations Report

Mucheru World of Golf • Chaka Farms • Kabete Residence

RIVER SAND HAULAGE

1 Tipper Lorry

Applied & Spread on Green 13

TEEBOX EARTHWORKS

4 Platforms

Tees 13, 15, 17 Red Soil • Tee 6 Trenched

DAILY DAIRY YIELD

9.0 Litres

8.0L Dispatched • 1.0L Farm Allocations

RESERVOIR & HYDRAULICS

100%

Complete

Dam 2 Liner Repaired • Pump Interconnected

Executive Summary & Multi-Site Operations Synthesis

Field operations on Wednesday, 21st October 2026 achieved significant, verifiable milestones across golf course agronomy, cross-site hydraulic engineering, reservoir maintenance, dairy yield accounting, canine behavioral conditioning, building structural steel fabrication, and domestic pet care across three active sites:

Key Milestone Accomplishments Across Active Sites

Mucheru World of Golf: Delivery and application of 1 heavy tipper lorry of clean river sand onto Green 13 over its foundation stone base; red topsoil applied, spread, and leveled across Teeboxes 13, 15, and 17; trench excavated through Teebox 6 platform to lay HDPE irrigation pipe connecting to Green 7 system; orange PVC drainage pipe invert levels measured with a water level hose to guarantee positive gravity flow; women crew backfilled the cross-course irrigation pipe trench; Chaka Farms irrigation pump successfully connected to golf course piping network; Dam 2 liner repair fully completed; Dam 3 maintained full water capacity; and 2 palm trees hauled from Chaka Farms and planted.

Chaka Farms: Daily dairy harvest reached 9.0 Litres gross yield (5.5L morning + 3.5L evening), with 8.0 Litres dispatched for commercial sales (4.5L morning + 3.5L evening) and 1.0 Litre distributed for routine internal farm allocations (0.5L Gladys staff ration + 0.5L Maasai), achieving 100% quantitative accounting reconciliation strictly in Litres; farm purchased 70kg dairy feeds, 2.5L cattle spraying chemical, and 500g DCP salt; Ken oversaw manual excavation of 5 deep fruit tree planting holes; Willy conducted canine kennel manners conditioning, paw command drills, obedience exercises, and morning socialization with Coby, Mali, and Logan; and Margaret and Monica maintained compound cleanliness and tended island grass.

Kabete Residence: Operations overseen and shared by Njoki; construction team bent, assembled, and welded steel rebar beam cages and reinforcement formwork for the SQ fireplace structure; set up fabricated beam cages into the timber shutter bed; raised electrical cables off the ground along the stone foundation wall to clear space for the shutter formwork base; excavated steep hillside drainage trench behind SQ wall; and cared for domestic pets (Ajabu walked on leash and fed indoors; resident cats Mocha, Reo, and Aiko reunited and fed together).

- **Green 13 River Sand Spreading & Teebox Topsoil Layering:** 1 lorry of clean river sand delivered and spread across Green 13 stone foundation; Teeboxes 13, 15, and 17 layered and leveled with rich red soil; Teebox 6 trenched for HDPE line.
- **Drainage Gravity Levelling & Cross-Site Pump Hookup:** Orange PVC drainage pipe levels measured with water level hose for continuous gravity runoff; cross-course pipe trench backfilled; Chaka Farms irrigation pump connected to golf network.
- **Dam 2 Liner Repair Completed & Palm Tree Landscaping:** Polythene liner seam repairs and anchor trench tucking on Dam 2 reached 100% completion; Dam 3 retains full water volume; 2 mature palm trees translocated and planted.
- **Zero-Variance Dairy Accounting & Farm Inputs:** 9.0 Litres harvested milk fully reconciled in Litres (8.0L commercial sales + 1.0L farm allocations); 70kg feeds, 2.5L spray chemical, and 500g DCP salt acquired; 5 fruit tree holes excavated.
- **SQ Fireplace Rebar Assembly, Shuttering & Cable Elevation:** Steel rebar beam cages fabricated and positioned into timber shutter formwork; electric cables lifted above ground level; hillside drainage trench excavated behind SQ wall.

Mucheru World of Golf

Site Oversight: Mr. Gichuhi & Ken

River Sand Spreading, Teebox Earthworks, Gravity Flow Calibration, Pipe Backfill & Dam Completion Brief

Field operations at Mucheru World of Golf on Wednesday, 21st October 2026 accomplished major technical, agronomic, and hydraulic milestones under the supervision of Mr. Gichuhi and Ken:

Golf Course Operational Highlights

One tipper lorry of clean river sand was delivered and spread across the foundation stone bed of Green 13. Ground crews applied, shaped, and leveled red topsoil across Teeboxes 13, 15, and 17, and trenched through Teebox 6 to lay an HDPE pipe connecting to Green 7. Invert levels of orange PVC drainage pipes were calibrated using a water level hose to guarantee positive gravity flow. Women crew backfilled the cross-course irrigation trench. The Chaka Farms irrigation pump was tied into the golf course mainline. Dam 2 liner repairs were fully completed, Dam 3 held full water capacity, and 2 palm trees were translocated and planted.

- **River Sand Delivery & Spreading on Green 13:** A tipper lorry delivered clean river sand to the course. Ground crews shoveled, wheelbarrowed, and spread the river sand over the gravel stone foundation layer of Green 13, preparing the agronomic profile for final surface leveling.
- **Red Soil Application & Leveling on Teeboxes 13, 15 & 17:** Ground crews hauled and spread rich red soil across three championship launch platforms: commencing initial soil placement on Teebox 13, spreading mounded soil to full terrace width on Teebox 15, and leveling Teebox 17 to finished design grade.
- **HDPE Irrigation Trenching Through Teebox 6:** Laborers excavated an open trench directly across Teebox 6 platform to lay a black HDPE irrigation line routing water across the corridor to interconnect with the secondary piping system near Green 7.
- **PVC Drainage Levelling & Gravity Flow Verification:** On-site plumbers and technicians used a transparent vinyl water level hose and tape measures along the orange PVC drainage pipeline to check trench invert elevations, ensuring continuous positive slope for gravity runoff into the main collector.
- **Cross-Course Pipeline Trench Backfilling:** The women manual labor crew followed the secondary irrigation line installed across the fairway, shoveling and leveling excavated topsoil back into the trench to protect the pipe and restore the playing surface.
- **Chaka Farms Irrigation Pump Network Interconnection:** Specialized plumbing crews linked the high-capacity irrigation pump station at Chaka Farms to the golf course main distribution network, fitting HDPE and green PPR pipes, compression fittings, and red handle isolation gate valves.
- **Dam 2 Liner Repair 100% Complete & Palm Tree Planting:** Githinji's women crew completed sealing and tucking all polythene liner connections on Dam 2 basin. Meanwhile, 2 palm tree holes were dug and 2 mature palm trees hauled from Chaka Farms were planted along the boundary. Dam 3 remained at full water level.

⛳ Course Agronomy & Engineering Status Audit — Putting Greens (1 – 18)

Audited by: Dennis

18-hole putting green status audit showing the latest work completed and current condition for each green as of October 21, 2026:

GREEN	CURRENT TECHNICAL & AGRONOMIC STATE	MILESTONE STATUS
Green 1	HDPE irrigation pipes laid and fitted inside perimeter sprinkler trenches (Oct 18).	Sprinkler Pipes Laid
Green 2	HDPE irrigation pipes laid and fitted inside perimeter sprinkler trenches (Oct 18).	Sprinkler Pipes Laid
Green 3	HDPE irrigation pipes laid and fitted inside perimeter sprinkler trenches (Oct 18).	Sprinkler Pipes Laid
Green 4	Pop-up sprinkler and irrigation perimeter trenches dug along marked chalk line (Oct 14).	Sprinkler Trenches Complete
Green 5	Ready. Fully established mature championship putting green turfgrass under active pop-up sprinkler irrigation conditioning.	Ready • Established Turf
Green 6	Pop-up sprinkler trenches digging completed around green perimeter collar (Oct 15).	Sprinkler Trenches Complete
Green 7	Drainage outlet trench connecting green 7 to main canal dug and leveled by manual crew (Oct 15).	Outlet Trench Dug • Leveled
Green 8	Pop-up sprinkler trenches digging completed around green perimeter (Oct 15).	Sprinkler Trenches Complete
Green 9	Orange drainage PVC pipe connected and outlet trench leveled leading to main canal (Oct 15).	PVC Connected • Trench Done
Green 10	Pop-up sprinkler trenches digging completed around collar and surrounds (Oct 15).	Sprinkler Trenches Complete
Green 11	Pop-up sprinkler trenches digging completed around green perimeter (Oct 15).	Sprinkler Trenches Complete
Green 12	Pop-up sprinkler trenches digging completed around perimeter collar (Oct 15).	Sprinkler Trenches Complete
Green 13 TODAY	Clean riversand delivered, applied, and spread across foundation stone layer (Oct 21).	Riversand Applied
Green 14	Riversand application and surface leveling completed across the foundation (Oct 18).	Riversand Leveled
Green 15	Pop-up sprinkler trenches digging completed around outer collar surrounds (Oct 15).	Sprinkler Trenches Complete
Green 16	Pop-up sprinkler trenches digging completed around green perimeter collar (Oct 15).	Sprinkler Trenches Complete
Green 17	Riversand application and surface leveling fully completed across foundation (Oct 19).	Riversand Leveled
Green 18	Pop-up sprinkler trenches dug; riversand applied and leveled across green surface (Oct 14).	Riversand • Sprinkler Trench

🏌️ Course Engineering Status Audit — Championship Teeboxes (1 – 18)

Audited by: Dennis

Comprehensive 18-hole championship teebox platform audit tracking earthwork leveling, structural embankments, and playing corridor alignments as of October 21, 2026:

TEEBOX	CURRENT TECHNICAL & EARTHWORK STATE	PLATFORM STATUS
Tee 1	Launch platform surface grading and leveling actively refined to design elevation per new instructions (Oct 20).	Refined & Graded
Tee 2	Platform surface grading and earthwork leveling further refined per updated instructions (Oct 20).	Refined & Graded
Tee 3	Playing launch platform contoured, leveled, and refined per new instructions given today (Oct 20).	Refined & Graded
Tee 4	Championship launch platform surface graded, contoured, and refined per new instructions (Oct 20).	Refined & Graded
Tee 5	Playing platform surface actively graded and refined with red soil per new instructions (Oct 20).	Grading & Refining
Tee 6 TODAY	Trench excavated through platform to lay HDPE irrigation pipe connecting to Green 7 system (Oct 21).	Irrigation Trench Dug
Tee 7	Both platforms actively graded, contoured, and refined with red soil per new instructions (Oct 20).	Refined & Graded
Tee 8	Championship launch platform surface grading and contour refinement actively continued (Oct 19).	Grading & Refining
Tee 9	Playing launch platform grading and contour refinement continued per new instructions (Oct 20).	Refinement in Progress
Tee 10	Playing launch platform surface further refined and graded as per updated instructions (Oct 20).	Platform Refined
Tee 11	Playing launch platform grading and contour refinement completely finished (Oct 13).	Refinement Complete
Tee 12	Both championship and forward platforms actively shaped, leveled, and refined to finished design elevation (Oct 8).	Shaped & Refined
Tee 13 TODAY	Initial layer of red soil hauled, applied, and spread across platform surface (Oct 21).	Red Soil Applied
Tee 14	Launch platform earthworks completely finished, shaped, and refined to final playing contour (Oct 7).	Finished & Refined
Tee 15 TODAY	Red soil hauled, spread, and leveled across platform to finished design elevation (Oct 21).	Red Soil Leveled
Tee 16	Surplus red soil moved onto platform; launch terrace completely reshaped and leveled (Oct 5).	Platform Reshaped
Tee 17 TODAY	Red soil applied, spread, and leveled across platform terrace adjacent to Green 17 (Oct 21).	Red Soil Leveled
Tee 18	Championship launch platform surface grading, red soil leveling, and refinement underway (Oct 16).	Grading & Refining

Operations Agronomy & Engineering Synthesis

Course Agronomy & Earthwork Milestones: Green 13 advanced with clean riversand delivery and spreading over its foundation layer; Teeboxes 13, 15, and 17 were layered and leveled with rich red topsoil; Teebox 6 was trenched to lay HDPE irrigation pipe routing to Green 7.
Hydraulic & Reservoir Infrastructure: Invert levels of orange PVC drainage pipes were verified with a water level tube for positive gravity flow; cross-course irrigation pipe trench was backfilled; Chaka Farms pump station was hooked into the golf mainline; Dam 2 liner repair reached 100% completion; Dam 3 maintained full water capacity; and 2 palm trees were translocated and planted.

🎬 Video Documentation — Mucheru World of Golf Daily Operations

🎥 VIDEO RECORDING

Field video documentation capturing Wednesday, 21st October 2026 operations at Mucheru World of Golf: tipper delivery and manual spreading of clean river sand across Green 13 stone foundation, application and grading of red topsoil across Teeboxes 13, 15, and 17, excavation of an irrigation trench across Teebox 6 connecting to Green 7, measuring orange PVC pipe levels with water level hose for continuous gravity fall, backfilling the cross-course pipeline trench, Chaka Farms pump station pipe connection, and Dam 2 liner completion.

▶ Watch on YouTube

URL: https://youtu.be/q12ryvoKvFg

📸 Photographic Field Evidence — Mucheru World of Golf

Sequential photographic field documentation capturing river sand deliveries, green foundation spreading, teebox red soil earthworks, irrigation trenching, gravity pipe levelling, backfilling, dam infrastructure, and landscaping at Mucheru World of Golf:

River Sand Material Delivery
Heavy commercial tipper lorry delivering a full load of clean river sand to site for putting green agronomic profile construction.

River Sand Spreading on Green 13
Ground crew utilizing shovels and wheelbarrows to transport and spread delivered river sand over the gravel stone foundation.

Green 13 Sand Placement Underway
Early phase of spreading river sand over the leveled foundation matrix inside the red soil collar perimeter on Green 13.

Aerial Drone View — Green 13
High-altitude drone perspective showing the circular putting green with river sand partially layered across the foundation bed.

Red Soil Application — Teebox 13
Manual crew wheelbarrowing and shoveling fresh red topsoil onto the elevated Teebox 13 platform along the perimeter fence.

Earthwork Layering — Teebox 15
Laborers moving red soil from a staged mound to build up and grade the playing surface platform on Teebox 15.

Teebox 15 Platform Surface

Ground perspective of the Teebox 15 launch terrace with red soil evenly distributed across the entire platform footprint.

Aerial Drone View — Teebox 15

Aerial overhead view showing the rectangular red soil playing platform of Teebox 15 aligned alongside the boundary corridor.

Teebox 17 Leveled Platform

Fresh red topsoil applied and leveled to finished grade across Teebox 17 playing platform situated adjacent to Green 17.

Aerial Drone View — Teebox 17

Drone capture showing workers spreading red soil on Teebox 17 platform, with the adjoining sand-leveled green visible nearby.

Pipe Trenching Through Teebox 6

Aerial view of trench excavated directly through Teebox 6 platform to lay the HDPE irrigation line connecting to Green 7 system.

Pipeline Trench Backfilling

Women manual labor crew using hoes and shovels to backfill topsoil over the black HDPE pipe installed across the fairway.

PVC Drainage Joint Assembly

Plumbers inside the trench joining orange drainage PVC pipes with solvent cement and elbow fittings for collector drainage.

Gravity Invert Level Calibration

Technician checking the vertical elevation of orange PVC pipe fittings with a tape measure and water level tube for positive slope.

PVC Pipe Alignment & String Line

Long connected run of orange drainage PVC pipe positioned alongside the trench with grade stakes and string line set up.

Grade Stake & Slope Calibration

Crew member fine-tuning trench reference pegs using a clear water level hose to guarantee uninterrupted gravity water flow.

Drainage Canal Bed Leveling

Aerial drone photograph of laborers working inside the winding drainage canal, trimming high spots to secure smooth gravity discharge.

Dam 2 Liner Seam Repair Operations

Githinji's women crew working across the polythene geomembrane liner in Dam 2 basin, cleaning and preparing seam joints.

Aerial Drone View — Dam 2 Basin

Drone capture of Dam 2 reservoir showing the complete black polythene liner laid across basin floor and surrounding central island.

Aerial Drone View — Dam 3 Reservoir

Aerial inspection confirming Dam 3 maintaining excellent water storage at full capacity without liner leakage or seepage.



Palm Tree Pit Excavation

Farm workers digging deep planting holes along the course boundary fence for the two palm trees hauled from Chaka Farms.

Irrigation Pump Pipe Manifold

Detailed view of manifold connecting Chaka Farms pump station to golf mainline, showing HDPE, green PPR pipes, and valves.



Cross-Site Irrigation Supply Trench

Excavated supply trench routing interconnected HDPE and PPR pipes from the Chaka Farms water intake directly to the golf course line.

Chaka Farms

Dairy & Purchases: Kamandau | Canine Unit: Willy | Fruit Trees: Ken | Grounds & Island: Margaret & Monica

Dairy Milking Reconciliation, Farm Inputs, Fruit Tree Pits, Canine Conditioning & Grounds Care Brief

Operations across Chaka Farms on Wednesday, 21st October 2026 maintained balanced production, animal wellness, and grounds maintenance across four coordinated supervisory sectors:

Farm Operational Highlights

Dairy production yielded 9.0 Litres gross harvest (5.5L morning + 3.5L evening), with 8.0 Litres dispatched for commercial sales (4.5L morning + 3.5L evening) and 1.0 Litre distributed for routine internal farm allocations (0.5L Gladys staff ration + 0.5L Maasai), achieving 100% accounting reconciliation strictly in Litres with zero discrepancy. Farm purchases included 70kg dairy feeds, 2.5L cattle spraying chemical, and 500g DCP salt. Ken supervised the manual excavation of 5 deep fruit tree planting holes. Willy conducted morning socialization with white shepherds Coby, Mali, and Logan, alongside kennel manners, paw command drills, and obedience routines. Margaret and Monica maintained compound cleanliness and tended island grass.

- **100% Reconciled Dairy Harvest (9.0 Litres):** Kamandau recorded 9.0 Litres total gross milk yield across daily milking (5.5L morning + 3.5L evening). Commercial sales dispatched totaled 8.0 Litres (4.5L morning + 3.5L evening). Internal farm allocations accounted for 1.0 Litre (0.5L Gladys staff ration + 0.5L Maasai), achieving 100% accounting balance strictly in Litres with zero variance.
- **Farm Feed & Animal Health Input Purchases:** Farm operations procured key livestock inputs: 70 kg of dairy feeds, 2.5 Litres of cattle spraying chemical (acaricide), and 500 grams of DCP salt to maintain cattle nutritional and ectoparasite management routines.
- **Fruit Tree Planting Pit Excavation (5 Holes):** Under Ken's direction, farm workers excavated 5 large, deep planting holes in the orchard grounds in preparation for fruit tree planting (specific fruit varieties to be confirmed).
- **Canine Socialization, Kennel Manners & Obedience Drills:** Willy oversaw comprehensive canine routines: morning socialization on the open lawn with Coby, Mali, and Logan; kennel sanitation; structured paw command reinforcement; and patience and obedience conditioning.
- **Palm Tree Haulage & Island Lawn Maintenance:** Farm crew dug out and loaded 2 palm trees onto Mr. Gichuhi's pickup for haulage to the golf course. Concurrently, Margaret and Monica carried out compound weeding, sweeping, and grass maintenance across the farm island lawn.

🥛 Daily Dairy Milking Yield & Reconciliation Ledger (Litres)

Logged by: Kamandau

Official quantitative dairy milking harvest and sales ledger for Wednesday, 21st October 2026, recording gross yields, commercial dispatches, and internal farm disbursements strictly in Litres:

Category / Transaction	Morning Session	Evening Session	Daily Total
Gross Milk Harvested	5.5 Litres	3.5 Litres	**9.0 Litres**
Commercial Milk Sales (Dispatched)	4.5 Litres	3.5 Litres	**8.0 Litres**
Internal Farm Allocation — Gladys (Staff)	0.5 Litres	—	**0.5 Litres**
Internal Farm Allocation — Maasai	0.5 Litres	—	**0.5 Litres**
Internal Farm Allocation — Goat Kids (Weaned)	0.0 Litres	0.0 Litres	0.0 Litres
Total Volume Accounted For	**5.5 Litres**	**3.5 Litres**	**9.0 Litres (100% Reconciled)**

🛒 Daily Farm Input Purchases Log

Item Description	Quantity / Unit	Department / Usage	Status
Dairy Feeds	70 kg	Dairy Cow Nutrition	Received • In Use
Cattle Spraying Chemical (Acaricide)	2.5 Litres	Livestock Tick & Parasite Control	Received • In Stock
DCP Salt (Di-calcium Phosphate)	500 g	Mineral Supplementation	Received • In Use

Dairy Accounting & Farm Reconciliation Note

Total gross milk harvested of 9.0 Litres is 100% accounted for by 8.0 Litres sold commercially (4.5L morning + 3.5L evening) and 1.0 Litre in routine farm allocations (0.5L Gladys + 0.5L Maasai). In accordance with reporting rules, milk volumes are recorded strictly in Litres, and Maasai is designated strictly as Maasai with zero discrepancy. All livestock purchases are logged and verified on site.

🐕 Canine Unit Behavioral Conditioning & Compound Care

Canine Unit: Willy | Compound Care: Margaret & Monica

Daily conditioning routines, behavioral discipline, fruit tree pit excavation, and island grounds maintenance conducted on Wednesday, 21st October 2026:

- **Morning Pack Socialization on Open Lawn:** Willy conducted structured morning socialization drills with white shepherds Coby, Mali, and Logan on the open green lawn, fostering calm pack manners and focus.
- **Kennel Manners & Sanitation Routine:** Daily kennel cleaning was observed alongside structured kennel manners training, conditioning the dogs to remain calm, orderly, and patient during stall entry and exit.
- **Paw Command Drills & Obedience Conditioning:** Handlers practiced the paw ("pow") command alongside stay-and-release obedience drills, reinforcing responsive handler engagement and discipline.
- **Patience and Obedience Video Documentation:** Recorded long-line stay exercises verifying the dogs' patience and steadfast adherence to release commands under distracting outdoor environments.
- **Fruit Tree Pit Preparation:** Ken directed the manual excavation of 5 deep planting holes across the farm grounds in anticipation of fruit tree saplings arriving for installation.
- **Island Lawn Weeding & Compound Cleanliness:** Margaret and Monica carried out grounds maintenance, hand-weeding and trimming the lush turfgrass on the farm island while keeping pathways swept and clean.

🎬 Canine Unit: Kennel Manners Routine

🎥 VIDEO RECORDING

Field video documentation capturing Wednesday, 21st October 2026 canine unit routines under Willy: kennel sanitation, paw command practice, and structured kennel manners conditioning demonstrating calm, patient entry and exit discipline.

📁 Access Video on Google Drive

Kennel manners.mp4 (10.2 MB)

🎬 Canine Unit: Patience & Obedience Drills

🎥 VIDEO RECORDING

Field video documentation capturing Wednesday, 21st October 2026 canine training under Willy: patience, stay commands, and reliable obedience response drills conducted with the white shepherds on the farm grounds.

📁 Access Video on Google Drive

Patience and obedience to commands.mp4 (11.8 MB)

📸 Photographic Field Evidence — Chaka Farms

Photographic field documentation capturing canine pack socialization, fruit tree planting pit excavation, and island grounds maintenance across Chaka Farms:

Pack Socialization on Lawn

White shepherds Coby, Mali, and Logan resting attentively side-by-side during morning socialization and obedience training.

Canine Unit Discipline & Manners

Coby, Mali, and Logan displaying calm demeanor and pack focus under handler direction on the lush farm grounds.

Fruit Tree Planting Holes

Farm workers standing alongside deep excavated planting pits prepared across the orchard for upcoming fruit tree planting.

Excavated Planting Pit Detail

Close-up view of deep planting pit showing excavated topsoil loosened and ready for organic matter blending and sapling planting.

Island Lawn Grass Maintenance

Margaret and Monica manually weeding, trimming, and caring for the lush green grass on the Chaka Farms pond island.

SQ Fireplace Rebar Fabrication, Shuttering Setup, Cable Elevation, Hillside Drainage & Pet Care Brief

Operations at Kabete Residence on Wednesday, 21st October 2026 advanced structural steelwork, electrical clearance, hillside drainage excavation, and domestic animal care, overseen and shared by Njoki:

Residence Operational Highlights

Construction workers fabricated, bent, and welded steel rebar beam cages for the SQ fireplace formwork, utilizing angle grinders and rebar tying wire. The assembled beam reinforcement cages were placed and wired onto the timber shutter bed. Electric cables running along the ground were elevated and secured against the foundation wall to clear space for the shutter formwork base. Laborers continued manual excavation of the steep hillside drainage trench behind the SQ wall. Domestic pets received attentive daily care: Ajabu the Golden Retriever enjoyed leashed walks and indoor meals, while resident cats Mocha, Reo, and Aiko were reunited and fed together.

- **SQ Fireplace Steel Rebar Beam Fabrication:** Metalworkers measured, cut with angle grinders, and bent heavy steel rebar bars, assembling rigid rectangular beam reinforcement cages with wire stirrups for the SQ outdoor fireplace structure.
- **Shutter Formwork Beam Rebar Placement:** The prefabricated steel rebar beam cages were lifted into place and secured onto the geometric timber shutter formwork floor, establishing the structural core for the fireplace base slab.
- **Electrical Cable Elevation for Formwork Clearance:** Workers lifted and rerouted buried black electrical conduits along the stone foundation wall base, securing them safely above ground level to pave the way for shutter formwork casting.
- **Hillside Drainage Trench Excavation Behind SQ:** Laborers equipped with gumboots and shovels continued manual digging of the deep hillside drainage trench behind the SQ building to intercept slope runoff and prevent water intrusion.
- **Domestic Pet Wellness & Feline Reunion:** Domestic pets received routine care: Ajabu the Golden Retriever completed outdoor leashed walks and was fed indoors; resident cats—Mocha, Reo, and Aiko—were reunited after Mocha's return and fed together in stainless bowls.

📸 Photographic Field Evidence — Kabete Residence

Sequential photographic field documentation capturing hillside drainage excavation, electrical cable elevation, rebar beam bending and shutter placement, and domestic pet care at Kabete Residence:

SQ Hillside Drainage Excavation

Laborers digging the deep drainage trench into the steep red soil embankment behind the SQ building near the fireplace.

Electrical Conduit Elevation

Worker lifting and securing electric cables off the ground along the stone foundation wall to clear space for the shutter formwork base.

Rebar Beam Cage Fabrication

Metalworker bending and wiring steel reinforcement rebar stirrups and longitudinal bars for the SQ fireplace beam structure.

Rebar Cutting & Assembly

Cutting steel rebar with an angle grinder with sparks flying as the fabrication of beam cages proceeds alongside the timber formwork.

Beam Rebar Setup in Shutter

Fabricated steel beam cages set up and wired along the perimeter of the timber shutter formwork bed at the SQ fireplace area.

Resident Cats Feline Reunion

All three resident cats—Mocha, Reo, and Aiko—peacefully eating together from stainless steel bowls after Mocha's safe return.

Domestic Pet Care — Ajabu Feeding

Ajabu the Golden Retriever enjoying his nutritious meal indoors on the tiled floor at Kabete Residence.

Ajabu Outdoor Leashed Walk

Ajabu exploring the compound grounds on a secure lead during daily outdoor exercise and walking routine.



Driveway Exercise Routine

Ajabu walking along the paved driveway grounds under handler guidance during outdoor exercise.

Garden Perimeter Walk

Ajabu investigating garden greenery and flower borders along the residence wall during outdoor exercise.

D

Compiled by Dennis

Daily Operations Reporting • Wednesday, 21st October 2026