

You only need the adaptor board if you using the old PCB.



You need to add 5v jumper on the SD Drive board

Then



Solder pin header in at top of adaptor board and remove plastic base from header pins.



Insert the pins through the holes in the SD Drive board then solder to SD Drive board.

Install side port edge card connector at bottom of adaptor.