

5 – MATING AND ASSEMBLY


By following this tutorial, you will learn how to:


- 1. Insert and move parts in an assembly
- 2. Use the Mate tool in assembly
- 3. Create an exploded view on assembly
- 4. Animate explode and collapse an assembly

For the purpose of this handout, please download "5-1.SLDPRT" and "5-2.SLDPRT" to be used in this tutorial.









5	Click part 5-2 and drag to move the part.	
6	Click on the Mate button. Select the outside top face of part 5-2 as shown. Select the inside top face of part 5-1 as shown. Click OK to confirm.	
7	Select the shoulder on part 5-2 as shown.	
8	Click the corresponding surface on part 5-1 as shown. Click OK to confirm.	

