R380

History

R380A: (NA/Y/Y/R/G) 13L-LED117-00,R25=150ohm
R380B: (NA/G/Y/R/G) 13L-LED123-00,R25=150ohm
R380C: (NA/R/G/Y/B) 13L-LED126-00,R25=5.6K.

AEWIN Technologies Co., Ltd.

Title: INDEX		
Size: B	Document Number: 5035-ZB R380	Rev: A0
Date: Tuesday, September 12, 2017	Sheet 1 of 4	

BLOCK DIAGRAM





AEWIN Technologies Co., Ltd.		
Title: BLOCK DIAGRAM		
Size: B	Document Number: 5035-ZB R380	Rev: A0
Date: Tuesday, September 12, 2017	Sheet 2 of 4	







AEWIN Technologies Co., Ltd.

Title	COM/PRT/KB/MS/GPO		
Size A	Document Number 5035-ZB R380		Rev A0
Date: Tuesday, September 12, 2017		Sheet 3 of 4	

沉板式 有正凸 RJ45 P/N#44L-A08F08-U9



LINK/ACTIVITY LED (LEFT)	
LINK	GREEN
ACTIVITY	BLINK

SPEED LED (RIGHT)	
10 Mbps	OFF
100 Mbps	YELLOW
1000 Mbps	GREEN



LAN1

沉板式 有正凸 RJ45 P/N#44L-A08F08-U9



LINK/ACTIVITY LED (LEFT)	
LINK	GREEN
ACTIVITY	BLINK

SPEED LED (RIGHT)	
10 Mbps	OFF
100 Mbps	YELLOW
1000 Mbps	GREEN



LAN2

USB*2PORT



TOPSEC R342	Sangfor R372	AEWIN/ Leadsec/Venuc Tech R380
N/A	HA(GPO57)	N/A
GPO54#	BYPASS	GPO
GPO55	HDD	GPO
GPO56	ALARM	HDD
GPO57	PWR	PWR

AEWIN Default	Topsec	Leadsec / Venuc Tech	Sangfor
R380A	R342A		R372A
NA	NA	NA	HA (*GPO)
GPO	GPO	GPO	Bypass (*GPO)
GPO	GPO	GPO	Status (*HDD)
HDD LED	GPO	HDD LED	Alarm (*Control By COM2)
PWR LED	GPO	PWR LED	PWR LED

DSN ERROR :
DEFAULT
DTR PIN8
RI PIN7



LED

R380A: (NA/Y/Y/R/G) 13L-LED117-00
R380B: (NA/G/Y/R/G) 13L-LED123-00
R380C: (NA/R/G/Y/B) 13L-LED126-00





CONSOLE



SWITCH



AEWIN Technologies Co., Ltd.

Title	FRONT IO		
Size A3	Document Number 5035-ZB	R380	Rev A0
Date: Tuesday, September 12, 2017	Sheet 4 of 4		