



Street Manager Tips & Tricks: Section 81 process

- **1. HA** identifies defective apparatus
- 2. Records a S81 in SM selecting the SU the apparatus belongs to
- 3. SU acknowledges receipt of the S81
- 4. Investigates ownership of asset reported as defective
- 5. If it isn't the SU's asset, or it is not a valid s81, the SU will reject the S81 providing a reason.
- **6. HA** will review the rejected S81 and if agrees with the SU rejection the HA will **cancel** the S81. To reassign to another SU, a new S81 must be recorded and issued to the appropriate SU.
- 7. SU If it is the SU's asset and it is a valid S81, the SU will accept the S81
- 8. At the time of accepting the S81, the SU will indicate whether any remediation work will require a permit or not.
- 9. When the remediation works have been carried out, the SU will make an entry in the S81 record 'mark as fixed/actioned'. If a works record number and permit reference were required to undertake the works, then the Works Record Reference should be entered in the text box which opens when marking as fixed.
- **10. HA** will review all S81's which have been marked as fixed/actioned and once satisfied that the record can be closed, the S81 can be 'marked as resolved'.

S81 Inspections

HA's can also record/schedule S81 type inspections from the S81 works record, these can currently only be viewed by the SU or the HA in the S81 record - (bug raised 3/3/20)





Future expected improvements to SM

Re-assigning a S81 to a different SU without cancelling the original one

The ability for SU to create a permit application from the S81 works record, creating an auto-link to works undertaken to remediate the S81.

First, the S81 is created.

Status: Issued	
Works reference: FMS8118644815 Works location: PEGS LANE	
Works location: PEGS LANE	
Section 81 location	
USRN	12413456
Road/street	PEGS LANE
Area	Not provided
Road category	3
Location coordinates	532538.01 - 212118.31
ssuing authority	HERTFORDSHIRE COUNTY COUNCIL
Receiving organisation	THAMES WATER
Section 81 details Location area	Carriageway
Location description	county hall carpark exit
inspection date	02/03/2020
Гуре	Tee/valve/access covers
Severity	Low
Made safe by HA	Not required
Inspector name	Not provided
Inspector contact details	Not provided
Additional details	rocking manhole cover
ssue date: 02/03/2020 09:04	
S81 response	
Acknowledge	
() Accept	





Click on the Works reference.

Works record

Reference: BHS8114537153

SECTION B1 WORKS

Key details

USRN	7300139	
Road/Street	SNOWHILL COTTAGES	
Road category	4	
Location coordinates	497697.25 - 205417.51	
Highway authority	BUCKINGHAMSHIRE COUNTY COUNCIL	
Promoter organisation	THAMESWATER	
Location description	5	

Works history

View history

Date and time	Topic	Details Usernan	
24/01/2020 20:02	Section 81	Section 81 accepted with permitted works indicated	janet.chapman@thameswater.co.uk
23/01/2020 16:20	Section 81	Section 81 acknowledged	janet.chapman@thameswater.co.uk
23/01/2020 16:19	Section 81	Section 81 created	hauser1@thameswater.co.uk

Section 81

Issue date	Reference	Location	Severity	Status
23/01/2020 16:19	BHS8114537153-S81	5, SNOWHILL COTTAGES,	Low	Accepted

Inspections

Add an inspection

No inspections have been recorded Schedule inspection

Fixed penalty notices (FPN)

Issue an FPN

No FPNs issued

Additional files Add a file





4 Back

hauserl@thameswater.co.uk (Sign out)

What are the inspection details?	
Works reference: BHS8114537153 (opens in new tab) Works location: SNOWHILL COTTAGES	
Inspection type Live site Reinstatement Non compliance follow up Section 81 Inspection date and time Enter timings using a 24-hour time format Day Month Year Hour Minute Continue	
Add an inspection	hauser1@thameswater.co.uk (Sis
	hauserl@thameswater.co.uk (Sis
Add an inspection What are the inspection details? Works reference: BHSS114537153 (opens in new tab)	hauser1@thameswater.co.uk (Sis





Add an inspection

What are the additional inspection details?

Works location: SNOWHILL COTTAGES	
Inspector name (optional)	
Complete if you're not the inspector	
fred bloggs	
Additional comments (optional)	
Relevant information can include names and phone nui inspection	mbers of on-site staff involved in th
Testing scenario - Jan	
Schedule a reinspection?	
Yes No	
Reinspection type	
Live site	
Reinstatement	
Non compliance follow up	
Section 81	
Reinspection date and time	
Enter time using a 24-hour format	
Day Month Year	
24 03 2020 🛗	
Hour Minute	
Attach photo evidence	





vvorks recora

Reference: BHS8114537153

SECTION 81 WORKS

Key details

USRN	7300139	
Road/Street	SNOWHILL COTTAGES	
Road category	4	
Location coordinates	497697.25 - 205417.51	
Highway authority	BUCKINGHAMSHIRE COUNTY COUNCIL	
Promoter organisation	THAMES WATER	
Location description	5	

Works history View history

Date and time	Topic	Details	Username
03/03/2020 11:55	Inspection	Section 81 inspection added with outcome: Failed - low	hauser1@thameswater.co.uk
03/03/2020 11:55	Scheduled Inspection	Section 81 inspection scheduled	hauser1@thameswater.co.uk
24/01/2020 20:02	Section 81	Section 81 accepted with permitted works indicated	janet.chapman@thameswater.co.uk
23/01/2020 16:20	Section 81	Section 81 acknowledged	janet.chapman@thameswater.co.uk
23/01/2020 16:19	Section 81	Section 81 created	hauser1@thameswater.co.uk

Section 81

Issue date	Reference	Location	Severity	Status
23/01/202016:19	BHS8114537153-S81	5, SNOWHILL COTTAGES,	Low	Accepted

Inspections		Add an inspection	
Inspection date	Inspection type	Inspection outcome	
24/03/2020	(Scheduled) Section 81	Cancel	
03/03/202011:10	Section 81	Failed - low	





The view of the SU

Can only be seen when looking at the S81 works record – however until bug fixed will have to look at every s81 work record to see if any have been received.

If bug not remedied before go-live then workaround will have to be added where the HA will need to add a comment to say S81 inspection has been recorded.