

# Signature Floor Care System

#### **Products**



PRO STRIP™ **HEAVY DUTY STRIPPER** 




SIGNATURE\*\* **UHS FLOOR FINISH** 



ACCUMIX™ UHS **CLEANER** 




**ACCUMIX™** STIDE-CITRUS **NEUTRAL CLEANER** 



**AUTOSCRUBBER** 



SINGLE DISK MACHINE



**Equipment** 



Stripping: Black

**PADS** UHS Burnishing: ETC Gorilla "Lite" Daily Scrubbing: Red Deep Scrubbing: Blue or Green



**MOPS** 

**■ STRIPPING** 

2. Place "Caution

serviced.

3. Mix Pro Strip™

according to label directions.

4. Apply stripper.

Allow to penetrate

for approximately

10 minutes. Do not allow to dry.

Wet Floor" signs

and "Caution Tape"

around area to be

**Heavy-Duty Stripper** 

1. Dust mop entire floor.

Untreated dust mop, cotton mop for cleaning, rayon or rayon blend for applying finish.

## MIX AND USE IN WELL VENTILATED AREA - ALWAYS WEAR PERSONAL PROTECTIVE EQUIPMENT.

### Floor Maintenance Procedures

#### ■ NEW FLOORS - TWO(2) WEEKS PRIOR TO GRAND OPENING OR EXISTING FLOORS AFTER STRIPPING

#### Night 1

- 1. Thoroughly clean or strip floors.
- 2. Place "Caution Wet Floor" signs and "Caution Tape" around area to be serviced.
- 3. Apply three (3)





#### DO NOT BURNISH NEWLY APPLIED FLOOR FINISH FOR 24 HOURS.

#### Night 2

- 1. Dust mop floors.
- 2. Place "Caution Wet Floor" signs and "Caution Tape" around area to be serviced.
- 3. Scrub floors with auto-scrubber and RED PADS using AccuMix® UHS Cleaner.
- 4. Burnish floor.
- 5. Dust mop floor. 6. Apply three (3) medium coats

of Signature™



**DO NOT BURNISH NEWLY APPLIED** FLOOR FINISH FOR 24 HOURS.



#### **■ DAILY MAINTENANCE**

- 1. Dust mop floors.
- 2. Place "Caution Wet Floor" signs and "Caution Tape" around area to be serviced.
- Scrub floors with an autoscrubber and RED PADS using **AccuMix**® **UHS** Cleaner (mixed at 1 oz. per 8 gallons of cold water) or AccuMix® Stide— Citrus Neutral Cleaner (mixed at 1 oz. per 4 gallons of cold water). BURNISH
- Dust mop floor.

#### **■ MONTHLY MAINTENANCE**

#### **High Traffic Areas –** *Procedures*

- 1. Dust mop entire floor.
- 2. Place "Caution Wet Floor" signs and "Caution Tape" around area to be serviced.
- 3. Autoscrub entire floor using BLUE or GREEN PADS and AccuMix® UHS Cleaner (mixed at 2 oz. per 8 gallons of cold water) or AccuMix® Stide-Citrus Neutral Cleaner (mixed at 2 oz. per 4 gallons of cold water).
- 4. Damp mop High Traffic Areas with water.
- 5. Burnish all High Traffic Areas
- 6. Dust mop floor.
- 7. Apply two coats of Signature<sup>TM</sup> to the High Traffic Areas and allow to dry.
- DO NOT BURNISH NEWLY APPLIED FLOOR FINISH FOR 24 HOURS.

#### ■ BI-MONTHLY MAINTENANCE

- **Low Traffic Areas –** *Procedures*
- 1. Dust mop entire floor.
- 2. Place "Caution Wet Floor" signs and "Caution Tape" around area to be serviced. Autoscrub entire floor using BLUE or GREEN PADS and  $\textbf{AccuMix}^{\circledR}$
- UHS Cleaner (mixed at 2 oz. per 8 gallons of cold water) or AccuMix® Stide-Citrus Neutral Cleaner (mixed at 2 oz. per 4 gallons of cold water).
- 4. Damp mop Low Traffic Areas with water.
- 5. Burnish all Low Traffic Areas.
- 6. Dust mon floor
- 7. Apply one coat of Signature<sup>TM</sup> to the Low Traffic Areas and allow to dry. DO NOT BURNISH NEWLY APPLIED FLOOR FINISH FOR 24 HOURS.


# ■ SEMI-ANNUAL MAINTENANCE

#### **Restoration** – *Procedures*

- 2. Place "Caution Wet Floor" signs and "Caution Tape" around area to be serviced.
- 3. In a bucket, mix 2 oz. of AccuMix® UHS Cleaner per 5 gallons of cold water. Apply liberally to floor. 4. Using a Single disk machine, Restoration Scrub borders and
- edges using BLUE or GREEN PADS. 5. Pick up solution with autoscrubber
- area using BLUE or GREEN PADS.
- 6. Using the autoscrubber, Restoration Scrub the main traffic 7. Pick up solution with autoscrubber.
- 8. Damp mop floor with water.
- 9. Apply four coats of SignatureTM
- 10. Allow Signature™ to thoroughly dry in between coats.
- DO NOT BURNISH NEWLY APPLIED FLOOR FINISH FOR 24 HOURS.
























6. Scrub-rinse floor. Trail mop edges and rinse again.



7. Apply Signature™ procedures outlined under "Initial Start-Up."



DO NOT BURNISH NEWLY APPLIED FLOOR FINISH FOR 24 HOURS.

SAFETY IS IMPORTANT. ALWAYS USE THE RECOMMENDED SAFETY EQUIPMENT.

If you have any questions about floor care, please call the Johnson Diversey Technical Response Team Toll Free 1-800-558-2332



