


x-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C1 / 1 × 3




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

x-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C2 / 1 × 3




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

x-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C3 / 1 × 3



Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

x-carriage

210 × 199 × 6.35 mm • make 1 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

x-carriage

210 × 199 × 6.35 mm • make 1 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

y-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C1 / 1 × 3




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

y-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C2 / 1 × 3



Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

y-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C3 / 1 × 3



Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

y-carriage

210 × 199 × 6.35 mm • make 1 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

y-carriage

210 × 199 × 6.35 mm • make 1 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

z-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C1 / 1 × 3




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

z-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C2 / 1 × 3




Transfer catalog mounting holes from the received part.

 50 mm - measure before drilling

z-bed

450 × 199 × 6.35 mm • make 1 • tile R1 C3 / 1 × 3



Transfer catalog mounting holes from the received part.

 50 mm - measure before drilling

z-carriage

210 × 199 × 6.35 mm • make 1 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

z-carriage

210 × 199 × 6.35 mm • make 1 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

force-gauge-backing

70 × 110 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

installed-Z-gauge-back

70 × 160 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

shaft-capture-interface

100 × 60 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

shaft-capture-bridge

100 × 60 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

capture-catch-upper

120 × 80 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

installed-Z-load-platen

60 × 40 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

test-output-bridge

140 × 40 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

test-output-arm

70 × 25 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

drive-test-foot

120 × 80 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

force-test-platen

120 × 80 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

torque-redirect-bracket

60 × 40 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

yaw-head-adapter

120 × 120 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

 50 mm - measure before drilling

z-head-diagonal

275 × 25 × 6.35 mm • make 1 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

z-head-diagonal

275 × 25 × 6.35 mm • make 1 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

rotator-platform

325 × 300 × 6.35 mm • make 1 • tile R1 C1 / 2 × 2




Transfer catalog mounting holes from the received part.

 50 mm - measure before drilling

rotator-platform

325 × 300 × 6.35 mm • make 1 • tile R1 C2 / 2 × 2




Transfer catalog mounting holes from the received part.

 50 mm - measure before drilling

rotator-platform

325 × 300 × 6.35 mm • make 1 • tile R2 C1 / 2 × 2




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

rotator-platform

325 × 300 × 6.35 mm • make 1 • tile R2 C2 / 2 × 2




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

yaw-bearing-back

180 × 90 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

yaw-crossbar

100 × 380 × 6.35 mm • make 1 • tile R1 C1 / 2 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

yaw-crossbar

100 × 380 × 6.35 mm • make 1 • tile R2 C1 / 2 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

yaw-side

100 × 180 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

pitch-bearing-foot

90 × 60 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

pitch-side

280 × 100 × 6.35 mm • make 2 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

pitch-side

280 × 100 × 6.35 mm • make 2 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

pitch-rear-crossbar

190 × 40 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

roll-bearing-foot

150 × 120 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

roll-cradle-side

216 × 60 × 6.35 mm • make 2 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

roll-cradle-side

216 × 60 × 6.35 mm • make 2 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

roll-cradle-back

120 × 70 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

gun-jaw

25 × 130 × 6.35 mm • make 4 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

service-load-jaw

35 × 160 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

angular-lever

190 × 50 × 6.35 mm • make 3 • tile R1 C1 / 1 × 1


			

Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

drive-bulkhead

38 × 60 × 6.35 mm • make 6 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

linear-drive-support

150 × 150 × 6.35 mm • make 6 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

motor-support-leg

100 × 25 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

thrust-support-leg

42.65 × 38 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

nut-face

46 × 38 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

force-link-end

110 × 38 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

force-link-shuttle

110 × 38 × 6.35 mm • make 6 • tile R1 C1 / 1 × 1



Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

force-link-shoulder

110 × 38 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

force-shuttle-boss

25.4 × 25.4 × 7.35 mm • make 28 • tile R1 C1 / 1 × 1




INWARD FACE: counterbore Ø12.1 × 2 mm deep; Ø8.5 passes through.

50 mm - measure before drilling

force-output-ear

60 × 40 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

overload-switch-tab

60 × 25 × 6.35 mm • make 6 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

 50 mm - measure before drilling

friction-spring-seat

38 × 60 × 6.35 mm • make 3 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

angular-clevis-cheek

80 × 40 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

trunnion-inner-ear

40 × 40 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

limit-stop

40 × 30 × 6.35 mm • make 12 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

bench-tether-anchor

60 × 30 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

brake-torque-lever

220 × 30 × 6.35 mm • make 1 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

brake-torque-lever

220 × 30 × 6.35 mm • make 1 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

angular-load-lever

220 × 30 × 6.35 mm • make 1 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

angular-load-lever

220 × 30 × 6.35 mm • make 1 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

hub-proof-lever

300 × 30 × 6.35 mm • make 1 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

hub-proof-lever

300 × 30 × 6.35 mm • make 1 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

hub-proof-load-saddle

40 × 50 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

 50 mm - measure before drilling

yaw-base-web

230 × 250 × 6.35 mm • make 2 • tile R1 C1 / 2 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

yaw-base-web

230 × 250 × 6.35 mm • make 2 • tile R1 C2 / 2 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

yaw-base-web

230 × 250 × 6.35 mm • make 2 • tile R2 C1 / 2 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

yaw-base-web

230 × 250 × 6.35 mm • make 2 • tile R2 C2 / 2 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

pitch-base-web

280 × 100 × 6.35 mm • make 2 • tile R1 C1 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

pitch-base-web

280 × 100 × 6.35 mm • make 2 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

roll-base-web

220 × 203.1 × 6.35 mm • make 2 • tile R1 C1 / 1 × 2



Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

roll-base-web

220 × 203.1 × 6.35 mm • make 2 • tile R1 C2 / 1 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

roll-base-anchor

160 × 190 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

angular-output-bridge

100 × 60 × 6.35 mm • make 3 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

crash-pod-end

40 × 80 × 6.35 mm • make 4 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

crash-pod-shoulder

40 × 40 × 6.35 mm • make 4 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

crash-pod-shuttle

40 × 40 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

crash-carrier-left

200 × 60 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

crash-carrier-right

200 × 60 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

 50 mm - measure before drilling

crash-magnet-back

120 × 90 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

gun-release-tray

200 × 80 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

gun-release-back

120 × 70 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

crash-output-wall

100 × 70 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

crash-ground-crossbar

200 × 40 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1



Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

vee-seat-keeper

24 × 8 × 6.35 mm • make 6 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

nozzle-test-fork-arm

210 × 30 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

nozzle-test-bridge

180 × 30 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

crash-guide-block

25.4 × 25.4 × 15 mm • make 4 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

 50 mm - measure before drilling

shaft-hub-XY-mounting-projection

38.1 × 38.1 × 25 mm • make 7 • tile R1 C1 / 1 × 1




HUB BROAD FACE: ream Ø12; saw 1.5 mm split slit 2 mm into bore. Shaft stays plain.

50 mm - measure before drilling

shaft-hub-YZ-clamp-projection

38.1 × 25 × 38.1 mm • make 7 • tile R1 C1 / 1 × 1




HUB SIDE FACE: Y horizontal / Z from bottom; drill both Ø4.2 bores along X.

50 mm - measure before drilling

shaft-end-pilot-projection

12 × 12 × 16 mm • make 8 • tile R1 C1 / 1 × 1




AXIAL END: Ø4.2 pilot 16 mm deep; tap M5 × 0.8, usable full thread ≈10 mm.

50 mm - measure before drilling

proof-gauge-quill-cap-upright-projection

70 × 50.8 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

50 mm - measure before drilling

linear-stop-angle-foot-projection

50.8 × 40 × 6.35 mm • make 6 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

50 mm - measure before drilling

linear-stop-angle-upright-projection

40 × 50.8 × 6.35 mm • make 6 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

50 mm - measure before drilling

guard-thrust-angle-minus-foot-projection

25.4 × 25.4 × 3.175 mm • make 6 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

 50 mm - measure before drilling

guard-thrust-angle-minus-upright-projection

25.4 × 25.4 × 3.175 mm • make 6 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

 50 mm - measure before drilling

guard-thrust-angle-plus-foot-projection

25.4 × 25.4 × 3.175 mm • make 6 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

50 mm - measure before drilling

guard-thrust-angle-plus-upright-projection

25.4 × 25.4 × 3.175 mm • make 6 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

50 mm - measure before drilling

installed-Z-jack-angle-foot-projection

50.8 × 40 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

 50 mm - measure before drilling

installed-Z-jack-angle-upright-projection

40 × 50.8 × 6.35 mm • make 1 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

50 mm - measure before drilling

friction-washer-drilling-projection

37 × 37 × 3 mm • make 3 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: bought steel washer; drill only added guide/keeper holes.

50 mm - measure before drilling

crash-striker-drilling-projection

25 × 25 × 2 mm • make 3 • tile R1 C1 / 1 × 1




DRILLING PROJECTION: bought steel washer; drill only added guide/keeper holes.

50 mm - measure before drilling

camera-fixed-plate

400 × 300 × 6.35 mm • make 2 • tile R1 C1 / 2 × 2




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

camera-fixed-plate

400 × 300 × 6.35 mm • make 2 • tile R1 C2 / 2 × 2




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

camera-fixed-plate

400 × 300 × 6.35 mm • make 2 • tile R2 C1 / 2 × 2




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

camera-fixed-plate

400 × 300 × 6.35 mm • make 2 • tile R2 C2 / 2 × 2




Transfer catalog mounting holes from the received part.

50 mm - measure before drilling

camera-carriage-plate

300 × 300 × 6.35 mm • make 2 • tile R1 C1 / 2 × 2



Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

camera-carriage-plate

300 × 300 × 6.35 mm • make 2 • tile R1 C2 / 2 × 2



Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

camera-carriage-plate

300 × 300 × 6.35 mm • make 2 • tile R2 C1 / 2 × 2




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

camera-carriage-plate

300 × 300 × 6.35 mm • make 2 • tile R2 C2 / 2 × 2



Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

lens-upright

100 × 200 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1




Hole diameters and blank dimensions are in the fabrication manifest.

50 mm - measure before drilling

lens-angle-foot-projection

50.8 × 80 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1



DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

50 mm - measure before drilling

lens-angle-upright-projection

80 × 50.8 × 6.35 mm • make 2 • tile R1 C1 / 1 × 1

DRILLING PROJECTION: keep the angle intact; STEP governs the 3D part.

