FORMAT		00000	04	00	45	7
FORMAT		OPCODE	31 24 :		T	7 0
0 0	0 0		OPCODE	DEST	SRC A	SRC B
	10		OPCODE	DEST	IMM	SRC B
	11		OPCODE	DEST	IMM	IMM
			OI GODE	DEGI	HAIIAI	HAIM
		0000	ADD			
		0001	SUB			
		0100	AND			
		0101	OR			
		0110	XOR			
		0111	XNOR			
	l					
0 1	0 0		OPCODE	DEST	SRC A	SRC B
	0 1		OPCODE	DEST	SRC A	IMM
	1 0		OPCODE	DEST	IMM	SRC B
	11		OPCODE	DEST	IMM	IMM
		ı				
		0000	LOAD BIT			
		0 0 0 1	TEST BIT			
	·					
		1110	SWAP BIT			
		1111	SWAP			
	·					
	1					
10			OPCODE	DEST SRC	IMM	
	00000		LOAD LOW			
		0 0 0 0 1	LOAD HIGH			
]		ODCODE	OOND 2D2	25	4 DDDC00
1 1	,	00000	OPCODE	COND SRC	BRANCH ADDRESS	
	000000		== 0			
	0 0 0 0 0 1		!= 0			
	000010		> 0			
		000011	< 0			
		000100	>= 0			
		000101	<= 0			
	,	100000	ALWAYS			
		10000	ALWAIS			