


Ref no:	Module 2	Calders & Grandidge	
Compiled By: D. Losty	Product & Stock Labelling		Revision 3
Effective Date: Mar 2020			Revision Date: Aug 2020

1 Receipt & Inspection of Consignment



Ref no:	Module 2	Calders & Grandidge	
Compiled By: D. Losty	Product & Stock Labelling	Revision 3	
Effective Date: Mar 2020		Revision Date: Aug 2020	

2. Attaching Labels – General Requirements

- 1 You must position all labels on the ends of the packs (or on the butts of poles), to allow for counting of product whilst in storage locations (both raw and treated).
- 2 When treated product is to be stored in block stacks, you must ensure that the label that you attach remains visible when it is in the storage location. If this is not the case, you must attach a further label which will be visible.
- 3 When attaching a label, you must ensure that sufficient staples are used to prevent the label from detaching from the product during high winds, handling and transportation.

3 Labelling

- 1 It is vital (for the purposes of charge booking, stock management, accurate consignments etc.) that you accurately label all products.
- 2 You must count all packs that arrive on site and label them accurately, during the unloading process and prior to storage and you must only use labels in the approved format for this purpose. (See examples below.)
- 3 This label format may be pre-printed or it may be required to be completed by you, manually.
- 4 There are three types of approved labels:
 - a) **Raw Stock Labels** (These are 1-part labels, showing number of pieces, Chain of Custody information and a description of the product)
 - b) **Green Treated Stock Labels** (These are 2-part labels, showing number of pieces, Chain of Custody information, a description of the product, the Use Class, the date of treatment and the treatment charge number. An additional label is printed off with these labels and the additional label provides Biocidal Product information [in this case for AC500])
 - c) **Creosote Treated Stock Labels** (These are 2-part labels, showing number of pieces, Chain of Custody information, a description of the product, the Use Class, the date of treatment and the treatment charge number. An additional label is printed off with these labels and the additional label provides Biocidal Product information [in this case for creosote])


Ref no:	Module 2	Calders & Grandidge	
Compiled By: D. Losty	Product & Stock Labelling	Revision 3	
Effective Date: Mar 2020		Revision Date: Aug 2020	

4 Example Labels

4.1 Raw Stock Labels

- The label below is a **fully completed label** (excluding charge number) that has been obtained from the labelling computer. You can see that fields such as FSC/PEFC product description, are already completed. These labels will be used where all product details are known prior to arrival of the vehicle.

Note: Where this is the case, you must still verify that the product matches the label that you are about to attach.



Mixed Sources: Product group from well managed forests and other controlled sources Cert no. TT-COC1098. LICENSE NUMBER C02248

PEFC ☐ FSC ☒

Use Class

3	30
4	15

105 Pcs.


1.8x75/100

CHG.: _____

02-2020

- The label below is a **partially completed label** (excluding charge number) showing only the product description. Where this label is used you must complete the missing fields eg. FSC/PEFC, before attaching. These labels will be used where only some of the product details (or stock products) are known prior to arrival of the vehicle.

Note: Where this is the case, you must still verify that the product matches the label that you are about to attach.



Mixed Sources: Product group from well managed forests and other controlled sources Cert no. TT-COC1098. LICENSE NUMBER C02248

PEFC ☐ FSC ☐

Use Class

3	30
4	15

Pcs.

1.8x75/100

CHG.: _____

02-2020

- The label below is an **uncompleted blank label** to be completed on arrival of timber, where none of the details regarding product description, quantity etc. are known in advance.

Note: You must take great care to ensure that the details that you are manually recording on the label precisely match the details of the physical product.

Ref no:	Module 2	Calders & Grandidge	
Compiled By: D. Losty	Product & Stock Labelling		Revision 3
Effective Date: Mar 2020			Revision Date: Aug 2020

		Mixed Sources: Product group from well managed forests and other controlled sources Cert no. TT-COC1098. LICENSE NUMBER C02248	
		Use Class	
		3	30
		4	15
	Pcs.		
CHG.: _____			02-2020

4.2 Treated Stock Labels

4.2.1 Creosote Treated Stock

- 1 In the case of creosote treated products you must:
 - a) Obtain details of the charge number from the charge loading sheet/treatment plant operator (*except poles*).
 - b) Enter the charge number onto the appropriate treated product label (a two part label containing biocidal information for creosote) (*except poles*).
 - c) Enter the remaining outstanding details for example, PEFC/FSC, Use Class, description and quantity (*except poles*).

Example creosote treated stock label

• Creosote preserved wood is a "treated article" which incorporates biocidal products. • Wood correctly preserved with creosote is protected against wood destroying insects and wood rotting fungi. • Contains: creosote and creosote constituents including polycyclic aromatic hydrocarbons (PAH), Benzo(A)pyrene and phenolic compounds. • Wear gloves when handling treated wood. • Do not burn preserved wood. • Wear a dust mask and goggles when cutting or sanding wood. • Preservative may migrate from the treated wood into soil/water. • Wash exposed skin thoroughly. • Dispose of waste responsibly. • Wash work clothes separately from other clothing before re-use. • Do not use where preserved wood may contact drinking water. • Do not use for mulch. • Only use treated wood that is not exuding creosote (bleeding). • Do not use for interior applications. • Disposal Recommendations: Preserved wood must be disposed of as controlled waste accordance with National and Regional regulations. • Post-treatment operations such as cutting, drilling etc. will render the treatment ineffective in those areas of the timber. • In the event of a claim the end tag, a sample of the failed product and proof of purchase must be supplied. • For additional information, please visit www.caldersandgrandidge.com.	<table border="1"> <tr> <td></td> <td></td> <td>Mixed Sources: Product group from well managed forests and other controlled sources Cert no. TT-COC1098. LICENSE NUMBER C02248</td> <td></td> </tr> <tr> <td></td> <td>☒</td> <td>Use Class</td> <td></td> </tr> <tr> <td>72</td> <td></td> <td>3</td> <td>30</td> </tr> <tr> <td>Pcs.</td> <td>☒</td> <td>4</td> <td>15</td> </tr> <tr> <td colspan="2">1.8x100/125</td> <td colspan="2"></td> </tr> <tr> <td colspan="2">CHG.:_27050_____</td> <td colspan="2">02-2020</td> </tr> </table>			Mixed Sources: Product group from well managed forests and other controlled sources Cert no. TT-COC1098. LICENSE NUMBER C02248			☒	Use Class		72		3	30	Pcs.	☒	4	15	1.8x100/125				CHG.:_27050_____		02-2020	
		Mixed Sources: Product group from well managed forests and other controlled sources Cert no. TT-COC1098. LICENSE NUMBER C02248																							
	☒	Use Class																							
72		3	30																						
Pcs.	☒	4	15																						
1.8x100/125																									
CHG.:_27050_____		02-2020																							

- d) Print sufficient labels for all units listed on the charge sheet
- e) Attach the labels appropriately and securely
- f) Properly complete all of the required fields on the charge loading sheet, sign the sheet and scan it to 'STOCK'
- g) Where there is an inaccuracy with the charge loading sheet, you must update the charge

Ref no:	Module 2	Calders & Grandidge	
Compiled By: D. Losty	Product & Stock Labelling		Revision 3
Effective Date: Mar 2020			Revision Date: Aug 2020

loading sheet with the correct information, sign the sheet and scan it to 'STOCK'

4.2.2 Green Treated Stock

- 2 In the case of green treated products, the original label (where attached) may be re-used for description, quantity etc. Where this is the case, the treatment plant operator will manually endorse the attached labels with details of the charge number and use class.
- 3 Where all products on a charge are appropriately labelled, you must:
 - a) Obtain biocidal product labels

Example Biocidal Label for Green Treated Products

† Celcure AC-500 preserved wood is a "treated article" which incorporates biocidal products. • Wood correctly preserved with Celcure AC-500 is protected against wood destroying insects and wood rotting fungi. • Contains: Basic copper carbonate (Copper (II) carbonate - Copper (II) hydroxide (1:1)), Boric acid, Benzalkonium chloride. • Wear gloves when handling freshly treated wood. • Do not burn preserved wood. • Wear a dust mask and goggles when processing wood. • Preservative may migrate from the treated wood into soil/water. • Wash exposed skin thoroughly. • Wash work clothes separately from other clothing. • Do not use where preserved wood may contact drinking water, except incidental contact such as fresh water docks and bridges. • Do not use if the preservative may become a component of food, animal feed, or beehives. • Do not use for mulch. • Only use treated wood that is clean and free of surface residue. • Do not use in contact with aluminium. • For interior applications, allow to dry before covering or enclosing. • Preserved wood must be disposed of in accordance with National and Regional regulations. • For additional finishing follow the manufacturer's instructions. • Apply finishing product to a test area first. • Some metals may corrode when in contact with treated wood. Follow manufacturer recommendations • To remove mould from treated wood, allow to dry and use mild soap and water. • For claims, the end tag, a sample of the failed product and proof of purchase must be supplied. • Additional Information: www.osmose-europe.com

- b) Attach the biocidal product label to the treated pack or product in accordance with your training.
- 4 Where any product or pack on a charge does not contain a product description label, you must:
 - a) Obtain a product description label that includes the biocidal product label (You must also enter the charge number onto this label) (*except poles*).

Example Product Description & Biocidal Label

• Celcure AC-500 preserved wood is a "treated article" which incorporates biocidal products. • Wood correctly preserved with Celcure AC-500 is protected against wood destroying insects and wood rotting fungi. • Contains: Basic copper carbonate (Copper (II) carbonate - Copper (II) hydroxide (1:1)), Boric acid, Benzalkonium chloride. • Wear gloves when handling freshly treated wood. • Do not burn preserved wood. • Wear a dust mask and goggles when processing wood. • Preservative may migrate from the treated wood into soil/water. • Wash exposed skin thoroughly. • Wash work clothes separately from other clothing. • Do not use where preserved wood may contact drinking water, except incidental contact such as fresh water docks and bridges. • Do not use if the preservative may become a component of food, animal feed, or beehives. • Do not use for mulch. • Only use treated wood that is clean and free of surface residue. • Do not use in contact with aluminium. • For interior applications, allow to dry before covering or enclosing. • Preserved wood must be disposed of in accordance with National and Regional regulations. • For additional finishing follow the manufacturer's instructions. • Apply finishing product to a test area first. • Some metals may corrode when in contact with treated wood. Follow manufacturer recommendations • To remove mould from treated wood, allow to dry and use mild soap and water. • For claims, the end tag, a sample of the failed product and proof of purchase must be supplied. • Additional information: www.osmose-europe.com	 		Mixed Sources: Product group from well managed forests and other controlled sources Cert no. TT-COC1098. LICENSE NUMBER C02248						
	Use Class <table border="1"> <tr> <td>3</td> <td></td> <td>30</td> <td>✓</td> </tr> <tr> <td>4</td> <td>✓</td> <td>15</td> <td></td> </tr> </table>		3			30	✓	4	✓
3		30	✓						
4	✓	15							
105 Pcs.		1.8x75/100							
CHG.:_2000405__		02-2020							

Ref no:	Module 2	Calders & Grandidge	
Compiled By: D. Losty	Product & Stock Labelling	Revision 3	
Effective Date: Mar 2020		Revision Date: Aug 2020	

- b) Attach these labels to the treated pack or product in accordance with your training.
- 5 Where any product description labels have not been properly endorsed by the treatment plant operator (for example, use class not ticked, charge number missing) you must bring this to the attention of the plant operator and ensure that this fault is rectified before proceeding to unload.
- 6 During labelling and unloading operations, you must:
- Attach the labels appropriately and securely.
 - Properly complete all of the required fields on the charge loading sheet, sign the sheet and scan it to 'STOCK'
 - Where there is an inaccuracy with the charge loading sheet, you must update the charge loading sheet with the correct information, sign the sheet and scan it to 'STOCK'

4.2.3 Defective Stock

- 7 If you identify any defective product, you must securely staple a white "DEFECTIVE PRODUCT" label to the product to prevent it being accidentally loaded or used. These are large labels and you **must securely staple the label at all 4 corners**.

Example Defective Product Label



5 Non-conforming Stock



(Example non-conforming stock label)

- 5.1 You must securely staple a yellow label to any product that is found to be non-conforming. The meaning of the NCR codes is as follows:
- Number only – Product is defective – move to quarantine area and inform Production Supervisor

Ref no:	Module 2	Calders & Grandidge	
Compiled By: D. Losty	Product & Stock Labelling	Revision 3	
Effective Date: Mar 2020		Revision Date: Aug 2020	

- Number followed by letter 'S' in brackets – Product is not defective – return to storage stack (generally as a result of a picking error or a change of customer requirements)
- Number followed by letter 'B' in brackets – Product is bleeding – segregate for a wash charge (for these products, you must also securely attach a blank red label to indicate that the product needs to be washed)

5.2 When products are returned as a result of a customer complaint you must keep them in quarantine until an investigation has been completed.

6 Picking & Loading

- 6.1 You must never load any product or pack for despatch to a customer that does not have an accurate product description label and biocidal product directive label securely attached.
- 6.2 Where any product or pack does not have an accurate product description label and biocidal product directive label securely attached, you must source or request an appropriate replacement label.
- 6.4 If you are required to split a pack of products, you must:
- Use the uncompleted blank label as described in 4.1.3
 - Fill in the blank label with the precise details from the label that was already attached to the pack.
 - Do this for each part pack that is formed from the original full pack.

Documents Replaced by this Module

Document Ref. **Document Title**
None.

7. Revision Record

Issue	Date	Details
1	Mar 2020	Original document.
2	Jul 2020	Requirements for non-conforming product added.