




ESI Drawing No. 435004

Fig. 4 — Scarfing and drilling for terminal and section angle 'H' type supports