




Fig. 2 'H' pole member drilling, scarfing and marking
(ESI Drawing 432002)