




ESI Drawing No. 435003

Fig. 3 — Scarfing and drilling 'H' type intermediate supports

68/6622