

Item no	Quantity lph 3ph		Drawing/ Schedule Ref.	Description
001	00	06	04-102-9	32 HD BARE COPPER
002	00	06	06-954-4	BONDING WASHER
<u>Reminder</u>				
003	00	00	06-950-2	12MM WASHERS
004	00	00	11-850-3	40 X 4 STAPLES
005	00	00	G6-S16	ADD. BONDING WASHERS (COASTAL)

Southern Electricity
 Component Schedule for Drawing Ref:
 App by R. C. NEWMAN
 Issue 1 Date NOVEMBER 86

BONDING KIT DRG REF A2008-1

E2008