

Item no	Quantity lph 3ph		Drawing/ Schedule Ref.	Description
001	01	00	96-214-2	SHACKLE (STEEL TOWER LINES)
002	01	00	19-310-4	LINK (ST LINE)
			<u>Reminder</u>	
003	00	00	G2-S58	AGS REPAIR UNIT (ST LINES)
004	00	00	G2-S64	ARMOUR SPLICE TO G2-S58

Southern Electricity
 Component Schedule for Drawing Ref:
 App by R. C. NEWMAN
 Issue 1 Date NOVEMBER 86

EARTH WIRE REPAIR SUSP. ASS.

A5003

