

Item no	Quantity lph	Quantity 3ph	Drawing/ Schedule Ref.	Description
001	00	02	17-513-9	INTERMEDIATE X-ARM HEAVY
002	00	02	19-234-9	LINE PLATE
003	00	04	06-908-1	X-ARM STRUT HEAVY
004	00	03	17-546-9	LINE POST INSULATOR 33KV
005	00	01	17-649-9	INSULATOR STOOL (ESI TYPE)
006	00	01	06-743-2	DANGER PLATE
007	00	14	06-085-9	M20 X 45 BOLT & NUT
008	00	01	G701	CIRCUIT IDENT PLATES TO G7-S4
<u>Decision</u>				
009	00	02	G6-S11	BOLTS TO G6-S11
010	00	03	G2-S34	33KV DISTRIBUTION TIES
011	00	01	A2004	33KV SP DRILLING DETAILS COAST
<u>Reminder</u>				
012	00	00	02-330-0	DENSO PASTE
013	00	00	11-669-5	DRIVE NAILS
014	00	00	11-899-8	PLASTIC WASHERS
015	00	00	G7-S1	POLE NUMBER PLATES

Southern Electricity
 Component Schedule for Drawing Ref:
 App by R. C. NEWMAN
 Issue 1 Date NOVEMBER 86

33KV INTER.SP.DOUBLE CROSSARM

A2005