Print Preview

Pending

```
DP515753
Deviation - Prototype • CRBU::: Churchill NG-1RU.
this deviation is for P4C-A2 HBM XR/SONIC
MB: any PCB vendor is fine
CPU: if WUS is 28-14428-05_02 from a recent batch you just receive, please use that. Make sure WUS is rev 02
28-14484-04: use ISU
28-14431-05: if only have GCE, then will have to build with GCE. If there is other vendor with 05_02 then use that
instead of GCE
BOM Deviation
HBM XR
73-20364-02_12
  17-15785-05. U72.
  17-15786-04. U1_C2.
  17-15787-01. U1_C0,U1_C1
  17-15788-04. U1_G0
  17-15905-01, U181 TM
  17-16082-02. J1C_U1_G1
  17-16083-01. J1C_U1_G2
  17-16084-01. J1C_U1_3V3L,J1C_U1_3V3R
  17-16398-01. U4_C2 to use raw part (raw material CIS-16-4194-01), and this material is non traceable.
PCAMP to use
  61-105254-02 A0. MB HBM XR
73-19882-05 10
  17-15977-06. U34_C, U36_C. (program at Centec with v0.17 file. 4x part. micron only. dont mix vendor). please
mark it so that dont mix up with XR/SONIC
  17-15888-05. U4
  17-16222-01. U4_M1
  17-16223-01. U5_M2
  17-15879-02. U92_C. (see if can program with -03 with dediprog. will need 4x part for XR/SONIC build)
  17-15890-02. U2_I2
  17-15769-02. U40
  17-15891-05. U1
  1. also there will be new SMT stencil to use to bridge U51_C.13 and U51_C.14
  2. add 0 ohm resistor to BOM CPN (12-206780-01 / 12-5663-01) to U8.W19 and U8.Y19 at U8 BGA
location. Please make sure have pick and place process ready for this
 3. depop R1261 (12-2905-02) from BOM kitting before SMT
PCAMAP to use
  61-104347-05 A0 CPU XR
73-19953-04_04. (I/O Board)
73-19884-05 06. (PDB Board)
  61-104443-04_A0 I/O Board
  61-104349-05 A0 PDB board
Compliance label to use:
47-107874-01 rev. -A0
CLEI Information to use:
CLEI Code
               : CMM6210ARA
                : 476969
ECI Number
HBM SONIC
```

https://www-pdmprd.cisco.com/Agile/PCMServlet

73-20560-01 Rev -09

6/7/2021 Print Preview

```
17-15785-05. U72.
   17-15786-04. U1 C2.
   17-15787-01. U1 C0,U1 C1
   17-15788-04. U1_G0
   17-15905-01. U181_TM
   17-16082-02. J1C_U1_G1
   17-16083-01. J1C_U1_G2
   17-16084-01. J1C_U1_3V3L,J1C_U1_3V3R
   17-16398-01. U4_C2 to use raw part (raw material CIS-16-4194-01), and this material is non traceable.
PCAMAP to use
  61-105593-01_A0 MB HBM sonic
73-20559-01 Rev -09
  17-16222-01. U4 M1
  17-16223-01. U5_M2
  17-15879-02. U92_C. (see if can program with -03 with dediprog. already done 4x above)
  17-15890-02. U2 I2
  17-15891-05. U1
  17-16264-02. U34_C, U36_C. (need FGU to program with dediprog with version v0.217. 4x quantity. micron only
dont mix vendor. please mark it so dont mix up between xr/sonic)
  17-16314-01. U4
  17-15769-02. U40
  1. also there will be new SMT stencil to use to bridge U51 C.13 and U51 C.14
  2. add 0 ohm resistor to BOM CPN (12-206780-01 or 12-5663-01) to U8.W19 and U8.Y19 at U8 BGA
location. Please make sure have pick and place process ready for this
  3. depop R1261 (12-2905-02). remove from BOM kitting before SMT
PCAMAP to use
```

61-105594-01_A0 CPU SONIC

Compliance label to use:

47-108026-01 rev. -A0

CLEI Information to use:

CLEI Code : CMM6310ARA ECI Number : 476971

Cover Page

Number: DP515753 Deviation Type: Deviation - Prototype Description of Change: CRBU::: Churchill NG-1RU.

this deviation is for P4C-A2 HBM XR/SONIC

MB: any PCB vendor is fine

CPU: if WUS is 28-14428-05_02 from a recent batch you just receive, please use

that. Make sure WUS is rev 02

28-14484-04: use ISU

28-14431-05: if only have GCE, then will have to build with GCE. If there is other vendor

with 05 02 then use that instead of GCE

BOM Deviation

HBM XR

73-20364-02_12

17-15785-05. U72. 17-15786-04. U1_C2 17-15787-01. U1_C0,U1_C1 Status: Pending

Reason For Change: temporary change for P4C HBM XR/SONIC and P1B MONO XR/SONIC

Workflow: Deviation - Prototype Originator: To, Kevin (kevinto)

Date Released: ******

Effective To:

```
17-15788-04. U1_G0
  17-15905-01. U181_TM
  17-16082-02. J1C U1 G1
  17-16083-01. J1C_U1_G2
  17-16084-01. J1C_U1_3V3L,J1C_U1_3V3R
  17-16398-01. U4_C2 to use raw part (raw material CIS-16-4194-01), and this material
is non traceable.
PCAMP to use
  61-105254-02_A0. MB HBM XR
73-19882-05_10
  17-15977-06. U34 C, U36 C. (program at Centec with v0.17 file. 4x part. micron
only. dont mix vendor). please mark it so that dont mix up with XR/SONIC
  17-15888-05. U4
  17-16222-01. U4 M1
  17-16223-01. U5_M2
  17-15879-02. U92_C. (see if can program with -03 with dediprog. will need 4x part for
XR/SONIC build)
  17-15890-02. U2_I2
  17-15769-02. U40
  17-15891-05. U1
  1. also there will be new SMT stencil to use to bridge U51_C.13 and U51_C.14
  2. add 0 ohm resistor to BOM CPN (12-206780-01 / 12-5663-01) to U8.W19 and
U8.Y19 at U8 BGA location. Please make sure have pick and place process ready for this
  3. depop R1261 (12-2905-02) from BOM kitting before SMT
PCAMAP to use
  61-104347-05_A0 CPU XR
73-19953-04_04. (I/O Board)
73-19884-05_06. (PDB Board)
  61-104443-04_A0 I/O Board
  61-104349-05_A0 PDB board
Compliance label to use:
47-107874-01 rev. -A0
CLEI Information to use:
CLEI Code
                : CMM6210ARA
ECI Number
                : 476969
HBM SONIC
73-20560-01 Rev -09
   17-15785-05. U72.
   17-15786-04. U1 C2.
   17-15787-01. U1_C0,U1_C1
   17-15788-04. U1_G0
   17-15905-01. U181_TM
   17-16082-02. J1C U1 G1
   17-16083-01. J1C_U1_G2
   17-16084-01. J1C_U1_3V3L,J1C_U1_3V3R
   17-16398-01. U4_C2 to use raw part (raw material CIS-16-4194-01), and this material
is non traceable.
PCAMAP to use
  61-105593-01_A0 MB HBM sonic
73-20559-01 Rev -09
  17-16222-01. U4_M1
  17-16223-01. U5_M2
  17-15879-02. U92_C. (see if can program with -03 with dediprog. already done 4x
```

6/7/2021 Print Preview

above)

17-15890-02. U2_I2

17-15891-05. U1

17-16264-02. U34_C, U36_C. (need FGU to program with dediprog with version v0.217. 4x quantity. micron only dont mix vendor. please mark it so dont mix up between xr/sonic)

17-16314-01. U4 17-15769-02. U40

1. also there will be new SMT stencil to use to bridge U51_C.13 and U51_C.14

2. add 0 ohm resistor to BOM CPN (12-206780-01 or 12-5663-01) to U8.W19 and

U8.Y19 at U8 BGA location. Please make sure have pick and place process ready for this

3. depop R1261 (12-2905-02). remove from BOM kitting before SMT

PCAMAP to use

61-105594-01_A0 CPU SONIC

Compliance label to use:

47-108026-01 rev. -A0

CLEI Information to use:

CLEI Code : CMM6310ARA

ECI Number : 476971

Reason Code: For temporary Manufacturing process change

Change Analyst: Change Analyst-Routing Group **Date Originated:** 06/02/2021 10:48:31 AM PDT

Final Complete Date: Effective From:

Page Two

Business Unit: CRBU

Visibility:

Marking Instructions: Please add the deviation label to the outside box sheet metal

Reject Reason History: Affected Items

Required Visibility: FLEX-GUAD-BV (FGU)

Extension / Re-extension Reason: Reject Reason:

Item Number	Item Description	Revision	LifeCycle Phase	Mass	Reliability Grade	L2 Use Condition	ERP Scheduling	Control Code	SuCM	Risk Rating	Risk Reason Code	Network Critical	Safety Critical	EMC Critical	NEBS Critical	Stan
73.19882.05	PCA, DBRD, NG2 1RU, CPU BOARD, Broadwell DE	-10	Prototype	No Privilege	Α	3	Success					Yes	No	Yes	No	
73-19953-04	PCA, DBRD, NG2 1RU, I/O	-04	Prototype	No Privilege	A	3	Success					Yes	No	Yes	No	
	PCA, MBRD, NG2 1RU, 2.5D GB, BASE BOARD, TI JMAC	-12	Prototype	No Privilege	A	3	Success	CN: Cisco Negotiated				Yes	No	Yes	No	

6/7/2021 Print Preview

Item Number	Item Description	Revision	LifeCycle Phase	Mass	Reliability Grade	L2 Use Condition	ERP Scheduling	Control Code	SuCM	Risk Rating	Risk Reason Code	Network Critical	Safety Critical	EMC Critical	NEBS Critical	Stan
/3-20559-01	PCA, DBRD, NG2 1RU, CPU BOARD, HBM Open PID	-09	Prototype	No Privilege	A	3	Success	CN: Cisco Negotiated				Yes	No	Yes	No	
73-20560-01	PCA, MBRD, NG2 1RU, HBM GB, BASE BOARD, OPEN PID	-09	Prototype	No Privilege	A	3	Success	CN: Cisco Negotiated				Yes	No	Yes	No	

Workflow

Status Code	Workflow Status	Reviewer Job Function	Reviewer	Action	Workflow	Req'd	Signoff User	Status Changed By	Local Client Time	Signoff Comments	Signoff Duration
Current Process	Pending				Deviation - Prototype						

Relationships

Criteria Met Name Description Current Status Rule Type
--

Attachments

Filename	File Description	File Size	File Type	Folder Number	Folder Description	Folder Version	Checkout User	Checkout Date	Modified Date	Last View Date	Label	Ch
BDXNS_10GBASET_NO_MNG_SDP_MODS_LAN0_2p00_800008D1_crc_fixed.bin		4,194,304	bin	FOLDER1424695		1				05/16/2021 11:57:07 AM PDT		
sfns-0-17-gef159d3-s.bin.signed (1).signed		16,777,216	signed	FOLDER1430846		1				06/02/2021 03:37:40 PM PDT		
osfns-0-217-gf344a22-sa.bin.signed		16,777,216	signed	FOLDER1430847		1				06/02/2021 03:39:21 PM PDT		
61-104443-04_A0 (3).doc		176,640	doc	FOLDER1431848		1				06/04/2021 01:45:59 PM PDT		
61-105594-01_A0 (2).doc		172,032	doc	FOLDER1431849		1				06/04/2021 01:46:00 PM PDT		
61-105593-01_A0 (2).doc		516,608	doc	FOLDER1431850		1			06/04/2021 01:46:01 PM PDT	06/04/2021 01:46:01 PM PDT		
61-105254-02_A0 (3).doc		517,120	doc	FOLDER1431851		1				06/04/2021 01:46:02 PM PDT		
61-104349-05_A0 (2).doc		171,008	doc	FOLDER1431852		1				06/04/2021 01:46:02 PM PDT		
61-104347-05_A0 (1).doc		171,520	doc	FOLDER1431853		1				06/04/2021 01:48:19 PM PDT		

History

Status	Next Status	Action	User	Group(s)	Local Client Time	Affected Object	Details	Comments	User(s) Notified	Find Number
Pending		User Defined Action	To, Kevin (kevinto)		06/07/2021 04:08:24 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			

6/7/2021 Print Preview

//2021	1		1	l	l_	l	Print Preview	I	1	1
Status	Next Status		User	Group(s)	Local Client Time	Affected Object	Details	Comments	User(s) Notified	Find Number
Pending		Print Tab	To, Kevin (kevinto)		06/04/2021 09:25:58 AM PDT		Cover Page;Page Two;Affected Items;Workflow;Relationships;Attachments;History;			
Pending		User Defined Action	To, Kevin (kevinto)		06/04/2021 09:25:46 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		Print Tab	To, Kevin (kevinto)		06/04/2021 09:17:49 AM PDT		Cover Page;Page Two;Affected Items;Workflow;Relationships;Attachments;History;			<u> </u>
Pending		Print Tab	To, Kevin (kevinto)		06/04/2021 09:17:46 AM PDT		Cover Page;Page Two;Affected Items;Workflow;Relationships;Attachments;History;			<u> </u>
Pending		User Defined Action	To, Kevin (kevinto)		06/04/2021 09:16:50 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		Print Tab	To, Kevin (kevinto)		06/04/2021 08:01:12 AM PDT		Cover Page;Page Two;Affected Items;Workflow;Relationships;Attachments;History;			
Pending		User Defined Action	Hoch, Jeff (jhoch)		06/04/2021 07:44:42 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	Hoch, Jeff (jhoch)		06/04/2021 07:44:05 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	Hoch, Jeff (jhoch)		06/04/2021 07:43:46 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	Hoch, Jeff (jhoch)		06/04/2021 07:42:44 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	Hoch, Jeff (jhoch)		06/04/2021 07:41:59 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		Add file attachment	To, Kevin (kevinto)		06/04/2021 06:48:20 AM PDT		FOLDER1431853 V 1 61-104347-05_A0 (1).doc			
Pending		Remove file attachment	To, Kevin (kevinto)		06/04/2021 06:47:32 AM PDT		FOLDER1431847 V 1 61-105594-01_A0 (3).doc			
Pending		Add file attachment	To, Kevin (kevinto)		06/04/2021 06:46:02 AM PDT		FOLDER1431852 V 1 61-104349-05_A0 (2).doc			
Pending		Add file attachment	To, Kevin (kevinto)		06/04/2021 06:46:02 AM PDT		FOLDER1431851 V 1 61-105254-02_A0 (3).doc			
Pending		Add file attachment	To, Kevin (kevinto)		06/04/2021 06:46:01 AM PDT		FOLDER1431850 V 1 61-105593-01_A0 (2).doc			
Pending		Add file attachment	To, Kevin (kevinto)		06/04/2021 06:46:00 AM PDT		FOLDER1431849 V 1 61-105594-01_A0 (2).doc			
Pending		Add file attachment	To, Kevin (kevinto)		06/04/2021 06:46:00 AM PDT		FOLDER1431848 V 1 61-104443-04_A0 (3).doc			
Pending		Add file attachment	To, Kevin (kevinto)		06/04/2021 06:45:59 AM PDT		FOLDER1431847 V 1 61-105594-01_A0 (3).doc			
Pending		User Defined Action	To, Kevin (kevinto)		06/04/2021 04:54:20 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		Print Tab	To, Kevin (kevinto)		06/04/2021 03:55:59 AM PDT		Cover Page;Page Two;Affected Items;Workflow;Relationships;Attachments;History;			
Pending		User Defined Action	To, Kevin (kevinto)		06/04/2021 01:53:28 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		Print Tab	To, Kevin (kevinto)		06/02/2021 08:45:36 AM PDT		Cover Page;Page Two;Affected Items;Workflow;Relationships;Attachments;History;			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 08:45:15 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 08:43:24 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 08:41:18 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		Add file attachment	To, Kevin (kevinto)		06/02/2021 08:39:21 AM PDT		FOLDER1430847 V 1 osfns-0-217-gf344a22-sa.bin.signed			
Pending		Add file attachment	To, Kevin (kevinto)		06/02/2021 08:37:40 AM PDT		FOLDER1430846 V 1 sfns-0-17-gef159d3-s.bin.signed (1).signed			
Pending		Remove file attachment	To, Kevin (kevinto)		06/02/2021 08:32:21 AM PDT		FOLDER1424696 V 1 osfns-0-4-gf5f2187-sa.bin.signed			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 04:00:53 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 03:59:06 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 03:57:21 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 03:56:12 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 03:54:22 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Pending		User Defined Action	To, Kevin (kevinto)		06/02/2021 03:49:20 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			1
Unassigned	Pending	Change Status	To, Kevin (kevinto)		06/02/2021 03:49:20 AM PDT		Unassigned => Deviation - Prototype Pending			
Unassigned	- enumg	User Defined Action	To, Kevin (kevinto)		06/02/2021 03:48:34 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Unassigned	1	User Defined Action	To, Kevin (kevinto)		06/02/2021 03:48:34 AM PDT		ChangeOrderUpdateTitleBlock: DF515753: No Action required			
Unassigned	1	User Defined Action	To, Kevin (kevinto)		06/02/2021 03:48:34 AM PDT		ChangeOrderUpdateTitleBlock: DF515753: No Action required ChangeOrderUpdateTitleBlock: DP515753: No Action required			
	-		` ` `		06/02/2021 03:48:34 AM PDT					
Unassigned	-	User Defined Action	To, Kevin (kevinto)				ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Unassigned	l	User Defined Action	To, Kevin (kevinto)		06/02/2021 03:48:33 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			L

6/7/2021 Print Preview

Status	Next Status	Action	User	Group(s)	Local Client Time	Affected Object	Details	Comments	User(s) Notified	Find Number
Unassigned		User Defined Action	To, Kevin (kevinto)		06/02/2021 03:48:33 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Unassigned		User Defined Action	To, Kevin (kevinto)		06/02/2021 03:48:33 AM PDT		ChangeOrderUpdateTitleBlock: DP515753: No Action required			
Unassigned		Create	To, Kevin (kevinto)		06/02/2021 03:48:32 AM PDT	DP515622	Save From Class: Deviations, Name: DP515622			

Printed by: To, Kevin (kevinto) on 06/07/2021 11:08:35 AM PDT