Release Notes Version 20.3.211

BT ID	Summary	Verified Date	Fixed in Version
10 (20)	ContourNail, when selected modelisation of Nail node should be improved	12.05.2026	20.3.182
9 (20)	delete a simple contour is no more possible	30.04.2026	20.3.177
8 (20)	060, Marking initialisation should be improved	14.04.2026	20.3.157
4 (20)	Option "display link rawpart" should be improved	11.03.2026	20.1.090
3 (20)	Copying part of the Nesting, and deleting nesting should be improved	23.02.2026	20.1.059
38 (19)	PanelConnector P2, depth should be translated	27.01.2026	19.7.538
34 (19)	Infos window, actual folder should be improved	22.01.2026	19.8.593
39 (19)	PanelConnector P2, new model for the 60	26.11.2025	19.7.545
37 (19)	PanelConnector P2, wrong model in case of depth=105	26.11.2025	19.7.537
2 (19)	New Processing PatternContour, Support for nested contours should be improved	13.11.2025	19.7.512
35 (19)	Missing UID or transformations should be completed automatically with 0/0/0	03.11.2025	19.7.500
33 (19)	Help menu, download function should be improved	17.10.2025	19.6.467
30 (19)	BTLx2.3.1 PatternContour MinNodeSpacing support should be improved	18.09.2025	19.5.368
6 (19)	Graphic setting, infos in header should be improved	01.09.2025	19.5.394
29 (19)	LockoutArea, attribute:ForGlueing='yes' not supported,	21.07.2025	19.5.340
20 (19)	New tool converter to extract UID GUID informations	15.07.2025	19.4.306
27 (19)	250, Contour, Improve change segment to spline	15.07.2025	19.4.297
23 (19)	BTLX, Aperture in contour for pocket contour depth should be improved	19.06.2025	19.4.268
21 (19)	BTLX Contour/Apertures with Dual contour should be improved	19.06.2025	19.3.207
18 (19)	BTLX Outline/Apertures with Dual contour should be improved	19.06.2025	19.3.204
22 (19)	BTLX Catalog save/load with Contours/Outlines should be improved	19.06.2025	19.3.212
24 (19)	PanelConnector P2, Parameter Depth should be used	19.06.2025	19.3.245
28 (19)	025 HipOrValleyRafterNotch, improve model with special parameters	19.06.2025	19.4.279

17 (19)	French ridge Lap should be improved	03.04.2025	19.2.160
16 (19)	Modification at BTL-start should be improved	06.03.2025	19.2.118
12 (19)	BTLx Bitmaps for contour group should be implemented	03.03.2025	19.2.112
7 (19)	BTLx, longitudinal cut, parameter start-end limited, bitmaps false shown	28.02.2025	19.2.108
8 (19)	BTLx, Bitmaps mit pulldonw menu, dynamic change should be improved	28.02.2025	19.2.109
14 (19)	BTLx Bitmaps, help protocol should be improved	26.02.2025	19.2.106
10 (19)	HipValleyRafterNotch 3/4-025-X, difference between BTL10.6 and BTLx	26.02.2025	19.2.106
1 (19)	New Processing PatternContour in BTLx 2.3.0	31.01.2025	18.6.525